



Expertise

Protocol number: 46179752  
Order No. / Reference: 26553528  
Inspection date: 26 Jun 2026

Manufacturer: Ford

Model: Kuga 2.0 EcoBlue Aut. 4x4 COOL&CONNECT

VIN: WF0FXXWPMFNS85534



| Vehicle details                             |                           |
|---------------------------------------------|---------------------------|
| Manufacturer / Type / Model / Equipment     |                           |
| Ford Kuga 2.0 EcoBlue Aut. 4x4 COOL&CONNECT |                           |
| Vehicle Identification number               | WF0FXXWPMFNS85534         |
| Mileage (Read)                              | 168,339 km                |
| First registration                          | 19 Apr 2022               |
| Number of holders                           | 1                         |
| Power / Engine displacement                 | 110 kw / 1,995 ccm        |
| Fuel type / Cylinder                        | Diesel / 4                |
| Gearbox / Number of gears                   | Automatic / 8             |
| Type of drive                               | All-wheel drive           |
| Type of vehicle                             | SUV                       |
| Colour / colour code                        | Obsidian Schwarz Metallic |
| Doors / Seats                               | 5 / 5                     |
| Upholstery type                             | Cloth                     |
| Colour of upholstery                        | Anthracite-Black          |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 17 %                                                       |
| <b>Last service on / at</b>                      | 10/2025 at 143,327 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GK790082                                                   |
| <b>Previous damage / Accident</b>                | None detectable              | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 8566 / BVH 00060             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,245 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                               | Manufacturer | Tread depth |
|----|-----------------|--------------------------------------------|--------------|-------------|
| 1) | 225/65 R17 106V | Summer tyres on Steel rim with wheel cover | Pirelli      | 4mm / 4mm   |
| 2) | 225/65 R17 106V | Summer tyres on Steel rim with wheel cover | Goodyear     | 4mm / 4mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre          | Manufacturer | Tread depth |
|----|-----------------|-----------------------|--------------|-------------|
| 1) | 225/65 R17 102H | Winter tyres on Steel | Goodyear     | 3mm / 3mm   |
| 2) | 225/65 R17 102H | Winter tyres on Steel | Goodyear     | 4mm / 4mm   |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- All-wheel drive
- Passenger airbag deactivation
- Tires: Tire repair kit
- Chrome decorative trim around the side windows
- Roof spoiler
- Dual exhaust system
- Electronic Stability Program (ESP)
- Driving mode switch selective
- Electric windows front and rear
- Ford Easy Fuel
- FordPower starting function
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- rear window wiper
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Post-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Headlights with delayed shut-off
- Power steering
- Seats: Driver's seat, 8-way manually adjustable, including adjustable lumbar support
- Seats: Front seats, individually and variably heated
- Power outlet: 12-volt connection in the luggage compartment
- Central locking with remote control and remote luggage compartment release
- Anti-lock braking system
- Tires: 7 J x 17 steel wheels
- third brake light
- Fabric headliner
- Diesel particulate filter
- Tachometer
- Driver information system with on-board computer - color
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment lighting
- Transmission: 8-speed automatic
- Heated rear window
- Intelligent Protection System (IPS)
- Front and rear headrests (5) height adjustable
- LED taillights
- Steering column, adjustable in height and reach
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3
- Front and rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Projection lens headlights with LED daytime running lights
- Headlight assistant with day/night sensor
- Seats: Passenger seat, 4-way manually adjustable
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Start-stop system
- Carpet floor mats in the front
- Immobiliser

### Extra equipment

- All-weather floor mats front All-weather floor mats rear
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Swiveling towbar (incl. ESP trailer stabilization)
- Paint finish: Metallic
- Safety partition net (including attachment points behind the first and second rows of seats)



## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group       | Description                                       |
|-----|-----------------------|---------------------------------------------------|
| 1   | Equipment             | Tirefit filler - Expired - Replace                |
| 2   | Rear bumper           | Spoiler - Scratched - Loss in value               |
| 3   | Interior              | Interior (Hundehaare) - Soiled - Conditioning     |
| 4   | Door - rear left side | Door - Dent / paintcoat damage - Repair and paint |
| 5   | Front bumper          | Front bumper - Scratch(es) - Paint                |
| 6   | Bonnet                | Bonnet - Scratch(es) - Paint                      |

## Wear and tear

| No. | Component group | Description                                            |
|-----|-----------------|--------------------------------------------------------|
| 1   | Rear bumper     | Rear bumper (unpainted) - Scratch(es) - No deduction   |
| 2   | Body            | Body (Waschanlagekratzer) - Scratch(es) - No deduction |
| 3   | Interior        | Interior - Scratch(es) - No deduction                  |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

### Description

Trim / covers - Floor mats

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

Fahrzeug hat erhöhte Lackwerte

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



**Figure 31:** Misc.




**Damage 1:** Equipment: Tirefit filler - Expired - Replace



**Damage 2:** Rear bumper: Spoiler - Scratched - Loss in value




**Damage 2:** Rear bumper: Spoiler - Scratched - Loss in value




**Damage 3:** Interior: Interior (Hundehaare) - Soiled - Conditioning



**Damage 3:** Interior: Interior (Hundehaare) - Soiled - Conditioning



**Damage 4:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 4:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 6:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 6:** Bonnet: Bonnet - Scratch(es) - Paint




**Damage 6:** Bonnet: Bonnet - Scratch(es) - Paint



**Wear and tear 1:** Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



**Wear and tear 1:** Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



**Missing part 1:** Trim / covers: Floor mats - Missing - Replace



**Missing part 1:** Trim / covers: Floor mats - Missing - Replace



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPMFNS85534

Hersteller / Modell: FORD FORD Kuga 2.0 EcoBlue Aut. 4x4 COOL&CONNECT

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                              |
|------------|----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 01.10.2025 | 143.327  | Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                              |
| 24.02.2025 | 115.921  | Bremsinspektion vo + hi; Bremse Sonstiges; Bremsklötze hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges      |
| 29.05.2024 | 85.837   | Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                          |
| 14.09.2023 | 56.836   | Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges |
| 28.08.2023 | 54.623   | Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne                                                                                                                          |
| 13.01.2023 | 27.876   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                  |