

## Expertise

Protocol number: 46206592  
Order No. / Reference: 26589064  
Inspection date: 29 Jun 2026

Manufacturer: MAN

Model: TGE 3.140 4X2F SB

VIN: WMA03VUY0P9018463



### Vehicle details

#### Manufacturer / Type / Model / Equipment

MAN TGE 3.140 4X2F SB

**Vehicle Identification number** WMA03VUY0P9018463

**Mileage (Read)** 83,940 km

**First registration** 17 Mar 2023

**Number of holders** 1

**Next periodical technical inspection** 02/2027  
(Report on hand)

**Power / Engine displacement** 103 kw / 1,968 ccm

**Fuel type / Cylinder** Diesel / 4

**Gearbox / Number of gears** Manual / 6

**Type of drive** Front drive

**Type of vehicle** Van

**Colour / colour code** Candy Weiß

**Doors / Seats** 4 / 2

**Upholstery type** Cloth

**Colour of upholstery** Black

**Re-import** no

**Vehicle with smoke odor** no

**readiness to drive** Roadworthy



Vehicle details			
<b>Maintenance booklet / proof</b>	digital proof / complete	<b>Next maintenance in</b>	14,900 km
<b>Last service on / at</b>	02/2025 at 78,510 km		
<b>Key is / should be</b>	2 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		<b>Letter No.</b>	GU300382
<b>Previous damage / Accident</b>	None detectable	<b>Repainting</b>	None detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	yes
<b>Test drive</b>	Not performed	<b>Engine function test</b>	Performed
<b>readiness to drive</b>	Roadworthy		
<b>Manufacturer key number/ type code number</b>	1516 / AYN 61577		
<b>Emission standard</b>	EURO6;WLTP;AR;PI/CI;N1 III, N2	<b>fine dust sticker</b>	
<b>Permitted total weight</b>	3,500 kg	<b>Empty weight</b>	

## Tyres

Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	Winter tyres on Steel rim with wheel cover	Maxxis	6mm / 7mm
2)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Continental	9 mm

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

- | Extra equipment   |  |
|---|--|
| <ul style="list-style-type: none"> <li>• Driver and passenger airbags</li> <li>• Cab doors, additionally with reinforced door seals</li> <li>• All-season tyres</li> <li>• MAN Media Van package with 4 speakers</li> <li>• Center wheel cover with chrome emblem</li> <li>• Steel spare wheel with road tires</li> <li>• Side interior paneling in the cargo area made of plywood</li> <li>• Super high roof</li> <li>• Lashing rails in the cargo area</li> </ul> | <ul style="list-style-type: none"> <li>• Battery with increased capacity</li> <li>• Fitting point</li> <li>• Wooden floor in the cargo area with wheel arch cladding</li> <li>• National registration documents Germany</li> <li>• Smoker's version</li> <li>• Rear View reversing camera</li> <li>• Comfort seat, left</li> <li>• Rear step, across the entire width</li> </ul> |



## Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

## Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper (Unterteil) - Scratched - Smart repair
2	Boot lid / rear door	Trim washable - lower (rechts) - Broken / torn - Replace
3	Rear bumper	Rear bumper - dent(s) - Loss in value
4	Wheel / tyres	Tyre - front (Mischbereifung) - Differs from the original configuration - Replace

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



**Damage 1:** Front bumper: Front bumper (Unterteil) - Scratched - Smart repair



**Damage 1:** Front bumper: Front bumper (Unterteil) - Scratched - Smart repair



**Damage 2:** Boot lid / rear door: Trim washable - lower (rechts) - Broken / torn - Replace



**Damage 2:** Boot lid / rear door: Trim washable - lower (rechts) - Broken / torn - Replace



**Damage 3:** Rear bumper: Rear bumper - dent(s) - Loss in value



**Damage 3:** Rear bumper: Rear bumper - dent(s) - Loss in value



**Damage 3:** Rear bumper: Rear bumper - dent(s) - Loss in value



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WMA03VUY0P9018463

Hersteller / Modell: MAN MAN TGE 3.140 4X2F SB

Datum	KM-Stand	Beschreibung
25.02.2025	82.948	HU + AU
17.02.2025	78.510	Bremse Sonstiges; Motoröl b. Wartung; Ölfilter ern; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
12.03.2024	38.824	Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges