


» Overview

Order number: 1002340041
Order completed: 27.02.2026 13:34
Report number: 10133295
VIN: VSSZZZKJ5RR098974



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SmallCar
Make:	Seat
Model:	Arona
Manufacturers and type code:	7593 / ANG
Date of first registration:	27.02.2024
Mileage:	16,719 km
Proof of mileage:	ReadOff
Exterior colour:	Mitternachtsschwarz
Roof colour:	Mitternachtsschwarz
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	1,000 ccm
Performance:	70 kW (96 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	3
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Manual 5-speed
Upholstery type:	Lining fabrics
Interior colour:	Grau-Schwarz-Swing
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	02.2027
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	650 Day(s)

16-inch alloy wheels "Design" 20/3, machined, Nuclear Gray	Electronic immobilizer
2 reading lights in front	Electronic stability control (ESC)
3-cylinder gasoline engine 1.0 l/70 kW TSI base engine: TJ4, "TSI"	Emission standard EU6 AP
3-cylinder SI engine 1.0 l unit 05C.A	Entry-level infotainment system Radio 2 (MIB3) 8.25-inch
3-point seat belt for center rear seat	Equipment options subset for Germany
3-point seat belts in front, with belt clamping device, without height adjustment	Extended and proactive pedestrian and cyclist protection
3-point seat belts, outer rear with ECE label	Exterior mirror housings and various add-on parts in body color
4 doors	Exterior mirrors, power-folding/adjustment, heated
5-speed manual transmission	External, USB type C, only data socket(s)
6 speakers (passive)	Forward collision warning incl. autonomous emergency braking, without adaptive cruise control
Activated carbon canister (Evaporative Emission Control System (EVAP))	Fresh air intake system with combination filter
Airbag on driver and front passenger side, without knee airbag, with front passenger airbag deactivation	Front head restraints
Alloy wheels 6.5J x 16	Front stabilizer bar
Alternator 140 A	Front-wheel drive
Antenna for AM/FM reception	Fuel system for fuel-injected SI engine (tropicalized)
Antifreeze up to -25 degree Celsius tolerance up to -30 degree C	Full Link
Axial and vertical adjustable steering column	Gearshift knob/handle in leather
Battery 320 A (49 Ah)	Hand brake lever handle in leather
Body-colored bumpers	Hatchback
Breakaway interior rearview mirror, auto-dimming	Headlight range control
Breakdown kit	Heat-reflecting windshield
Carrier frequency 433.92 MHz-434.42 Mhz	Hill hold control
Center armrest in front	Initial standard fuel filling
Central locking w/ radio remote control, interior controls, without SAFELOCK	In-plant control of self-collection
Child seat anchors for child seat system ISOFIX	Installation differentiation for transmission MQ 200 -- vehicle components --
Chrome package	Instrument cluster, km/h speedometer
Climatronic with impact pressure control, CFC-free	Interior package: double floor, drawer under right seat, storage compartment under left seat, front center armrest
Comfort package	Lane keeping system
Control of series production	Leather-wrapped multi-function sports steering wheel
Cruise control system and speed limiter	LED headlamps
Decorative inserts	Left exterior mirror, convex
Digital Cockpit	Left-hand drive
Digital radio reception	LongLife Service Regime
Disc brakes in front (Geomet D)	Luggage compartment cover, folding
Door and side trim panel	Luggage compartment trim (design 1)
Drawers under front seats	Luxury equipment
Driver alert system	Manual height adjustment for front seats
Driving on the right	Manual in German
Drum brakes in rear	Mobile phone interface
	Mounting fixture in luggage compartment

Multi-function display/trip computer active info display "Entry"	Standard license plate lighting
Nameplate set in basic style	Standard manufacturing sequence
No special edition	Standard paint coating
No special purpose vehicle, standard equipment	Standard pedal cluster
Non-smoker version	Standard rear axle
Not hot country	Standard seats in front
Online service, with OCU, without head unit coding, without engine immobilizer interconnection	Standard version
Operating permit, alteration	Start-stop system with regenerative braking
Pan-European emergency call service	Sun visors with mirror, airbag label on front passenger sun visor
Park distance control	Suspension range 04 installation control only, no requirement forecast
Park distance control using ultrasonic sensors	Three rear head restraints
Part set without country-specific prescriptive standard	Tire pressure monitoring system
Plane luggage/load compartment floor in rear	Tires 195/55 R16 91V xl super-low rolling resistance, generation 2
Power steering	Tires without specification of tire brand
Power windows with comfort operation and circuit breaker	Tool kit
Protective side molding	Trims for alloy wheels
Rear combination lamp, standard design	Type approval country Germany
Rear exhaust tailpipe (standard)	Type sign and company logo
Rear floor panel module, type 1	Unsplit molded headliner
Rear fog lamp	Unsplit rear seat bench, split folding backrest
Rear overhang, short	Variant
Rear shock absorption	Vehicle class differentiation -6F0-
Rear window wiper and washer system with intermittent control	Vehicles with special upgrade measures
Reduced price package	Vent
Refrigerant R1234yf	Vent package in Neutral color
Regional code " ECE " for radio	Visual and acoustic seat belt reminder, electric contact in front and rear
Right exterior mirror, convex	Weight range 8 installation control only, no requirement forecast
Seat heater for front seats separately controlled	Wheel bolts with anti-theft protection (unlockable)
Seat trim covers in fabric	Wheelbase
Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature	Windshield wiper intermittent control with light/rain sensor
Service indicator 30 000 km or 2 years (variable)	Winter package
Shock absorption in front	Wired & Wireless App-Connect
Side airbag in front with curtain airbag	With multifunction camera
Side and rear windows in heat-insulating glass	Without "drive select"
Single-tone horn	Without add. lights (interior lighting)
Special identification label for EC for M1 passenger vehicles	Without additional front underbody guard
Special price	Without additional noise suppression measures for passenger compartment
Standard air cleaner	Without additional side body covers (stone guard)
Standard climatic zones	Without additional tires
Standard dashboard	Without alternative drive system
Standard decorative trims	Without applications
Standard design	

Without auxiliary heater/parking heater
Without backrest release for front seats
Without camera systems/accident sensors
Without CD changer/CD player
Without CD/DVD for navigation
Without customized installation
Without decorative films/emoles
Without delivery equipment
Without differential lock
Without dynamic road sign display
Without ECO function
Without extended safety system
Without fire extinguisher
Without first aid kit and warning triangle
Without floor mats
Without front fog lamps
Without headlamp washer system
Without heat accumulator/auxiliary heater
Without heated washer nozzles
Without interior light in footwell
Without lane change assist
Without light control
Without luggage nets/pockets on backrests
Without lumbar support in seat backrests
Without navigation device
Without rear spoiler
Without roof insert (standard roof)
Without roof rails/roof load rack
Without second battery
Without special body measures
Without special color trim
Without special specifications
Without surface protection, with additional transport protection measures
Without trailer hitch
Without UN-ECE cybersecurity & software update
Without voice control
Without washer fluid level indicator

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Fulda	Front	Left	All season	Aluminium	195/55 R 16 91 H	6.0 mm
Fulda	Front	Right	All season	Aluminium	195/55 R 16 91 H	6.0 mm
Fulda	Rear	Left	All season	Aluminium	195/55 R 16 91 H	7.0 mm
Fulda	Rear	Right	All season	Aluminium	195/55 R 16 91 H	7.0 mm

Permitted: Yes

Roadworthy: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Bumper F	Scratch(es)	Smart repair
2	Bumper R	Scratch(es)	Smart repair
3	Tailgate / Boot	Dent(s)	Paintless dent repair
4	Door FR	Dent(s)	Paintless dent repair
5	Roof	Dent(s)	Paintless dent repair

» Usage Damages

Nr	Location	Damage type	Repair type
1	Roof	Dent(s)	Acceptable

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Liability loss		€ 7,106.26
Total without VAT:				€ 7,106.26

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

VSSZZZKJ5RR098974

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes


» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures




Front Left 3/4



Front Right 3/4



Rear Left 3/4




Rear Right 3/4



Mileage




Sill outer L




Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL




Wheel RR



Central console




Engine compartment




Documents




Interior arrangement




Registration Certificate



History Maintenance



Interior - front



Interior - rear



GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Bumper F - Scratch(es) - Smart repair



2 - Bumper R - Scratch(es) - Smart repair




3 - Tailgate / Boot - Dent(s) - Paintless dent repair



4 - Door FR - Dent(s) - Paintless dent repair



5 - Roof - Dent(s) - Paintless dent repair



USAGE DAMAGES

1 - Roof - Dent(s) - Acceptable

