



Expertise

Protocol number: 46557849
Order No. / Reference: 26536668
Inspection date: 16 Jul 2026

Manufacturer: Peugeot

Model: 308 SW BlueHDi 130 EAT8 Allure Pack

VIN: VR3FCYHZTPY503895



Vehicle details	
Manufacturer / Type / Model / Equipment	
Peugeot 308 SW BlueHDi 130 EAT8 Allure Pack	
Vehicle Identification number	VR3FCYHZTPY503895
Mileage (Read)	116,423 km
First registration	21 Apr 2023
Number of holders	1
Power / Engine displacement	96 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Schneeweiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	Yes (not ozone-treated)



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	27,700 km
Last service on / at	04/2026 at 114,167 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG050149
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AEI 00038		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,950 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment: Illuminated glove compartment
- Active Safety Brake Plus
- Airbags (6)
- Adaptive Cruise Control (ACC) with Stop & Go function (EAT8)
- Hill start assist
- On-board computer
- Decorative fabric inserts "Texa" for door panels and dashboard
- Tachometer
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP)
- Electric windows, front and rear
- electric parking brake
- Front collision warning
- luggage compartment roller blind
- Cup holder in the center console
- rear window wiper
- Infotainment system: PEUGEOT i-Connect Advanced
- Map pockets on the front seatbacks
- Child safety lock at the rear
- LED lighting in the front footwell
- LED ceiling lighting at the front
- LED daytime running lights
- Steering wheel: Leather steering wheel with paddle shifters
- Mirror Screen
- front center armrest
- Multi-collision brake
- Emergency brake assist with automatic activation of the hazard warning lights
- Peugeot i-Toggles
- Rain sensor
- Wheels: Halong 17" alloy wheels, two-tone
- Reversing camera with 180° surround view
- Electric power steering
- Seats: Passenger seat height adjustable
- Seats: Manual lumbar support for driver
- Seats: Rear seats
- Seats: Front seats
- 12-volt socket
- Blind spot assist
- Chrome-plated decorative exhaust tailpipes
- Immobiliser
- Decorative trim in high-gloss black on the side windows
- Adjustable intermediate loading shelf
- ABS (Anti-lock Braking System) with electronic brake force distribution
- Traffic Alert - Rear Cross Traffic Alert
- Electrically adjustable, heated and folding exterior mirrors
- Exterior mirror caps in Perla Nera Black
- Turn signals with lane change indicator function
- third brake light
- Digital instrument cluster with high-resolution 10" screen, adjustable and customizable
- Eco-LED headlights
- Front parking aid, acoustic and visual
- Driving mode selector (Sport - Normal - Eco)
- High beam assist
- Follow-me-home function (automatic)
- Laminated glass windshield, noise-reducing
- Transmission: 8-speed automatic transmission EAT8
- Heated rear window
- Rear apron in black
- Interior mirror automatically dimming
- Keyless System Plus
- Automatic climate control (2-zone), with activated carbon filter
- LED taillights
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- light sensor
- Armrest - centre, rear
- Multifunctional touchscreen with 10" HD color display
- Fatigue warning
- Particulate filter: FAP diesel particulate filter
- Break warning
- Upholstery: Fabric/faux leather
- Tire pressure monitoring system
- Wheels: Tire repair kit (compressor + tire sealant spray)
- Side windows in the second row and rear window are more heavily tinted.
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat and backrest split 40/20/40, foldable
- Lane keeping assist with steering intervention
- Stop&Start automatic
- Doors lock automatically when driving off
- Traffic sign recognition
- Central locking system, activatable from inside via remote control

Extra equipment

- Detachable towbar (with removable ball head without tools)
- Seats: Heated front seats
- luggage compartment partition net
- Paint finish: Solid



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Door - front left side	Door handle - outside (Schlossabdeckung) - Scratch(es) - Smart repair
3	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
4	Door - front left side	Door edge - Scratch(es) - Smart repair
5	Wheel / tyres	Tyre - front left side (Flanke) - Damaged - Replace
6	Wheel / tyres	Tyre - front right side (Flanke) - Damaged - Replace
7	Wheel / tyres	Tyre - rear right side (Flanke, nicht fahrbereit) - Damaged - Replace
8	Interior	Interior (Zigaretten) - Odour - Ozone treatment
9	Interior	Interior - Soiled - Clean
10	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
11	Exhaust system	Exhaust system (Blende rechts) - Scratched - Replace
12	Engine	Engine cowling - lower - Broken / torn - Replace
13	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace
14	Interior	Boot cover / roller cover - Deformed - Replace
15	Sill - left side	Sill - Deformed - Repair and paint
16	Side panel - rear right side	Side panel - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	2nd wheel set	1 tyre - Damaged - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction
4	Front bumper	Spoiler - Scratch(es) - No deduction
5	Roof	Roof - dent(s) - Smooth repair work
6	Trim / covers	Floor mats - Broken / torn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Damage 2: Door - front left side: Door handle - outside (Schlossabdeckung) - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door handle - outside (Schlossabdeckung) - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Wheel / tyres: Tyre - front left side (Flanke) - Damaged - Replace



Damage 5: Wheel / tyres: Tyre - front left side (Flanke) - Damaged - Replace



Damage 5: Wheel / tyres: Tyre - front left side (Flanke) - Damaged - Replace



Damage 6: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 6: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 6: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - rear right side (Flanke, nicht fahrbereit) - Damaged - Replace




Damage 7: Wheel / tyres: Tyre - rear right side (Flanke, nicht fahrbereit) - Damaged - Replace



Damage 9: Interior: Interior - Soiled - Clean




Damage 9: Interior: Interior - Soiled - Clean




Damage 9: Interior: Interior - Soiled - Clean



Damage 10: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 11: Exhaust system: Exhaust system (Blende rechts) - Scratched - Replace




Damage 11: Exhaust system: Exhaust system (Blende rechts) - Scratched - Replace



Damage 11: Exhaust system: Exhaust system (Blende rechts) - Scratched - Replace



Damage 12: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 12: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 12: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 12: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace




Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace




Damage 14: Interior: Boot cover / roller cover - Deformed - Replace




Damage 14: Interior: Boot cover / roller cover - Deformed - Replace




Damage 15: Sill - left side: Sill - Deformed - Repair and paint



Damage 15: Sill - left side: Sill - Deformed - Repair and paint



Damage 15: Sill - left side: Sill - Deformed - Repair and paint



Damage 15: Sill - left side: Sill - Deformed - Repair and paint



Damage 16: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 16: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 16: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 16: Side panel - rear right side: Side panel - Deformed - Repair and paint



Wear and tear 2: 2nd wheel set: 1 tyre - Damaged - No deduction



Wear and tear 2: 2nd wheel set: 1 tyre - Damaged - No deduction



Wear and tear 5: Roof: Roof - dent(s) - Smooth repair work



Wear and tear 5: Roof: Roof - dent(s) - Smooth repair work



Wear and tear 6: Trim / covers: Floor mats - Broken / torn - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR3FCYHZTPY503895

Hersteller / Modell: PEUGEOT PEUGEOT 308 SW BlueHDi 130 EAT8 Allure Pack

Datum	KM-Stand	Beschreibung
24.04.2026	114.167	AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.05.2025	90.067	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.08.2024	59.826	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.12.2023	25.513	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges