



Expertise

Protocol number: 46518147  
Order No. / Reference: 26639794  
Inspection date: 1 Jul 2026

Manufacturer: Skoda  
VIN: TMBJC9NY0PF041296

Model: Enyaq iV 80



| Vehicle details                         |                             |
|-----------------------------------------|-----------------------------|
| Manufacturer / Type / Model / Equipment |                             |
| Skoda Enyaq iV 80                       |                             |
| Vehicle Identification number           | TMBJC9NY0PF041296           |
| Mileage (Read)                          | 40,236 km                   |
| First registration                      | 26 Apr 2023                 |
| Number of holders                       | 1                           |
| Next periodical technical inspection    | 04/2026                     |
| (Report not on hand)                    |                             |
| Power / Engine displacement             | 70 kw / 0 ccm               |
| Fuel type / Cylinder                    | Electric / 0                |
| Gearbox / Number of gears               | Direct drive / 1            |
| Type of drive                           | Rear drive                  |
| Type of vehicle                         | Station wagon               |
| Colour / colour code                    | Blue Metallic               |
| Doors / Seats                           | 5 / 5                       |
| Upholstery type                         | Cloth / leather combination |
| Colour of upholstery                    | Grey-Black                  |
| Re-import                               | no                          |
| readiness to drive                      | Roadworthy                  |



## Vehicle details

|                                                  |                                |                                |                                                            |
|--------------------------------------------------|--------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete       | <b>Next maintenance in</b>     | 296 Tag(e)                                                 |
| <b>Last service on / at</b>                      | 04/2025 at 22,338              |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                          | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                                | <b>Letter No.</b>              | GQ567977                                                   |
| <b>Previous damage / Accident</b>                | None detectable                | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                     | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed                  | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                     |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 8004 / AWS 00124               |                                |                                                            |
| <b>Emission standard</b>                         | 2017/1151;WLTP;reine Elektrofz | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,600 kg                       | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R19 101T | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |
| 2) | 255/50 R19 103T | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                     | Manufacturer | Tread depth |
|----|-----------------|----------------------------------|--------------|-------------|
| 1) | 235/55 R19 101T | Winter tyres (Without wheel rim) | Continental  | 8mm / 8mm   |
| 2) | 255/50 R19 103T | Winter tyres (Without wheel rim) | Continental  | 7mm / 7mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 03/2027 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment



## Standard equipment

- Storage compartments (Four roof grab handles, rear with coat hooks - Warning vest compartment in the doors - Storage compartments in the front door panels with 1.5l bottle holders - Storage compartments in the rear door panels - Umbrella compartments in the front doors - Ticket holder on the windshield - Ice scraper in the tailgate panel - Coat hooks on the B-pillars - Cup holder in the front center console - Storage compartments in the trunk)
- Evasive steering assist including turning assistant (The turning assistant monitors oncoming vehicles when you turn left (for left-hand drive vehicles). If there is an immediate danger, it brings the vehicle to a standstill and a warning signal sounds.)
- Design Selection Loft
- Third brake light
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Front radar assist with pedestrian and cyclist detection and city emergency braking function (The front radar assist is a safety system with collision warning: If confronted with an unavoidable collision, it brakes the vehicle to minimize the consequences. It also performs emergency braking if a pedestrian or cyclist attempts to cross the vehicle's path. The front radar assist recognizes from the way the driver moves the vehicle that they are attempting to avoid an obstacle and actively intervenes in the steering to steer around it.)
- Child safety locks on the rear doors
- Removable boot cover
- Front and rear headrests are height-adjustable.
- Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A) (Fast charging connector (CCS / Combo 2))
- Steering wheel: Leather steering wheel with multifunction buttons
- Navigation system
- Front and rear parking sensors
- Radio: Infotainment system with capacitive 13" color display (2 x USB ports (Type-C) at the front - Digital radio reception DAB+ - Bluetooth hands-free phone system - Voice control - SmartLink (Apple CarPlay, Android Auto) - Wireless SmartLink)
- Rear view camera
- Rear seat backrest split 60:40, foldable
- Power steering
- Safety lights in the front side doors
- Seats: Front seats height-adjustable including manually adjustable lumbar support
- Speed limiter
- Lane keeping assistant (Lane Assist)
- 12V socket - in the trunk
- Traffic sign recognition
- Immobiliser
- heat pump
- Central locking including remote control integrated into the key (EASY START (keyless start-stop system))
- Airbag, center airbag front
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, front and rear head airbags
- Airbag, front side airbags
- acoustic windscreen
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors, including automatic dimming.
- Outdoor temperature display
- Hill start assist
- AERO anodized roof rails
- Digital instrument cluster (Virtual Cockpit)
- E-Sound (external speaker for generating a driving sound)
- Increased battery charging power max. 125 kW
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- Cruise control
- Transmission: 1-speed (EV)
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Automatic interior mirror dimming
- Isofix anchorage on the front passenger seat
- Isofix anchorage on the outer rear seats including top tether
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, including odor and allergen filter)
- LED headlights with daytime running lights
- LED taillights
- Steering wheel adjustable for height and reach
- Manual headlight range adjustment
- Multi-collision brake
- Package: Chrome (chrome trim strips on the outside of the side windows - AERO anodized roof rails)
- Rain sensor and driving light assistant with coming and leaving home function
- Tire mobility kit (tire repair spray incl. compressor)
- Tire pressure monitoring
- Wheels: 19" Regulus AERO alloy wheels, anthracite polished (8Jx19, tires 235/55 R19 101T front, 255/50 R19 103T rear)
- Seat belts (Height-adjustable three-point seat belts in the front - Three three-point seat belts in the rear - Seat belt reminder indicators on the front and rear seats)



- Skoda Care Connect (SOS emergency call function (eCall including automatic activation in the event of an accident with airbag deployment) - Free remote vehicle access to iV-specific functions for 10 years (iV Remote Services Basic) such as starting and stopping the charging process, creating charging plans, setting the interior climate control before starting the journey, etc. - Mobility service - Information service - Free remote vehicle access for 3 years (Remote Access) - Skoda Infotainment Online)

### Extra equipment

- Paint finish: Metallic
- Package: Transport (Net program in the trunk incl. charging cable bag - Variable loading floor in the trunk - Remote release of the rear seat backrests in the trunk - Cargo elements in the trunk)

### Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                                                                                         |

### Value reducing factors

| No. | Component group              | Description                                         |
|-----|------------------------------|-----------------------------------------------------|
| 1   | Side panel - rear right side | Side panel - dent(s) - Smooth repair work           |
| 2   | Misc.                        | Main inspection - Due - Perform                     |
| 3   | Mudguard - right side        | Mudguard - right side - Deformed - Repair and paint |

### Wear and tear

| No. | Component group | Description                             |
|-----|-----------------|-----------------------------------------|
| 1   | Vehicle glazing | Windscreen - Stone chips - No deduction |
| 2   | Rear bumper     | Spoiler - Scratch(es) - No deduction    |

The vehicle shows signs of wear and tear commensurate with its age and use.

### Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Winterreifensatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel




Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



**Damage 3:** Mudguard - right side: Mudguard - right side - Deformed - Repair and paint



**Damage 3:** Mudguard - right side: Mudguard - right side - Deformed - Repair and paint



**Damage 3:** Mudguard - right side: Mudguard - right side - Deformed - Repair and paint