



Expertise

Protocol number: 46867776
Order No. / Reference: 26715258
Inspection date: 3 Aug 2026

Manufacturer: Seat

Model: Arona 1.0 TSI OPF Style

VIN: VSSZZKJZNR043302



Vehicle details

Manufacturer / Type / Model / Equipment

Seat Arona 1.0 TSI OPF Style	
Vehicle Identification number	VSSZZKJZNR043302
Mileage (Read)	113,648 km
First registration	2 Mar 2022
Number of holders	1
Next periodical technical inspection	01/2028
(Report on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	81 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Midnight Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	15,500 km
Last service on / at	01/2026 at 99,094 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG155333
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ARJ 01397		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,630 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	All-season tyres on Light alloy	Hankook	5mm / 5mm
2)	205/60 R16 92H	All-season tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- 12V socket at the front
- Airbags
- Exterior mirror housings in body color
- Hill Start Assist (HHC)
- On-board computer
- Electronic differential lock (XDS)
- Three-point automatic seat belts, front and rear
- Electronic Stability Control (ESC)
- luggage compartment cover
- Speed limiter
- Transmission: 6-speed transmission
- Heated rear window with timer function
- ISOFIX child seat restraint system
- Child safety locks on the rear doors
- illuminated trunk
- Paintwork: Vehicle roof in body color
- Steering wheel: Steering column with height and reach adjustment
- light sensor
- Fatigue detection
- Emergency call service
- Pollen filter
- Radio: 8.25" Media System
- Tire pressure monitoring system
- Front windshield wipers with intermittent function
- Seats: Driver's seat with height adjustment
- Lane departure warning system
- Bumpers in body color
- Front Assist area monitoring system with City Emergency Braking function and pedestrian detection
- thermal insulation glazing
- Storage compartment in the front doors
- Electrically adjustable exterior mirrors
- Outdoor temperature display
- Turn signals in the wing mirrors
- Roof rails and design element in the C-pillar in black
- Tachometer
- Third brake light integrated into the rear spoiler
- Electric window regulator with anti-pinch protection and one-touch function
- Cruise control
- Cup holders, 2 front
- Rear window wiper/washer system with intermittent function
- Air conditioning
- Height-adjustable headrests, front and rear
- LED technology for headlights and daytime running lights
- Steering wheel: Multifunction steering wheel in nappa leather
- Multi-collision brake
- Fog light
- Otto particulate filter
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Wheels: Tyre fit
- Electromechanical power steering
- Seats: Rear seat backrest split 1/3 to 2/3, foldable
- Start-stop technology
- Door handles in car color
- Electronic immobilizer
- Leather gear selector
- Central locking with remote control and comfort closing



Extra equipment

- Deletion of the colored air vents in the dashboard (air vents in neutral, unlit grey)
- Package: Storage package (front center armrest - storage compartment under the passenger seat - owner's manual holder under the driver's seat - lashing eyes in the luggage compartment)
- Package: Climate Comfort Package (Heated and electrically folding exterior mirrors - Automatic coming home and leaving home function - Climatronic with electronic temperature control, separate temperature control for driver and front passenger - Automatically dimming interior mirror - Rain sensor)
- Wheels: 4 all-season tires on alloy wheels "Design 20/1" (6J x 16", tires 205/60 R16)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Virtual Cockpit (fully digital instrument cluster with TFT display)
- Wireless charger in V with navigation system and parking assist
- Paint finish: Metallic
- Navigation: Navigation data for Europe including MAPCARE (on SD card) for navigation systems
- Package: Infotain (9.2" media system with navigation system and Full Link, prepared for activation of the SEAT CONNECT online infotainment service package - wireless charger)
- Package: Safety (Parking Assist with ultrasonic parking aid front and rear incl. reversing camera - Driving Assistance Package M for navigation system - Adaptive Cruise Control ACC - High Beam Assist - Traffic Sign Recognition)
- Package: Winter (Passenger seat with height adjustment - Heated front seats - Heated and electrically folding exterior mirrors)
- Manufacturer's warranty extended by 3 years, or a maximum of 100,000 km
- Full LED headlights (low beam, high beam and turn signals at the front in LED technology - dynamic headlight range control - rear lights in LED technology)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Damaged - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Trim / covers	Door trim - rear right side - Scratched - Replace
4	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
5	Side panel - rear right side	Wheel arch - Scratched - Replace
6	Roof	Roof - dent(s) - Smooth repair work
7	Sill - left side	Sill - Scratch(es) - Smart repair
8	Side panel - rear left side	Side panel - dent(s) - Smart repair
9	Sill - right side	Sill - Dent / paintcoat damage - Smart repair
10	Side panel - rear left side	Elbow (Einstieg hinten) - Scratched - Smart repair
11	Instrument panel	Dashboard - right side - Scratch(es) - Loss in value
12	Trim / covers	Boot lining (Beschädigungen ebenfalls vorhanden) - Missing - Replace
13	Side panel - rear right side	Elbow (Einstieg hinten) - Scratched - Smart repair
14	Body	Underbody panelling - Scratched - Replace
15	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Smart repair
16	Seat - front	Seat cover - left side - Damaged - Replace
17	Rear bumper	Spoiler - Scratched - Replace
18	Rear bumper	Rear bumper - Scratched - Paint
19	Front bumper	Front bumper - Scratched - Paint
20	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
21	Door - front left side	Door - Scratch(es) - Paint
22	Door - front right side	Door - Scratch(es) - Paint
23	Mudguard - left side	Mudguard - left side - Deformed - Repair and paint
24	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 8 Dec 2022	6.512,94 €

Repainting

No.	Repainting
1	Roof rail - left side, Roof rail - right side, Mudguard - right side, Bonnet, Side panel - rear left side, Side panel - rear right side, Door - rear left side, Door - rear right side, Door - front left side, Door - front right side, Professionally carried out

Paint coat thickness measurement

Roof rail - left side	248 µm	Roof rail - right side	218 µm
Mudguard - right side	205 µm	Bonnet	194 µm
Side panel - rear left side	206 µm	Side panel - rear right side	217 µm
Door - rear left side	205 µm	Door - rear right side	207 µm
Door - front left side	476 µm	Door - front right side	312 µm



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.





Figure 28: Misc.



Figure 29: Misc.



Damage 1: Trim / covers: Floor mats - Damaged - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Trim / covers: Door trim - rear right side - Scratched - Replace



Damage 3: Trim / covers: Door trim - rear right side - Scratched - Replace



Damage 4: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 4: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 5: Side panel - rear right side: Wheel arch - Scratched - Replace



Damage 5: Side panel - rear right side: Wheel arch - Scratched - Replace



Damage 5: Side panel - rear right side: Wheel arch - Scratched - Replace



Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 8: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 8: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 8: Side panel - rear left side: Side panel - dent(s) - Smart repair




Damage 8: Side panel - rear left side: Side panel - dent(s) - Smart repair




Damage 8: Side panel - rear left side: Side panel - dent(s) - Smart repair




Damage 8: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 9: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 9: Sill - right side: Sill - Dent / paintcoat damage - Smart repair




Damage 9: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 9: Sill - right side: Sill - Dent / paintcoat damage - Smart repair




Damage 10: Side panel - rear left side: Elbow (Einstieg hinten) - Scratched - Smart repair



Damage 10: Side panel - rear left side: Elbow (Einstieg hinten) - Scratched - Smart repair



Damage 10: Side panel - rear left side: Elbow (Einstieg hinten) - Scratched - Smart repair




Damage 10: Side panel - rear left side: Elbow (Einstieg hinten) - Scratched - Smart repair



Damage 11: Instrument panel: Dashboard - right side - Scratch(es) - Loss in value



Damage 11: Instrument panel: Dashboard - right side - Scratch(es) - Loss in value




Damage 12: Trim / covers: Boot lining (Beschädigungen ebenfalls vorhanden) - Missing - Replace



Damage 12: Trim / covers: Boot lining (Beschädigungen ebenfalls vorhanden) - Missing - Replace



Damage 12: Trim / covers: Boot lining (Beschädigungen ebenfalls vorhanden) - Missing - Replace




Damage 12: Trim / covers: Boot lining (Beschädigungen ebenfalls vorhanden) - Missing - Replace



Damage 13: Side panel - rear right side: Elbow (Einstieg hinten) - Scratched - Smart repair




Damage 13: Side panel - rear right side: Elbow (Einstieg hinten) - Scratched - Smart repair



Damage 13: Side panel - rear right side: Elbow (Einstieg hinten) - Scratched - Smart repair



Damage 13: Side panel - rear right side: Elbow (Einstieg hinten) - Scratched - Smart repair




Damage 14: Body: Underbody panelling - Scratched - Replace




Damage 14: Body: Underbody panelling - Scratched - Replace



Damage 14: Body: Underbody panelling - Scratched - Replace




Damage 14: Body: Underbody panelling - Scratched - Replace



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Smart repair



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Smart repair




Damage 16: Seat - front: Seat cover - left side - Damaged - Replace



Damage 16: Seat - front: Seat cover - left side - Damaged - Replace




Damage 17: Rear bumper: Spoiler - Scratched - Replace




Damage 17: Rear bumper: Spoiler - Scratched - Replace



Damage 18: Rear bumper: Rear bumper - Scratched - Paint



Damage 18: Rear bumper: Rear bumper - Scratched - Paint



Damage 19: Front bumper: Front bumper - Scratched - Paint




Damage 19: Front bumper: Front bumper - Scratched - Paint



Damage 20: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 20: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 20: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 20: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 21: Door - front left side: Door - Scratch(es) - Paint



Damage 21: Door - front left side: Door - Scratch(es) - Paint



Damage 21: Door - front left side: Door - Scratch(es) - Paint



Damage 21: Door - front left side: Door - Scratch(es) - Paint



Damage 21: Door - front left side: Door - Scratch(es) - Paint



Damage 21: Door - front left side: Door - Scratch(es) - Paint




Damage 22: Door - front right side: Door - Scratch(es) - Paint




Damage 22: Door - front right side: Door - Scratch(es) - Paint




Damage 23: Mudguard - left side: Mudguard - left side - Deformed - Repair and paint



Damage 23: Mudguard - left side: Mudguard - left side - Deformed - Repair and paint



Damage 24: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 24: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Roof rail - left side: 248 µm



Roof rail - right side: 218 µm




Mudguard - right side: 205 µm



Bonnet: 194 µm



Side panel - rear left side: 206 µm



Side panel - rear right side: 217 µm



Door - rear left side: 205 µm



Door - rear right side: 207 µm



Door - front left side: 476 µm



Door - front right side: 312 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZKJZNR043302
Hersteller / Modell: SEAT SEAT Arona 1.0 TSI OPF Style

Datum	KM-Stand	Beschreibung
07.01.2026	99.094	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.09.2025	81.824	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
16.07.2024	59.573	Batterie ern; Bremsflüssigkeit; Bremsflüssigkeit ern; Systemtest/ Eigendiagnose; Wartung Sonstiges; Zündkerzen ern
29.11.2023	42.513	Bremse Sonstiges; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.01.2023	16.446	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges