



Expertise

Protocol number: 44785717
Order No. / Reference: 26192187
Inspection date: 1 Apr 2026

Manufacturer: Ford

Model: Transit 310 L2H2 Lkw VA Trend

VIN: WF0EXXTTREKM22942



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit 310 L2H2 Lkw VA Trend	
Vehicle Identification number	WF0EXXTTREKM22942
Mileage (Read)	80,574 km
First registration	21 Jan 2020
Number of holders	1
Power / Engine displacement	79 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Polar-Silber Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	Available / complete	Next maintenance in	0 km
Last service on / at	03/2024 at 69,749 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FR757775
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BSB 00178		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,140 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Summer tyres on Steel	Continental	4mm / 4mm
2)	215/65 R15 104T	Summer tyres on Steel	Continental	7mm / 7mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109R	Winter tyres on Steel	Continental	6mm / 6mm
2)	215/65 R16 109R	Winter tyres on Steel	Continental	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R15 104T C	Summer tyres on Steel	Continental	8 mm
Legend: Tread depth for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel				

Equipment

Standard equipment

- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headlining in driver's cab
- Tachometer
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Cargo area lighting
- leather steering wheel
- Steering column, adjustable in height and reach
- Fog light
- Particulate filter: diesel particulate filter
- Wheels: Tire repair kit
- Headlights with static cornering lights
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Start-stop system
- Partition to the cargo area without windows
- Immobiliser
- auxiliary heater, electric
- Front overhead storage compartment
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, middle
- Double rear door with 180° opening angle (without window)
- Front window lifter, electric
- Ford Easy Fuel
- Cruise control including leather steering wheel
- Glove compartment with lockable lid
- Front air conditioning
- Cargo area floor: Vinyl floor covering "Easy Clean" including wheel arch lining
- MyKey key system
- Front and rear parking pilot system
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires
- Headlight dipped beam with switch-off delay
- Sliding door: Sliding door, right
- Rear mud flaps
- Side wall cladding extending up to the roof
- Seat belts
- Daytime running light
- Lashing eyes
- Central locking with remote control
- Second key with remote control

Extra equipment

- 2 batteries
- Paint finish: Metallic
- Wheels/Tires: Spare wheel, steel wheel
- Seats: Seat Package 15 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated (fold-out) tray in the double passenger seat - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Manual lumbar support (driver's seat) - Seat upholstery: fabric)
- Parking heater package 1 (parking heater (fuel-operated auxiliary heater), programmable, incl. remote control)
- Manufacturer's transport costs => BOTT
- 3rd and 4th master keys
- Radio: Audio System 24: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation system. (Radio (FM/AM) 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, Android Auto and Apple CarPlay support, capacitive touchscreen technology,...), dynamic navigation, lane guidance, road map for Western Europe)
- Steel rear step



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Boot lid / rear door	Rear door - left side - dent(s) - Smooth repair work
3	Boot lid / rear door	Rear door - right side - Scratch(es) - Smart repair
4	Rear of vehicle	Foot plate - Paint defect - Loss in value
5	Side panel - rear left side	Wheel well extension - Scratch(es) - Loss in value
6	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
7	Door - front right side	Door (Verkleidung außen) - Scratch(es) - Loss in value
8	Trim / covers	Trim / covers (Seitenwand links) - Scratch(es) - Loss in value
9	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
10	Interior	Cargo space partition - Scratched - Loss in value
11	Misc.	Inspection / maintenance - Due - Perform
12	Roof	Roof (Dellen+ Verformung) - Deformed - repair according to calculation

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Mudguard - right side	Mudguard - right side - Scratch(es) - No deduction
4	Door - front right side	Door - Scratch(es) - No deduction
5	Body	Body (Waschanlagenkratzer) - Scratch(es) - No deduction
6	Door - front right side	Door (Innen) - Dent / paintcoat damage - No deduction
7	Trim / covers	Floor mats - Holes - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Die Beiliegenden Räder sind kein Teil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 3: Boot lid / rear door: Rear door - right side - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Rear door - right side - Scratch(es) - Smart repair



Damage 4: Rear of vehicle: Foot plate - Paint defect - Loss in value



Damage 4: Rear of vehicle: Foot plate - Paint defect - Loss in value




Damage 4: Rear of vehicle: Foot plate - Paint defect - Loss in value



Damage 5: Side panel - rear left side: Wheel well extension - Scratch(es) - Loss in value



Damage 5: Side panel - rear left side: Wheel well extension - Scratch(es) - Loss in value



Damage 5: Side panel - rear left side: Wheel well extension - Scratch(es) - Loss in value



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value




Damage 6: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 7: Door - front right side: Door (Verkleidung außen) - Scratch(es) - Loss in value




Damage 7: Door - front right side: Door (Verkleidung außen) - Scratch(es) - Loss in value



Damage 7: Door - front right side: Door (Verkleidung außen) - Scratch(es) - Loss in value



Damage 8: Trim / covers: Trim / covers (Seitenwand links) - Scratch(es) - Loss in value



Damage 8: Trim / covers: Trim / covers (Seitenwand links) - Scratch(es) - Loss in value



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value




Damage 10: Interior: Cargo space partition - Scratched - Loss in value




Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 10: Interior: Cargo space partition - Scratched - Loss in value



Damage 11: Misc.: Inspection / maintenance - Due - Perform



Damage 11: Misc.: Inspection / maintenance - Due - Perform



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation




Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation




Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Damage 12: Roof: Roof (Dellen+ Verformung) - Deformed - repair according to calculation



Wear and tear 7: Trim / covers: Floor mats - Holes - No deduction



Wear and tear 7: Trim / covers: Floor mats - Holes - No deduction