



Expertise

Protocol number: 46557591
Order No. / Reference: 26544840
Inspection date: 16 Jul 2026

Manufacturer: Ford

Model: Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut.
COOL&CONNECT

VIN: WF0PXXGCHPNJ64002



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. COOL&CONNECT	
Vehicle Identification number	WF0PXXGCHPNJ64002
Mileage (Read)	129,694 km
First registration	1 Sept 2022
Number of holders	1
Power / Engine displacement	88 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Silber-Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	71 %
Last service on / at	01/2026 at 121,724 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK832049
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BPV 00636		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,035 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	205/60 R16 92H	Winter tyres on Steel rim with wheel cover	2mm / 2mm
2)	205/60 R16 92H	Winter tyres on Steel rim with wheel cover	5mm / 5mm

Replacement			
Typ	Tyre size	Type of tyre	Tread depth
	Tirefit	Expiration date 05/2026	

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 6.5 J x 16 design wheels (4) with 205/60 R16 tires
- Hill start assist
- Roof rails, black
- Diesel particulate filter (DPF)
- Electronic Shifter
- Driver information system with on-board computer, color (10.7 cm screen diagonal)
- Electronic parking brake
- Luggage compartment cover
- Speed limiter
- Transmission: 8-speed automatic transmission
- Back window, heater
- Interior lighting with LED technology
- Isofix bracket
- Headrests: 2 front and 3 rear, height adjustable
- Leather gear knob
- Adjustable steering column
- Center console "Premium" front
- Front and rear parking pilot system
- Post-Collision Assist
- Radio: Ford SYNC 3 Light with AppLink, 8" touchscreen and DAB/DAB+
- Headlight assistant with day/night sensor
- Seats: Passenger seat height-adjustable, manually
- Seats: Map grid on the driver's and front passenger's seat backrests
- Start-stop system
- Carpet floor mats in the front
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Attachment points behind the second row of seats for mounting the safety partition net
- Fabric headliner
- Roof spoiler painted in car color
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric windows front and rear
- FordPass Connect including eCall, live traffic information (only with navigation) and Wi-Fi hotspot
- Cruise control
- Illuminated glove compartment
- Rear window wiper
- Intelligent security system
- Air conditioning, manual
- LED headlights
- Steering wheel: 3-spoke design
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Upholstery: Cloth
- Pre-Collision Assist
- Tire repair kit
- Tire Pressure Monitoring System (TPMS)
- Electromechanical speed-dependent power steering
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest
- Seats: Front sports seats with enhanced lateral support
- 12-volt power outlet in the luggage compartment
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Package: Driver Assistance Package II (Drive Assist Intelligent adaptive cruise control Lane keeping assist Traffic jam assist with Stop&Go Traffic sign recognition Wrong-way driver warning radio Evasive steering assist Distance display and distance warning Driver drowsiness detection High beam assist (in conjunction with adaptive LED matrix headlights with glare-free high beam assist) Blind spot assist with cross traffic alert including emergency braking function (when reversing out of parking spaces) and trailer recognition Rear view camera with split view Electrically folding exterior mirrors with surround view)
- Paint finish: Metallic
- Package: Family Package I (Inductive charging station for mobile devices - Rear seat backrest, foldable, 60:40 split, additionally with pass-through function for skis - Rear center armrest with 2 cup holders - 2 USB ports on the rear center console)
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Safety partition net for luggage compartment



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyres - complete set - Differs from the original configuration - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Wheel / tyres	Wheel cover - front right side - Missing - Replace
4	Equipment	Tirefit filler - Expired - Replace
5	Electronic systems	Electronic systems - Functional / admissibility - Perform diagnosis
6	Wing mirror - right side	Cap - Scratch(es) - Smart repair
7	Door - front left side	Door - dent(s) - Smooth repair work
8	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
9	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
10	Side panel - rear right side	Sill - dent(s) - Smooth repair work
11	Indicator - front	Mirror - right side (Materialabtrag) - Scratched - Replace
12	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
13	Door - rear right side	Door - Scratch(es) - Smart repair
14	Drive train	Sleeve prop shaft - front left side (knarrt beim einlenken) - Broken / torn - Perform diagnosis
15	Tail light	Tail lamp - left side - Broken / torn - Replace
16	Door - front left side	Door - Deformed - Repair and paint
17	Bonnet	Bonnet - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Rear bumper	Spoiler - Scratch(es) - Smart repair
3	Door - front right side	Door - Scratch(es) - Smart repair
4	Trim / covers	Floor mats - Broken / torn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit compressor

Interior - Separation net

Equipment - Vehicle key with remote control



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Front, Side right, Provided by user / customer, from 24 Jul 2024	7.572,99 €

Repainting

No. Repainting

- Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
- Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	180 µm	Door - front right side	169 µm
-----------------------	--------	-------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Damage 1: Wheel / tyres: Tyres - complete set - Differs from the original configuration - No deduction



Damage 1: Wheel / tyres: Tyres - complete set - Differs from the original configuration - No deduction



Damage 1: Wheel / tyres: Tyres - complete set - Differs from the original configuration - No deduction



Damage 1: Wheel / tyres: Tyres - complete set - Differs from the original configuration - No deduction



Damage 3: Wheel / tyres: Wheel cover - front right side - Missing - Replace



Damage 4: Equipment: Tirefit filler - Expired - Replace



Damage 5: Electronic systems: Electronic systems - Functional / admissibility - Perform diagnosis




Damage 6: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 6: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 7: Door - front left side: Door - dent(s) - Smooth repair work



Damage 7: Door - front left side: Door - dent(s) - Smooth repair work




Damage 8: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 8: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 9: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 9: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 10: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 10: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 11: Indicator - front: Mirror - right side (Materialabtrag) - Scratched - Replace



Damage 11: Indicator - front: Mirror - right side (Materialabtrag) - Scratched - Replace



Damage 11: Indicator - front: Mirror - right side (Materialabtrag) - Scratched - Replace



Damage 12: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 13: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 13: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 13: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 14: Drive train: Sleeve prop shaft - front left side (knarrt beim einlenken) - Broken / torn - Perform diagnosis



Damage 14: Drive train: Sleeve prop shaft - front left side (knarrt beim einlenken) - Broken / torn - Perform diagnosis



Damage 14: Drive train: Sleeve prop shaft - front left side (knarrt beim einlenken) - Broken / torn - Perform diagnosis



Damage 15: Tail light: Tail lamp - left side - Broken / torn - Replace



Damage 15: Tail light: Tail lamp - left side - Broken / torn - Replace



Damage 15: Tail light: Tail lamp - left side - Broken / torn - Replace




Damage 16: Door - front left side: Door - Deformed - Repair and paint



Damage 16: Door - front left side: Door - Deformed - Repair and paint



Damage 16: Door - front left side: Door - Deformed - Repair and paint



Damage 16: Door - front left side: Door - Deformed - Repair and paint



Damage 17: Bonnet: Bonnet - Deformed - Repair and paint



Damage 17: Bonnet: Bonnet - Deformed - Repair and paint



Damage 17: Bonnet: Bonnet - Deformed - Repair and paint



Damage 17: Bonnet: Bonnet - Deformed - Repair and paint



Damage 17: Bonnet: Bonnet - Deformed - Repair and paint



Wear and tear 2: Rear bumper: Spoiler - Scratch(es) - Smart repair



Wear and tear 2: Rear bumper: Spoiler - Scratch(es) - Smart repair



Wear and tear 2: Rear bumper: Spoiler - Scratch(es) - Smart repair



Wear and tear 3: Door - front right side: Door - Scratch(es) - Smart repair



Wear and tear 3: Door - front right side: Door - Scratch(es) - Smart repair



Wear and tear 3: Door - front right side: Door - Scratch(es) - Smart repair



Wear and tear 4: Trim / covers: Floor mats - Broken / torn - No deduction



Missing part 3: Equipment: Vehicle key with remote control - Missing - Replace



Repainting 1: Mudguard - right side



Repainting 2: Door - front right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0PXXGCHPNJ64002

Hersteller / Modell: FORD FORD Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut.
COOL&CONNECT

Datum	KM-Stand	Beschreibung
22.01.2026	121.724	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben+Beläge v+h; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.11.2024	91.765	Batterie ern; Reparatur Sonstiges; Systemtest/Eigendiagnose
18.07.2024	86.819	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.02.2024	61.234	Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben+Beläge v+h; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.03.2023	31.796	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges