



Vehicle details

VIN	WF0TK3SU8 MMA15269	Brand	FORD	Maintenance date	-
Licence Plate		Model	Mustang Mach-E 98kWh Extended Range First Edition	Maintenance mileage	-
Registration date	23/07/2021	Year	2021	Exterior Color	Red Metallic
Odometer	86 217 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date		20/07/2026		Inspection loc.					
									
									
									
									

Generic equipment

Automated air-conditioning	✔
Cruise control	✔
Leather	✔
GPS system	✔
Alloy wheel rims	✔
Automatic Gearbox	✔
Heating seats	✔
Electric seats	✔
Tow	✔
Metallic paint	✔
Central locking	✔
Electric windows	✔
4x4	✔
Park Distance Control	✔
Audio System	✔
Led lighting	✔

Removable element


Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	
Remote key	
Sat Nav CD ROM Software	

Tyres

Michelin 225/55/19 All seasons 4.0 mm




Michelin 225/55/19 All seasons 4.0 mm



Winter kit

Pirelli 225/55/19 Winter 4.0 mm




Pirelli 225/55/19 Winter 4.0 mm




Exterior

1



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3




Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

4




Part	Spoiler
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



Part	Wing moulding
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Alloy wheel 19"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7




Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Alloy wheel 19"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

9



Part	Wing moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Bumper
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



Part	Bumper
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Repair

