

Vehicle details

VIN	WVGZZZE2Z NP018536	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh 150kW Pro Auto 5d Onze Deal	Maintenance mileage	-
Registration date	28/12/2021	Year	2021	Exterior Color	Blue Metallic
Odometer	143 647 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 02/07/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓





Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓









Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 235/55/19 Summer 5.0 mm			Pirelli 235/55/19 Summer 5.0 mm	
Pirelli 235/55/19 Summer 5.0 mm			Pirelli 235/55/19 Summer 5.0 mm	

Exterior

1		<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	2		<table border="0"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Door																								
Position	Back left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Wing																								
Position	Back left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
3		<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	4		<table border="0"> <tr><td>Part</td><td>Spoiler</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Spoiler	Position	Back	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Roof																								
Position	-																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Spoiler																								
Position	Back																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
5		<table border="0"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Tailgate / Boot door	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	6		<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Dented	Severity	-	Repair mode	Repair
Part	Tailgate / Boot door																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Door																								
Position	Back right																								
Damages	Dented																								
Severity	-																								
Repair mode	Repair																								
7		<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Dented	Severity	-	Repair mode	Repair	8		<table border="0"> <tr><td>Part</td><td>Alloy wheel 19"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 19"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Door																								
Position	Front right																								
Damages	Dented																								
Severity	-																								
Repair mode	Repair																								
Part	Alloy wheel 19"																								
Position	Front right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								