

INSPECTION REPORT


End of contract

GENERAL INFO

File	305527
License plate	1YRL815
Vehicle identification number	W0VVS3601LB215037
Dossier	2019290173
Make	Opel Mov.CDTI 150 L2H1 3.5T DC
Mileage	53255
First registration	01/01/2021
client availability date	11/02/2026
inspectionDate	05/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	









DAMAGES


Damages	Type	Acceptable
77	Side View Mirror Left / Shell / Replace Not Painted	N
78	Side View Mirror Left / Direction Indicator / Replace	N
12	Bumper Front // Smart Repair Large	N
244	Light / Front Right / Replace	N
81	Door Front Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
654	Lettering Removal 15min	N
35	Front Bonnet // Polish	Y
54	Headlight / Front left / Replace	Y
65	Wing Front Left // Replace & Painting	N
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	Y
98	Rocker Panel Left / Cover Not Painted / Replace	Y
193	Door Rear Right // Painting	N
205	Rocker Panel Right // Polish	Y
208	Rocker Panel Right / Cover Not Painted / Replace	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
412	Seat Front Left / Bottom Coating / Replace	Y
422	Seat Front Right / Bottom Coating / Replace	Y
540	Interior // Repair 1	N
614	Front Left Door Interior Coating // Replace Completely	Y

Damage Pictures





Damage within Renta-norm-hole



Front Left Door Interior Coating // Replace Completely-scratch




Side View Mirror Right / Shell / Replace Not Painted-scratch




Rocker Panel Right // Polish-scratch





Rocker Panel Left // Smart Repair Medium-scratch







Seat Front Left / Bottom Coating / Replace-scratch




Headlight / Front left / Replace-scratch



Door Front Left // Smart Repair Medium-dent



Front Bonnet // Polish-scratch



Wing Front Left // Replace & Painting-scratch + dent



Door Rear Right // Painting-scratch + dent



Interior // Repair 1-worn



Rocker Panel Right / Cover Not Painted / Replace-Chipped paint



Rocker Panel Left / Cover Not Painted / Replace-Chipped paint



Seat Front Right / Bottom Coating / Replace-hole



Side View Mirror Left / Direction Indicator / Replace-scratch



Side View Mirror Left / Shell / Replace Not Painted-cracked




Lettering Removal 15min-




Bumper Front // Smart Repair Large-scratch



Light / Front Right / Replace-cracked



Door Front Left // Smart Repair Medium-dent



Door Rear Left // Repair & Painting-scratch + dent