



Ford Focus: [redacted]			
Vinnumber:	WF0PXXGCHPMM37679	Versionname:	FORDFOCUS CLIPPER 1.5 EcoBlue 88kW Connected
First Registrationdate:	12/04/2021	Fiscalpower:	120PK 5d/p MAN6 (B5M7)
Expertise Mileage:	133797	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3504
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

205/60/16/92 H				
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				3.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			963,99
Steering wheel, Worn, Acceptable			0,00



Floor covering FL, Hole, Replace

543,00



Bumper F, Scratch(es), Acceptable

0,00



Door seal FL, Broken, Replace

97,02



Step L, Dent(s), Paintless dent repair

95,47



Roof pillar L, Bad repair, Check

0,00




Roof pillar L, Dent(s), Acceptable

0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

133,03



Wing RL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable 0,00



Bumper moulding R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Wing RR, Dent(s), Paintless dent repair 95,47



Door RR, Scratch(es), Acceptable 0,00



Door FR, Dent(s) and scratch(es), Acceptable 0,00



Roof pillar R, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00

