



Expertise

Protocol number: 47029000
Order No. / Reference: 26652165-1
Inspection date: 29 Jul 2026

Manufacturer: Iveco
VIN: ZCFCR35A805543646

Model: 35 S 14NA8 V



Vehicle details	
Manufacturer / Type / Model / Equipment	
Iveco 35 S 14NA8 V	
Vehicle Identification number	ZCFCR35A805543646
Mileage (Read)	68,809 km
First registration	28 Jun 2023
Number of holders	1
Fuel type	Natural gas
Engine displacement / Cylinder	2,998 ccm / 4
Power	100 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Weiss
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	
Last service on / at	06/2025 at 64,136 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV979837
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	4192 / 000 000		
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115S	Winter tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	235/65 R16 115S	Winter tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112T	Summer tyres on Steel	Bridgestone	7mm / 7mm
2)	225/65 R16 112T	Summer tyres on Steel	Bridgestone	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • AdBlue tank 20l • Dashboard Comfort • Electrically adjustable and heated exterior mirrors • On-board computer • Diesel particulate filter • First aid kit • Electric window regulators, left and right • Generator Eco-Smart 3080 W (14 V x 220 A) • Transmission: 8-speed automatic • Panel van, partially glazed • Fuel tank 70 l • Radiator grille with chrome inserts • Manual headlight range adjustment • Upholstery: Cloth • Tire repair kit • Rear wall paneling of the driver's cab • Power steering • Seat: Passenger bench seat with three-point seatbelt for middle seat • Splash guard flaps • Partition wall to the cargo area • Maintenance indicator • Windscreen and side windows of the driver's cab tinted | <ul style="list-style-type: none"> • Driver airbag with seatbelt tensioner • Bodybuilder interface • 110 Ah battery • third brake light • Tachometer • Window: Sliding window on the right side of the sliding door • Transmission: 6-speed manual transmission • Rear door, opening angle 180° • Headrests (3) • Heated crankcase ventilation • Paint finish: Solid color paint • Model designation on both sides • Tires: 225/65 R 16 • Wheels: Steel rims 6.5 J x 16 • Sliding door on the right side • Seat belts, height-adjustable for driver and passenger seats • Mud flaps front and rear • TFT display instrument cluster in color • Preparation for trailer socket • Electronic immobilizer • Central locking with remote control |
|--|---|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Floor mats, rubber, front | <ul style="list-style-type: none"> • Front parking distance control including installation |
|---|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Bonnet	Insulation lining - Soiled - Replace
3	Boot lid / rear door	Rear door - left side - dent(s) - Smart repair
4	Boot lid / rear door	Rear door - right side - dent(s) - Smart repair
5	Misc.	Vehicle - Glued / labelled - De-glue / neutralise



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der montierte Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Damage 2: Bonnet: Insulation lining - Soiled - Replace



Damage 2: Bonnet: Insulation lining - Soiled - Replace



Damage 3: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 5: Misc.: Vehicle - Glued / labelled - De-glue / neutralise



Damage 5: Misc.: Vehicle - Glued / labelled - De-glue / neutralise



Damage 5: Misc.: Vehicle - Glued / labelled - De-glue / neutralise