



Expertise

Protocol number: 46707843
Order No. / Reference: 26795076
Inspection date: 24 Jul 2026

Manufacturer: Ford

Model: Transit 350 L4H3 Lkw HA Trend

VIN: WF0EXXTTREMUM21977



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit 350 L4H3 Lkw HA Trend	
Vehicle Identification number	WF0EXXTTREMUM21977
Mileage (Read)	76,738 km
First registration	26 Jul 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	136 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	15,000 km
Last service on / at	04/2023 at 39,555 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FZ491366
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BSA 00907		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	All-season tyres on Steel	Continental	8mm / 8mm
2)	235/65 R16 115R	All-season tyres on Steel	Continental	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115S C	All-season tyres on Steel	Goodyear	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- On-board computer (with fuel consumption and mileage information (e.g. remaining range) as well as outside temperature display and Ford ECO mode)
- Tachometer
- Third brake light
- Front electric windows (with quickdown/up function for driver's side)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Generator, high-performance version
- Transmission: 6-speed transmission
- Lockable glove compartment with lid
- Interior lighting with delay function (with reading lights at the front)
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering "Easy Clean"
- MyKey key system (individually programmable secondary key)
- Front and rear parking pilot system
- Radio: Audio system 13 (Radio (FM/AM) - DAB/DAB+ - MyFord Dock - FordPass Connect - Four speakers, antenna - Audio remote control on the steering wheel - Bluetooth interface - USB port - Hands-free system)
- Sliding door entry light automatically illuminates when the door is opened
- Rear mud flaps
- Side wall cladding up to the roof
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened driver's seat belt)
- Start-stop system
- Rear bumper with integrated step
- Partition wall (plastic) at the height of the B-pillar
- Lashing eyes
- Immobiliser
- Heat-insulating glazing, lightly tinted
- Second key with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated (with integrated turn signals)
- roof, high
- Double-wing rear doors with a 256° opening angle, (without windows) (without rear windows, with holding magnets)
- Electronic Stability Program (ESP) with Traction Control System (TCS) (Hill Start Assist - Crosswind Assist - Emergency Brake Assist - Rollover Protection)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Cruise control system including leather steering wheel (steering wheel with audio remote control (operation of the audio system and the on-board computer))
- Front air conditioning (including dust and pollen filter)
- Fuel tank 70 l
- Cargo area lighting
- Steering column, adjustable in height and reach
- Fog light
- Emergency brake assist including emergency brake light
- Particulate filter: diesel particulate filter
- Wheels: Wheel trims
- Wheels: Tire repair kit
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Headlight low beam: Halogen headlights with daytime running lights
- Sliding door: Sliding door, right
- Side protection strips
- Power steering
- Seats: Seat package 13 (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - double passenger seat with storage compartment under individually foldable seat cushions - height-adjustable headrests - integrated tray in the double passenger seat (foldable) - interior armrest for driver - manual lumbar support (driver's seat) - seat cover: fabric)
- Central locking with remote control
- Front overhead storage compartment



Extra equipment

- Blind Spot Assist incl. Cross Traffic Alert (Trend) (Electrically Folding Exterior Mirrors)
- Exterior mirrors, electrically adjustable, heated and folding (with integrated turn signals)
- LED lights in the cargo area
- Package: Visibility Package III (Trend, Limited) (Electrically folding exterior mirrors - Lane Keeping Assist with Driver Alert and High Beam Assist - Heated windscreen - High-mounted LED downlights - Adjustable instrument lighting - Front and rear parking sensors - Rearview camera with image transmission of the rearward driving path on the display - Windscreen wipers with rain sensor - Headlight assist with day/night sensor - Windscreen washer fluid level sensor)
- Reversing camera (reversing camera with image transmission of the rear driving path in the multifunction display and coupling aid - with high-mounted LED exterior light "downlight")
- Wheels/Tires: Spare wheel, steel wheel
- Battery: Extended battery life, battery life can be programmed to 30 minutes
- Front and rear parking pilot system (also with side sensors)
- Package: Express Line (Plastic side wall cladding (4.8 mm) - Wooden floor in the cargo area (9 mm) - Airline rails on the side walls right and left at heights of 550/650 mm and 1575/1675 mm - 6 lashing eyes - Partition (plastic))
- Radio: Audio system 21: Ford audio system with 8" multifunction display
- Seats: Seat Package 15 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated (fold-out) tray in the double passenger seat - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Manual lumbar support (driver's seat) - Seat upholstery: fabric)
- Wheels: Steel wheels 6.5 J x 16, winter tires, suitable for all seasons (replace standard tires) (with 235/65 R 16 tires)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Reflector - right side - Broken / torn - Replace
2	Indicator - front	Mirror - right side - Scratch(es) - Replace
3	Rear bumper	Rear bumper (unpainted) - dent(s) - Loss in value
4	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Smart repair
5	Boot lid / rear door	Rear door - left side (Innenverkleidung) - Broken / torn - Replace
6	Trim / covers	Cargo area - lining - right side - Holes - Replace
7	Sill - right side	Trim - Scratch(es) - Replace
8	Engine	Engine cover - Damage caused by marten / rodent - Replace
9	Roof	Roof (vorne) - Corrosion - Paint
10	Boot lid / rear door	Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint
11	Sliding door, right	Sliding door - Dent / paintcoat damage - Paint



Wear and tear

No.	Component group	Description
1	Door - front right side	Door - Scratch(es) - No deduction
2	Side panel - rear right side	Side panel - Scratch(es) - No deduction
3	Roof	Roof rail - right side - Scratch(es) - No deduction
4	Indicator - front	Mirror - left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.





Figure 28: Misc.



Figure 29: Misc.



Damage 1: Rear bumper: Reflector - right side - Broken / torn - Replace



Damage 1: Rear bumper: Reflector - right side - Broken / torn - Replace



Damage 2: Indicator - front: Mirror - right side - Scratch(es) - Replace



Damage 2: Indicator - front: Mirror - right side - Scratch(es) - Replace



Damage 3: Rear bumper: Rear bumper (unpainted) - dent(s) - Loss in value




Damage 3: Rear bumper: Rear bumper (unpainted) - dent(s) - Loss in value



Damage 3: Rear bumper: Rear bumper (unpainted) - dent(s) - Loss in value



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side (Innenverkleidung) - Broken / torn - Replace



Damage 5: Boot lid / rear door: Rear door - left side (Innenverkleidung) - Broken / torn - Replace



Damage 6: Trim / covers: Cargo area - lining - right side - Holes - Replace



Damage 6: Trim / covers: Cargo area - lining - right side - Holes - Replace




Damage 7: Sill - right side: Trim - Scratch(es) - Replace




Damage 7: Sill - right side: Trim - Scratch(es) - Replace




Damage 7: Sill - right side: Trim - Scratch(es) - Replace



Damage 8: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 9: Roof: Roof (vorne) - Corrosion - Paint



Damage 9: Roof: Roof (vorne) - Corrosion - Paint




Damage 10: Boot lid / rear door: Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint



Damage 10: Boot lid / rear door: Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint



Damage 10: Boot lid / rear door: Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint



Damage 10: Boot lid / rear door: Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint



Damage 10: Boot lid / rear door: Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint




Damage 10: Boot lid / rear door: Rear door - right side (+ Innenverkleidung erneuern) - Deformed - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint




Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 11: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0EXXTTREM U21977
Hersteller / Modell: FORD FORD Transit 350 L4H3 Lkw HA Trend

Datum	KM-Stand	Beschreibung
13.04.2023	39.555	Motoröl b. Wartung; Regelwartungsdienst