



Expertise

Protocol number: 46864235
Order No. / Reference: 26776811
Inspection date: 3 Aug 2026

Manufacturer: Opel	Model: Astra 1.5 D Start/Stop Sports Tourer Automatik Elegance
VIN: W0VBE8EV6N8039834	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Automatik Elegance	
Vehicle Identification number	W0VBE8EV6N8039834
Mileage (Read)	178,059 km
First registration	10 Jun 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	70 %
Last service on / at	05/2026 at 172,005 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ647687
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALM 00231		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Continental	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Ambient lighting, front doors
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof rails, silver
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Front camera
- Transmission: 9-speed automatic transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Steering column, height and reach adjustable
- Sliding center armrest, front
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Tire pressure monitoring system
- Power steering
- Luggage compartment safety net
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches
- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Decorative trim strips in piano black
- Tachometer
- Electric windows front and rear
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Automatic climate control, two zones
- trunk light
- Front headrests
- LED headlights
- Light alloy wheels 7 J x 16 in a "10-spoke" design
- Lighting equipment
- Electric parking brake
- Upholstery: Fabric/Premium leather look
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield



Extra equipment

- Detachable trailer hitch (including trailer stability program TSP)
- High Gloss Black Exterior Equipment (Sports Tourer) (Roof design line, top in high gloss black - radiator grille, frame in high gloss black - roof rails in high gloss black)
- Paint finish: Metallic
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Package: Elegance Package (IntelliLux LED Matrix headlights - LED taillights - Multimedia Navi Pro voice control touchscreen color display multimedia radio Apple CarPlay/Android Auto Bluetooth - Solar Protect heat-insulating glazing, heavily tinted, in the rear)
- Seats: Ergonomic active seat, driver and front passenger (certified by the Campaign for Healthy Backs (AGR) Driver and front passenger seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)
- Electric tailgate with foot sensor (Sensor-controlled electric tailgate, self-opening and closing via foot gesture or push of a button, including keyless locking and starting system Keyless Open & Start)
- Interior equipment Sports Tourer (rear seat backrest foldable in 40:20:40 ratio - rear center armrest with pass-through from the luggage compartment - FlexFold rear seat backrest)
- Fog light
- Park & Go Digital (Automatic parking assistant including parking pilot, front and rear parking aid - blind spot warning in both exterior mirrors - electrically folding exterior mirrors - digital reversing camera with steering guidelines)
- Electric sliding/tilting sunroof (with pre-selection function and spoiler position, including anti-pinch protection, comfort closing function via remote control of the central locking system (only in conjunction with electric windows, front and rear), and manually operated sunshade)
- Phone: Wireless charging including 2 USB ports, rear

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smooth repair work
2	Door - front right side	Door - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Smart repair
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Smart repair
5	Body	A-pillar - right side - Scratch(es) - Smart repair
6	Side panel - rear left side	Elbow - Scratched - Paint
7	Front bumper	Spoiler - Scratched - Replace
8	Sill - left side	Sill (Einstieg Tür vorn links) - Scratch(es) - Paint
9	Sill - right side	Sill (Einstieg vorn rechts) - Scratch(es) - Paint
10	Sill - right side	Sill - Scratched - Repair and paint
11	Rear bumper	Rear bumper - Scratched - Paint
12	Front bumper	Front bumper - Scratched - Paint
13	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
14	Door - front left side	Door - Scratch(es) - Paint
15	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
16	Roof	Roof - Scratch(es) - Paint



Missing parts

Description

Equipment - Tirefit complete

Repainting

No. Repainting

1 Side panel - rear left side

Paint coat thickness measurement

Side panel - rear left side

211 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Damage 1: Door - front right side: Door - dent(s) - Smooth repair work



Damage 1: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - Scratch(es) - Smart repair



Damage 2: Door - front right side: Door - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Smart repair




Damage 5: Body: A-pillar - right side - Scratch(es) - Smart repair




Damage 5: Body: A-pillar - right side - Scratch(es) - Smart repair




Damage 6: Side panel - rear left side: Elbow - Scratched - Paint




Damage 6: Side panel - rear left side: Elbow - Scratched - Paint




Damage 7: Front bumper: Spoiler - Scratched - Replace



Damage 7: Front bumper: Spoiler - Scratched - Replace



Damage 7: Front bumper: Spoiler - Scratched - Replace




Damage 7: Front bumper: Spoiler - Scratched - Replace



Damage 8: Sill - left side: Sill (Einstieg Tür vorn links) - Scratch(es) - Paint



Damage 8: Sill - left side: Sill (Einstieg Tür vorn links) - Scratch(es) - Paint



Damage 8: Sill - left side: Sill (Einstieg Tür vorn links) - Scratch(es) - Paint



Damage 9: Sill - right side: Sill (Einstieg vorn rechts) - Scratch(es) - Paint



Damage 9: Sill - right side: Sill (Einstieg vorn rechts) - Scratch(es) - Paint



Damage 10: Sill - right side: Sill - Scratched - Repair and paint



Damage 10: Sill - right side: Sill - Scratched - Repair and paint



Damage 11: Rear bumper: Rear bumper - Scratched - Paint



Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 12: Front bumper: Front bumper - Scratched - Paint



Damage 12: Front bumper: Front bumper - Scratched - Paint




Damage 12: Front bumper: Front bumper - Scratched - Paint



Damage 12: Front bumper: Front bumper - Scratched - Paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint




Damage 14: Door - front left side: Door - Scratch(es) - Paint




Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 16: Roof: Roof - Scratch(es) - Paint



Damage 16: Roof: Roof - Scratch(es) - Paint



Damage 16: Roof: Roof - Scratch(es) - Paint



Missing part 1: Equipment: Tirefit complete - Missing - Replace



Side panel - rear left side: 211 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBE8EV6N8039834

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Automatik Elegance

Datum	KM-Stand	Beschreibung
21.05.2026	172.005	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
28.11.2025	153.121	Wasserpumpe ern
07.11.2025	151.653	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.06.2025	134.002	HU + AU; Kondensator ern; Reparatur Sonstiges; Trockner Klima ern
05.03.2025	121.692	Bremse Sonstiges; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
21.01.2025	116.236	Kraftstofffilter ern; Luftfiltereinsatz ern; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
21.06.2024	86.254	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
13.12.2023	62.120	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
20.02.2023	29.595	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges