

DEKRA Automotive Solutions

Vehicle details

VIN	VR7BAHNSA NE050298	Registration date	01/01/1900	Exterior Color	Unknown
Brand	CITROEN	Licence Plate	GJ343SX	Odometer	44 643 km
Model	C4				

Inspection Details

Arrival Date	28/08/2024	Inspection ID	5429272	Inspection date	03/09/2024
Assign Date	28/08/2024	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment


Removable element

Emergency compressor kit	✓
Triangle	✓
Fire extinguisher	✓
Floor mat BR	✗
Floor mat BL	✗
Floor mat FR	✗
Floor mat FL	✗

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Log books	✓
First aid kit	✓
Spare key	✓
Key	✓
Certificate of conformity	✗
Title / License document	✗

Tyres





Front left: Michelin 195/60/18 H Summer 7.0 mm

Front right: Michelin 195/60/18 H Summer 7.0 mm








Rear left: Goodyear 195/60/18 H Summer 6.0 mm

Rear right: Goodyear 195/60/18 H Summer 6.0 mm

Damages

1		Part	Alloy wheel 18"	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	165.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	165.00€	Net Cost	165.00€
		● ● ● ●					
2		Part	Unpainted bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	90.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	90.00€	Net Cost	90.00€
		● ● ● ●					

DEKRA Automotive Solutions

3		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
4		Part	Windscreen	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	99.00€
		Damages	Stone impact	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	99.00€	Net Cost	99.00€
5		Part	Unpainted bumper	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
6		Part	Interior complete	Repair Time	1.00	Part Cost	-
		Position	-	Repair Cost	60.00€	Gross Cost	60.00€
		Damages	Stained/dirty	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Cleaning	Flat Rate	60.00€	Net Cost	60.00€
7		Part	Floor mat	Repair Time	0.10	Part Cost	56.67€
		Position	Front left	Repair Cost	6.00€	Gross Cost	62.67€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	62.67€
8		Part	Title / License document	Repair Time	-	Part Cost	250.00€
		Position	-	Repair Cost	-	Gross Cost	250.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	250.00€
9		Part	Certificate of conformity	Repair Time	-	Part Cost	250.00€
		Position	-	Repair Cost	-	Gross Cost	250.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	250.00€

Comments

wagen Interieur en exterior vuil!

Summary Inspection

Gross Price	976.67€	Depreciation	-	Net Price	976.67€
-------------	---------	--------------	---	-----------	---------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	60.00€	1.10	66.00€	-	-	66.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	556.67€	-	-	556.67€
Flat Rate	354.00€	-	-	354.00€

Signatures
Signature Receiver
Signature Expert
Signature Customer / Driver