



Skoda Octavia (UKL): 2AMB838

Vinnumber:	TMBJW9NX5MY139660	Versionname:	Octavia Combi Clever 1.4TSi iV 204pk/cv 5p DSG6
First Registrationdate:	10/05/2021	Fiscalpower:	
Expertise Mileage:	77041	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 10300 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	3	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/18/98 Y			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/45 R 18 98 Y
Tyre size FR				225/45 R 18 98 Y
Tyre size RL				225/45 R 18 98 Y
Tyre size RR				225/45 R 18 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Floor covering FL, Worn, Check



Seat cover R, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Ignition key, Not functioning (well), Acceptable



Bumper F, Scratch(es), Spot repair



Bumper moulding F, Scratch(es), Acceptable



Bonnet, Scratch(es), Polish



Windscreen, Not original part, Remove lettering



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door FL, Bad repair, Repair and paint (complete)



Door RL, Bad repair, Repair and paint (complete)



Wing RL, Dent(s), Acceptable



Luggage compartment cover, Stain, Acceptable



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Wheel aperture RL, Dent(s), Acceptable



Alloy rim RR polished, Scratch(es), Replace



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Roof, Scratch(es), Polish



Kenteken	2AMB838
Merk Model	Skoda Octavia Combi Clever 1.4TSi iV 204pk/cv 5p DSG6
Brandstofsoort	Benzine
Datum deel1	5/10/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/4/26	69,846	batterij	Vervangen
2/4/26	69,846	klein materiaal	
2/4/26	69,846	koelwatervloeistof	Bijvullen/-laden
2/4/26	69,846	ruitenwisservloeistof	Bijvullen/-laden
2/4/26	69,846	selectorhandel	Vervangen
2/4/26	69,846	Tussentijds onderhoud (vast interval)	Uitvoeren
4/10/25	57,876	airco systeem reiniging	Uitvoeren
4/10/25	57,876	batterij	Vervangen
4/10/25	57,876	bougie	Vervangen
4/10/25	57,876	Inspectie met olie vervanging (vast interval)	Uitvoeren
4/10/25	57,876	klein materiaal	
4/10/25	57,876	koelwatervloeistof	Bijvullen/-laden
4/10/25	57,876	luchtfILTER interieur	Vervangen
4/10/25	57,876	remvloeistof	Vervangen
4/10/25	57,876	ruitenwisserrubber achter	Vervangen
4/10/25	57,876	ruitenwisserrubber vooraan	Vervangen
4/10/25	57,876	ruitenwisservloeistof	Bijvullen/-laden
4/10/25	57,876	tech. keuring: nazicht/tijdens onderhoud	Uitvoeren
4/10/25	57,876	versnellingsbakolie	Vervangen
7/5/24	45,088	klein materiaal	Uitvoeren
7/5/24	45,088	ruitenwisservloeistof	Bijvullen/-laden
7/5/24	45,088	Tussentijds onderhoud (vast interval)	Uitvoeren
6/5/23	31,019	batterij	Vervangen
6/5/23	31,019	Inspectie met olie vervanging (vast interval)	Uitvoeren
6/5/23	31,019	klein materiaal	Uitvoeren
6/5/23	31,019	koelwatervloeistof	Bijvullen/-laden
6/5/23	31,019	luchtfILTER interieur	Vervangen
6/5/23	31,019	remvloeistof	Vervangen
6/5/23	31,019	ruitenwisserrubber achter	Vervangen
6/5/23	31,019	ruitenwisserrubber vooraan	Vervangen
6/5/23	31,019	ruitenwisservloeistof	Bijvullen/-laden
6/27/22	17,636	klein materiaal	Uitvoeren
6/27/22	17,636	Tussentijds onderhoud (vast interval)	Uitvoeren