

DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZ3CZ ME109772	Registration date	01/01/1900	Exterior Color	Unknown
Brand	VW	Licence Plate	2DMB321	Odometer	125 892 km
Model	PASSAT VARIANT				

Inspection Details

Arrival Date	28/05/2026	Inspection ID	7017917	Inspection date	22/06/2026
Assign Date	28/05/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment


Removable element

Rear parcel shelf	✓
Emergency compressor kit	✗
Refill emergency kit	✗

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres





Hankook 215/60/16 V Summer 5.0 mm

Hankook 215/60/16 V Summer 5.0 mm







Hankook 215/60/16 V Summer 5.0 mm

Hankook 215/60/16 V Summer 5.0 mm

Damages

1		Part	Emergency compressor kit	Repair Time	-	Part Cost	74.58€
				Repair Cost	-	Gross Cost	74.58€
		Position	-	Paint Time	-	Depreciation %	-
		Damages	Missing	Paint cost	-	Depreciation	-
		Severity	-	Flat Rate	-	Net Cost	74.58€
		Repair mode	Replace				
2		Part	Refill emergency kit	Repair Time	-	Part Cost	25.84€
				Repair Cost	-	Gross Cost	25.84€
		Position	-	Paint Time	-	Depreciation %	-
		Damages	Missing	Paint cost	-	Depreciation	-
		Severity	-	Flat Rate	-	Net Cost	25.84€
		Repair mode	Replace				

DEKRA Automotive Solutions

3		Part	Interior tailgate lining	Repair Time	1.00	Part Cost	-
		Position	-	Repair Cost	75.00€	Gross Cost	75.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	75.00€	Net Cost	75.00€
renovateur plastique sous reserve							
4		Part	Bonnet	Repair Time	1.00	Part Cost	-
		Position	Front	Repair Cost	75.00€	Gross Cost	262.00€
		Damages	Improper repair	Paint Time	2.20	Depreciation %	-
		Severity	-	Paint cost	187.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	262.00€
mauvaise repaatio/rouillé							
5		Part	Bumper	Repair Time	0.50	Part Cost	-
		Position	Front right	Repair Cost	37.50€	Gross Cost	37.50€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	37.50€	Net Cost	37.50€
6		Part	Bumper	Repair Time	0.50	Part Cost	-
		Position	Back	Repair Cost	37.50€	Gross Cost	37.50€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	37.50€	Net Cost	37.50€
7		Part	Wing	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
8		Part	Door sill	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-

Summary Inspection

Gross Price	512.42€	Depreciation	-	Net Price	512.42€
-------------	---------	--------------	---	-----------	---------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	75.00€	3.00	225.00€	-	-	225.00€
Paintwork	85.00€	2.20	187.00€	-	-	187.00€
Paint preparation	85.00€	0.00	0.00€	-	-	0.00€

DEKRA Automotive Solutions
Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	100.42€	-	-	100.42€
Flat Rate	0.00€	-	-	0.00€

Signatures
Signature Receiver
Signature Expert
Signature Customer / Driver
