



Expertise

Protocol number: 46652776
Order No. / Reference: 26701687
Inspection date: 22 Jul 2026

Manufacturer: Opel

Model: Corsa 1.2 Start/Stop Elegance

VIN: VXXUPHMHDP4069224



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Corsa 1.2 Start/Stop Elegance	
Vehicle Identification number	VXXUPHMHDP4069224
Mileage (Read)	49,473 km
First registration	20 Jun 2023
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	55 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Arktis Weiß uni
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Blue-Black
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	19,800 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS819878
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1889 / ABT 00168		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,550 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartments
- Airbag: Front airbags, driver and front passenger
- Airbag: Side airbag for driver and front passenger side
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Tachometer
- Electronic Stability Program Plus (ESP Plus)
- Electric windows front and rear
- Pedestrian protection
- Intelligent speed control and limiter
- Back window, heater
- Child safety lock in the rear doors, manual
- Headrests (5)
- Steering wheel made of vegan synthetic leather, flattened at the bottom.
- Makeup mirror
- Fatigue detection
- Upholstery: Fabric/premium leatherette combination
- Radio: Multimedia radio with 7" touchscreen color display
- Wheels: 6.5 J x 16 alloy wheels in 4-twin-spoke design in silver
- Power steering
- Visibility equipment
- Seats: Rear seat backrest split 60:40, foldable
- Start/Stop System
- Traction Control (TC) Plus
- Traffic sign recognition
- Pre-wiring for child seat mounting system "ISOFIX"
- Heat-insulating glazing, tinted
- Ignition key (2)
- Adaptive brake light
- Airbag: Front and rear head airbags
- Anti-lock braking system (ABS)
- Hill Start Assist
- On-board computer
- Headliner, Grey
- Electronic brake force distribution (EBD)
- Driver information display 7", color
- Front collision warning system with automatic emergency braking and pedestrian detection
- Transmission: 5-speed manual transmission
- rear window wiper
- Air conditioning
- LED headlights
- Steering column, height and reach adjustable
- Headlight range adjustment, manual
- Center armrest with storage compartment in front
- Pollen filter
- Radio: Digital radio reception DAB+
- Tire pressure warning
- Wheels: Tire repair kit
- Side impact protection
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort driver's seat
- Lane Keeping Assist
- 12V power outlet in the center console, front
- Ambient lighting
- Pre-installation for ISOFIX child seat mounting system
- Immobiliser
- Central locking with remote control

Extra equipment

- Paint finish: Solid
- Wheels: All-weather tires 195/55 R16
- Parkpilot, rear parking aid (with acoustic warning signal when reversing)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.



Value reducing factors

No.	Component group	Description
1	Roof	Roof - dent(s) - Smooth repair work
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Bonnet	Insulation lining - Missing - Replace
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Rear bumper	Rear bumper - Scratched - Paint
6	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Mudguard - right side	Mudguard - right side - Soiled - No deduction
2	Tail light	Tail lamp - left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Roof: Roof - dent(s) - Smooth repair work



Damage 1: Roof: Roof - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 3: Bonnet: Insulation lining - Missing - Replace



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Rear bumper: Rear bumper - Scratched - Paint




Damage 5: Rear bumper: Rear bumper - Scratched - Paint



Damage 5: Rear bumper: Rear bumper - Scratched - Paint



Damage 5: Rear bumper: Rear bumper - Scratched - Paint



Damage 5: Rear bumper: Rear bumper - Scratched - Paint



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 1: Mudguard - right side: Mudguard - right side - Soiled - No deduction



Wear and tear 2: Tail light: Tail lamp - left side - Scratch(es) - No deduction