



Expertise

Protocol number: 46644092
Order No. / Reference: 26589039
Inspection date: 21 Jul 2026

Manufacturer: MAN
VIN: WMA03VUY8P9009509

Model: TGE 3,5T 4x2F



Vehicle details	
Manufacturer / Type / Model / Equipment	
MAN TGE 3,5T 4x2F	
Vehicle Identification number	WMA03VUY8P9009509
Mileage (Read)	86,485 km
First registration	23 Nov 2022
Number of holders	1
Next periodical technical inspection	01/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	103 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	14,700 km
Last service on / at	02/2025 at 63,475 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GR210237
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1516 / AYN 58721		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	Winter tyres on Steel rim with wheel cover	Sonstige	9mm / 9mm
2)	205/75 R16 113R	Winter tyres on Steel rim with wheel cover	Sonstige	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Dunlop	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Extra equipment

- Storage package 2
- Battery with increased capacity
- Fitting point
- Wooden floor in the cargo area with wheel arch cladding
- Center wheel cover with chrome emblem
- Steel spare wheel with road tires
- Side interior paneling in the cargo area made of plywood
- Rear step, across the entire width
- Driver and passenger airbags
- Cab doors, additionally with reinforced door seals
- All-season tyres
- MAN Media Van package with 4 speakers
- Smoker's version
- Rear View reversing camera
- Comfort seat, left
- Lashing rails in the cargo area

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Electrical system	Lighting system - on - Perform diagnosis
2	Boot lid / rear door	Rear door - left side (Verkleidung) - Broken / torn - Replace
3	Wheel / tyres	Spare wheel - Worn - Replace
4	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint
5	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
6	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Repair and paint

Missing parts

Description

Equipment - First aid kit

Equipment - Warning triangle

Equipment - Vehicle tool kit

Equipment - Vehicle jack

Repainting

No. Repainting

- 1 Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
- 2 Door - rear left side

Paint coat thickness measurement

Side panel - rear left side	204 µm	Door - rear left side	238 µm
-----------------------------	--------	-----------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Damage 1: Electrical system: Lighting system - on - Perform diagnosis




Damage 2: Boot lid / rear door: Rear door - left side (Verkleidung) - Broken / torn - Replace



Damage 2: Boot lid / rear door: Rear door - left side (Verkleidung) - Broken / torn - Replace



Damage 2: Boot lid / rear door: Rear door - left side (Verkleidung) - Broken / torn - Replace



Damage 3: Wheel / tyres: Spare wheel - Worn - Replace



Damage 3: Wheel / tyres: Spare wheel - Worn - Replace



Damage 3: Wheel / tyres: Spare wheel - Worn - Replace



Damage 4: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 4: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint




Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint




Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Repainting 2: Door - rear left side



Repainting 2: Door - rear left side



Side panel - rear left side: 204 µm



Door - rear left side: 238 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WMA03VUY8P9009509
Hersteller / Modell: MAN MAN TGE 3.140 4X2F SB

Datum	KM-Stand	Beschreibung
24.02.2025	63.475	AU; Bremsbelagfühler ern; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Reparatur Sonstiges; Wartung Sonstiges
08.01.2025	63.475	Reparatur Sonstiges
11.03.2024	37.755	Bremse Sonstiges; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges