



Expertise

Protocol number: 46695902
Order No. / Reference: 26631085
Inspection date: 22 Jul 2026

Manufacturer: Opel

Model: Insignia Sports Tourer 1.5 Diesel Automatik Elegance

VIN: W0VZT8EN6N1023906



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Insignia Sports Tourer 1.5 Diesel Automatik Elegance

Vehicle Identification number W0VZT8EN6N1023906
Mileage (Read) 163,837 km
First registration 9 Nov 2022
Number of holders 1
Next periodical technical inspection 11/2027
(Report on hand)

Fuel type Diesel
Engine displacement / Cylinder 1,496 ccm / 3
Power 90 kW
Gearbox / Number of gears Automatic / 8
Type of drive Front drive
Type of vehicle Station wagon

Colour / colour code Nautic Blau Metallic
Doors / Seats 5 / 5
Upholstery type Cloth / leather combination
Colour of upholstery Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	76 %
Last service on / at	04/2026 at 163,360 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN166450
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AME 00298		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,200 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98W	Summer tyres on Light alloy	Nexen	4mm / 4mm
2)	215/55 R17 98W	Summer tyres on Light alloy	Nexen	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Steel rim with wheel cover	Nexen	5mm / 5mm
2)	215/55 R17 98V	Winter tyres on Steel rim with wheel cover	Nexen	6mm / 6mm
3)	225/45 R17 91H	Winter tyres (Without wheel rim)	Pirelli	5 mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front airbags and side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Hill Start Assist
- third brake light
- Roof rails, silver anodized
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Driver information display, 3.5"
- Front collision warning system with pedestrian detection and automatic emergency braking
- Noise-reducing, laminated front side windows
- Transmission: 8-speed automatic transmission
- rear window wiper
- Automatic climate control, two zones
- Rear headrests (3 pieces)
- LED fog lights
- Steering column adjustable for height and reach
- Illuminated makeup mirrors in both sun visors
- Package: Innovations 1
- Parkpilot, front and rear parking aid
- Radio: Digital radio reception DAB+
- Tire repair kit
- Wheels: 7.5 J x 17 alloy wheels in a 5 double-spoke design
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Lane Keeping Assist
- Bumpers painted in body color
- Pre-installation for child seat mounting system "ISOFIX"
- Thermal insulation glazing, green tinted
- Adaptive brake light
- Airbag: Front and rear outer head airbags
- Ambient lighting
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- Glasses compartment in the headliner
- Decorative strip hexagon
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric windows front and rear
- Pedestrian protection including active hood
- luggage compartment cover
- Speed controller
- Back window, heater
- Child safety lock in the rear doors, manual
- Front headrests
- LED headlights
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Electric parking brake
- Quickheat rapid heating system
- Radio: Multimedia Radio 7" Touchscreen Color Display
- Tire pressure gauge
- Rear seat backrest folds forward in a 60:40 split
- Power steering
- safety net
- Seats: Ergonomic active seat (AGR) driver
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control

Extra equipment

- Package: Easy-Access (Keyless locking and starting system (Keyless Open & Start) - Sensor-controlled tailgate, electric - Loading sill protection, stainless steel)
- Upholstery: Monita fabric/Premium leather look including Winter Package 2 (Ergonomic active seat, certified by the Campaign for Healthy Backs (AGR), front/front seat heating, multi-stage, front/front heated leather steering wheel, heated ThermoTec windshield, Seat Comfort Equipment 1: 8-way electrically adjustable driver's seat, electro-pneumatically adjustable lumbar support, memory function - driver and exterior mirrors, massage function, front exterior mirrors, electrically adjustable, heated, folding rear seat backrest with FlexFold function, 40:20:40 split, Charging Package: Wireless charging, 2 USB ports)
- Fuma + safety set
- Paint finish: Metallic
- Park & Go with digital reversing camera (digital reversing camera - reversing assistant - lane change assistant - blind spot warning in both exterior mirrors)
- Radio: Multimedia Navi Pro with 8" color touchscreen display (voice control for audio, telephone and navigation, USB port, Bluetooth audio streaming, navigation system with SD card storage, connected navigation services, predictive navigation, online map updates, real-time traffic information, 8" driver information display, steering wheel controls, Apple CarPlay and Android Auto)
- Wheels: Additional set of 17" winter wheels - Design RZG



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Gearbox	Gearbox - Leaking - Perform diagnosis
2	Door - front left side	Door edge - Scratch(es) - Smart repair
3	Roof	Roof - dent(s) - Smart repair
4	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
5	Door - front right side	Door edge - Scratch(es) - Smart repair
6	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
7	Engine	Engine cover - Damage caused by marten / rodent - Replace
8	Instrument panel	Centre console - front (Ablagefachdeckel schließt nicht) - Malposition - Replace
9	Rear bumper	Rear bumper - Scratched - Paint
10	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace
11	Bonnet	Bonnet (Sandstrahleffekt) - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel




Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis




Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 3: Roof: Roof - dent(s) - Smart repair




Damage 3: Roof: Roof - dent(s) - Smart repair



Damage 4: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 4: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 5: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 5: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 5: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 5: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 7: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 7: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 8: Instrument panel: Centre console - front (Ablagefachdeckel schließt nicht) - Malposition - Replace



Damage 8: Instrument panel: Centre console - front (Ablagefachdeckel schließt nicht) - Malposition - Replace



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint




Damage 10: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace




Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT8EN6N1023906

Hersteller / Modell: OPEL OPEL Insignia Sports Tourer 1.5 Diesel Automatik Elegance

Datum	KM-Stand	Beschreibung
29.04.2026	163.360	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges; Wartung Sonstiges
28.11.2025	144.562	AU
29.08.2025	139.191	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
25.03.2025	114.671	Wartung Sonstiges
21.03.2025	114.671	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Wartung Sonstiges
21.02.2025	108.942	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges; Wartung Sonstiges
23.08.2024	83.176	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
16.02.2024	52.263	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges; Wartung Sonstiges
25.07.2023	31.403	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges