







2-FHA-986

2-FHA-986 · ST Line 1.0i EcoBoost 125pk M6 · 22 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FHA-986	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF02XXERK2RA29098
Model	Puma	Cylinder Capacity	999 ^{cm³}
Model Versions	ST Line 1.0i EcoBoost 125pk M6	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	07-05-2024
Color	Silver	Odometer	49.703 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	92	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	4 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Fender - Rear Left

Damage Type


Small scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Frontdoor - Left

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Alloy - Left Front

Damage Type

Damaged

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Rear

Damaged

Rim repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Small scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Small scratch(es)

Spray

No