

## Expertise

Protocol number: 46184185  
Order No. / Reference: 26639358  
Inspection date: 25 Jun 2026

Manufacturer: Volkswagen

Model: ID.4 Performance Upgrade Pro

VIN: WVGZZZE2ZNP029903



### Vehicle details

#### Manufacturer / Type / Model / Equipment

Volkswagen ID.4 Performance Upgrade Pro

**Vehicle Identification number** WVGZZZE2ZNP029903

**Mileage (Read)** 99,932 km

**First registration** 29 Mar 2022

**Number of holders** 1

**Next periodical technical inspection** 04/2027

(Report on hand)

**Power / Engine displacement** 70 kw /

**Fuel type / Cylinder** Electric / 0

**Gearbox / Number of gears** Direct drive / 1

**Type of drive** Rear drive

**Type of vehicle** SUV

**Colour / colour code** Mangangrau Metallic

**Doors / Seats** 5 / 5

**Upholstery type** Cloth

**Colour of upholstery** Black-Grey

**Vehicle with smoke odor** no

**readiness to drive** Roadworthy



## Vehicle details

<b>Maintenance booklet / proof</b>	digital proof / complete	<b>Next maintenance in</b>	612 Tag(e)
<b>Last service on / at</b>	02/2026 at 93,294 km		
<b>Key is / should be</b>	2 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		<b>Letter No.</b>	GJ091371
<b>Previous damage / Accident</b>	Detectable	<b>Repainting</b>	Detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	yes
<b>Test drive</b>	short drive on the company premises	<b>Engine function test</b>	Performed
<b>readiness to drive</b>	Roadworthy		
<b>Manufacturer key number/ type code number</b>	0603 / CLQ 00045		
<b>Emission standard</b>	2017/1151;WLTP;reine Elektrofz	<b>fine dust sticker</b>	
<b>Permitted total weight</b>	2,540 kg	<b>Empty weight</b>	

## Tyres

Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tires (with run-flat tires) on Light alloy	Pirelli	5mm / 5mm
2)	255/50 R19 103T	Summer tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Winter tires (with run-flat tires) on Light alloy	Bridgestone	7mm / 7mm
2)	255/50 R19 103T	Winter tires (with run-flat tires) on Light alloy	Bridgestone	6mm / 6mm

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment

### Standard equipment

- 2 USB-C ports on the front
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Ambient lighting, 10 colors
- Electrically adjustable, folding and heated exterior mirrors
- Car2X
- e-Sound
- ESP Electronic Stability Program
- Speed limiter
- Back window, heater
- Interior mirror automatically dimming
- "Climatronic" air conditioning system
- Paint finish: Solid
- Charging: 11 kW AC charging power (alternating current)
- LED headlights with automatic headlight control
- Makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery: Seat center panels of the front seats and the outer rear seats in "Matrix" fabric
- Tire pressure monitoring system
- LED taillights
- electromechanical power steering
- Seats: Armrest for front seats
- Seats: Driver's seat height adjustable
- Voice control
- Lane keeping assistant "Lane Assist"
- Ambient lighting with logo projection
- Traffic sign recognition
- Green thermal insulation glazing, sides and rear

### Extra equipment

- Paint finish: Metallic
- Wheels: Winter wheels (4) "Hamar" 8 J x 19 (total) in Dark Graphite/ gloss-turned (winter tires 235/55 R 19 T / 255/50 R 19 T)
- Heat pump for range optimization

- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect Wireless for Apple CarPlay and Android Auto
- third brake light
- black roof rails
- Parking assistance
- Driving profile selection
- Transmission: 1-speed automatic
- rear window wiper
- ISOFIX mounting points for child car seats
- Front and rear headrests (5)
- Mode 3 Type 2 charging cable, 16 A
- Charging: 125 kW DC charging power (direct current)
- Steering wheel: Multifunction steering wheel with touch controls
- Navigation system "Discover Pro"
- Emergency call service
- Package: Infotainment Package
- Radio "Ready 2 Discover"
- Radio accessories: 6 + 1 speakers
- Wheels: Steel wheels (4) 8 J x 19
- Keyless Start system
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking including remote control

- Wheels: Alloy wheels (4) "Hamar" 8 J x 19 in Dark Graphite, polished finish (Airstop all-season tires 235/55 R 19 front, Airstop all-season tires 255/50 R 19 rear - wheel locks with enhanced theft protection)



### Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

### Value reducing factors

No.	Component group	Description
1	Body	Body (Klebereste) - Glued / labelled - De-glue / neutralise
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Front bumper	Spoiler - Deformed - Replace
4	Vehicle glazing	Windscreen (reparierter Steinschlag) - Unprofessionally repaired - Replace

### Wear and tear

No.	Component group	Description
1	Door - rear left side	Door edge - Scratch(es) - No deduction
2	2nd wheel set	1 alloy rim (Optischer Mangel) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

### Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 21 Aug 2024	1.114,97 €
2	Front, Provided by user / customer, from 4 Sept 2022	4.062,64 €

### Repainting

No.	Repainting
1	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
2	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

### Paint coat thickness measurement

Side panel - rear left side	181 µm	Door - front left side	168 µm
-----------------------------	--------	------------------------	--------



## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise




**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise



**Damage 1:** Body: Body (Klebereste) - Glued / labelled - De-glue / neutralise




**Damage 2:** Door - front right side: Door - dent(s) - Smooth repair work



**Damage 2:** Door - front right side: Door - dent(s) - Smooth repair work



**Damage 3:** Front bumper: Spoiler - Deformed - Replace



**Damage 3:** Front bumper: Spoiler - Deformed - Replace



**Damage 3:** Front bumper: Spoiler - Deformed - Replace



**Damage 3:** Front bumper: Spoiler - Deformed - Replace



**Damage 4:** Vehicle glazing: Windscreen (reparierter Steinschlag) - Unprofessionally repaired - Replace



**Damage 4:** Vehicle glazing: Windscreen (reparierter Steinschlag) - Unprofessionally repaired - Replace



**Damage 4:** Vehicle glazing: Windscreen (reparierter Steinschlag) -  
Unprofessionally repaired - Replace



**Repainting 1:** Side panel - rear left side



**Repainting 2:** Door - front left side



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZE2ZNP029903

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN ID.4 Performance Upgrade Pro

Datum	KM-Stand	Beschreibung
27.02.2026	93.294	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
08.12.2025	84.176	Reparatur Sonstiges
05.11.2025	84.176	Wartung Sonstiges
13.03.2024	45.000	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst; Wartung Sonstiges