



Expertise

Protocol number: 46710040
Order No. / Reference: 26699257
Inspection date: 21 Jul 2026

Manufacturer: Fiat

Model: Scudo L2 Basis AT

VIN: VXFVFEHS7N7065607



Vehicle details	
Manufacturer / Type / Model / Equipment	
Fiat Scudo L2 Basis AT	
Vehicle Identification number	VXFVFEHS7N7065607
Mileage (Read)	125,737 km
First registration	16 Dec 2022
Number of holders	2
Next periodical technical inspection	12/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	106 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Weiss
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Grey-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	43,980 km
Last service on / at	05/2026 at 119,730 km		
Key is / should be	2 / 2	FZG documents	ZB#1+2 (B+S) was available (copy)
		Letter No.	GN089193
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	3003 / BCD 00723		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,795 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 109T	All-season tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	215/60 R17 109T	Winter tyres on Steel rim with wheel cover	Michelin	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/60 R17 109T C	Winter tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • ABS • Hill start assist • Third brake light • Transmission: 8-speed automatic • Air conditioning with pollen filter • Particulate filter: Soot particle filter for diesel engines • Radio: DAB radio with Bluetooth and USB • Tires: Tire repair kit • Tire pressure sensor • Wheels: Full-size spare wheel • Sliding door, side right, sheet metal cladding • Seat: Driver's seat height adjustable with armrest & lumbar support • Partition wall: steel, without windows | <ul style="list-style-type: none"> • Airbag: Driver and passenger airbags • Tachometer • Rear parking sensors • Rear wing doors, sheet metal, 180° opening • Paint finish: Solid color paint • Upholstery: Cloth • Radio accessories: Radio control satellite behind the steering wheel • Wheels: 16" steel rim with black hubcap • Windscreen wipers with rain sensor • Power steering • Seats: Driver/passenger seat with double armrests and headrests • Immobiliser |
|---|---|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • 13-pin fixed towbar • Grip Control ASR • Air conditioning (Automatic single-zone air conditioning with pollen filter and outside temperature display) • Screen-printed floor in the cargo area with aluminum protective edges • Bumpers, side protection & door handles in body color | <ul style="list-style-type: none"> • Increased payload + 400 kg • Keyless Entry and Go • Cargo area equipment • Rear view camera • Seats: Passenger bench seat with Moduwork function • Steel rim with full wheel covers, winter tires 215/60 • Auxiliary heater: Webasto (programmable) with radio remote control |
|---|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were available. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear right side - Scratched - Replace
2	Wheel / tyres	Wheel cover - front right side - Scratched - Replace
3	Sill - left side	Sill - Scratch(es) - Smart repair
4	Wheel / tyres	Tyre - front right side - Broken / torn - Replace
5	Side panel - rear right side	Side panel (+ Kratzer) - dent(s) - Smart repair
6	Vehicle glazing	Windscreen - Stone chips - Replace
7	Rear bumper	Rear bumper - Scratch(es) - Paint
8	Body	Body - Damage by hail - Smooth repair work



Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Sill - Scratch(es) - No deduction
2	Boot lid / rear door	Rear door - left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Damage 1: Wheel / tyres: Wheel cover - rear right side - Scratched - Replace



Damage 1: Wheel / tyres: Wheel cover - rear right side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 4: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 4: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 5: Side panel - rear right side: Side panel (+ Kratzer) - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Side panel (+ Kratzer) - dent(s) - Smart repair




Damage 5: Side panel - rear right side: Side panel (+ Kratzer) - dent(s) - Smart repair



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work




Damage 8: Body: Body - Damage by hail - Smooth repair work




Damage 8: Body: Body - Damage by hail - Smooth repair work




Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work




Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Damage 8: Body: Body - Damage by hail - Smooth repair work



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXFVFEHS7N7065607
Hersteller / Modell: FIAT FIAT Scudo L2 Basis AT

Datum	KM-Stand	Beschreibung
21.05.2026	119.730	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/Eigendiagnose; Wartung Sonstiges
09.02.2026	105.371	Bremsinspektion vo + hi; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne; Systemtest/Eigendiagnose
26.09.2025	86.433	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.12.2024	0	AU
14.06.2024	29.912	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges