



Expertise

Protocol number: 46643414
Order No. / Reference: 26577975
Inspection date: 21 Jul 2026

Manufacturer: Opel	Model: Grandland 1.5 D Automatik Business Elegance
VIN: W0VZCYHZ0N6806060	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Grandland 1.5 D Automatik Business Elegance	
Vehicle Identification number	W0VZCYHZ0N6806060
Mileage (Read)	143,017 km
First registration	7 Mar 2022
Number of holders	1
Next periodical technical inspection	02/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	27,500 km
Last service on / at	05/2026 at 140,577 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ637811
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AHG 00209		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	Summer tyres on Light alloy	Dunlop	5mm / 5mm
2)	225/55 R18 102V	Summer tyres on Light alloy	Dunlop	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/65 R17 103H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- 2 ignition keys, both foldable
- Storage compartments
- Airbag: Front and side airbags
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- On-board computer
- Decorative strips, Erino/Palladium Medium
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- luggage compartment cover
- Transmission: 8-speed automatic
- Interior lighting, front and rear
- IntelliLux LED Pixel Matrix Light
- Dual-zone automatic climate control
- Front headrests, height adjustable
- Leather steering wheel including remote control
- Illuminated makeup mirror in sun visor, for driver and front passenger
- Park & Go
- Radio: Multimedia Navi Pro
- Rain sensor
- Wheels: Light alloy 7.5 J x 18 with 5 double spokes in bicolor/black
- Seat belts
- Seats: Rear seat backrest split 40:60 and foldable
- Solar Protect thermal insulation glazing
- Start/Stop System
- Bumpers and side panels in high-gloss black
- Pre-wiring for ISOFIX child seat mounting system, including top tether attachment points, rear outer

Extra equipment

- Forward Collision Warning (monitors the distance (close, medium, far) to the vehicle ahead; if the vehicle approaches a vehicle ahead or a pedestrian too quickly, a warning tone sounds and a message appears in the driver information display. - with automatic emergency braking and pedestrian detection - Lane Keeping Assist: warns if the vehicle unintentionally leaves its lane - Traffic Sign Recognition - Driver Drowsiness Detection - Automatic Speed Assist with Stop&Go function - Automatic Headlights)
- Winter equipment (heated seats, multi-stage, driver and front passenger - heated ThermoTec windshield - FlexFold rear seat backrest split and foldable in a 40:60 ratio and center armrest, rear, with pass-through from the luggage compartment)

- 230V equipment
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Automatic activation of the hazard warning lights
- Exterior mirrors, electrically adjustable and heated, electrically folding
- Roof design line in chrome
- Diesel particulate filter with SCR and oxidation catalyst
- Electric parking brake
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning
- Cruise control with intelligent speed limiter
- rear window wiper
- Interior rearview mirror, automatically dimming
- Child safety lock in the rear doors, manual
- Rear headrests (3), height adjustable
- LED headlights
- Steering wheel, height and reach adjustable
- Center armrest, sliding, front, including storage compartment and cup holder
- Quickheat heating system
- Radio accessories: Digital radio reception DAB+
- Tire pressure warning
- Wheels: Tire repair kit
- Speed-sensitive power steering
- Seats: Ergonomic active seat with AGR seal of approval, driver
- Lane Assist
- 12-volt power outlet
- Phone: Charging equipment
- Immobiliser
- Central locking with remote control and interior switches

- Paint finish: Uni Jade White
- Package: Design package Business Elegance (Keyless locking and starting system "Keyless Open & Start" and sensor-controlled tailgate - roof rails in high-gloss black - roof in diamond black)
- Seats: Ergonomic active seats with AGR seal of approval, driver and front passenger (length, height and backrest angle manually adjustable - seat tilt electrically adjustable - lumbar support electropneumatically adjustable in height and length - extendable thigh support, manually adjustable - pocket on front seat back - all seats in fabric/premium leather look, black)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Scratched - Cover / polish
2	Sill - left side	Sill - Scratched - Cover / polish
3	Rear bumper	Rear bumper - Scratched - Cover / polish
4	Trim / covers	Door trim - front left side - Scratched - Smart repair
5	Door - rear right side	Door - Scratched - Smart repair
6	Roof	Roof rail - left side - dent(s) - Smooth repair work
7	Door - front left side	Door - Scratch(es) - Smart repair
8	Rear bumper	Spoiler - Scratched - Smart repair
9	Multimedia system	Multimedia system (Flackert) - Sub-function - Perform diagnosis
10	Front bumper	Spoiler - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Roof	Roof rail - left side - Stone chips - No deduction
3	Mudguard - right side	Mudguard - right side - Stone chips - No deduction
4	Roof	Roof rail - right side - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 28 Oct 2022	3.769,26 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Additional tyres



Figure 20: Additional tyres



Figure 21: Additional tyres



Figure 22: Additional tyres




Figure 23: Navigation



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.




Figure 38: Misc.



Figure 39: Misc.




Figure 40: Misc.



Figure 41: Misc.




Figure 42: Misc.



Damage 1: Boot lid / rear door: Boot lid - Scratched - Cover / polish



Damage 1: Boot lid / rear door: Boot lid - Scratched - Cover / polish



Damage 1: Boot lid / rear door: Boot lid - Scratched - Cover / polish



Damage 1: Boot lid / rear door: Boot lid - Scratched - Cover / polish



Damage 2: Sill - left side: Sill - Scratched - Cover / polish




Damage 2: Sill - left side: Sill - Scratched - Cover / polish



Damage 3: Rear bumper: Rear bumper - Scratched - Cover / polish




Damage 3: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage 3: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage 3: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage 4: Trim / covers: Door trim - front left side - Scratched - Smart repair




Damage 4: Trim / covers: Door trim - front left side - Scratched - Smart repair



Damage 5: Door - rear right side: Door - Scratched - Smart repair



Damage 5: Door - rear right side: Door - Scratched - Smart repair



Damage 5: Door - rear right side: Door - Scratched - Smart repair



Damage 5: Door - rear right side: Door - Scratched - Smart repair



Damage 6: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 6: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 7: Door - front left side: Door - Scratch(es) - Smart repair



Damage 7: Door - front left side: Door - Scratch(es) - Smart repair



Damage 8: Rear bumper: Spoiler - Scratched - Smart repair




Damage 8: Rear bumper: Spoiler - Scratched - Smart repair



Damage 9: Multimedia system: Multimedia system (Flackert) - Sub-function - Perform diagnosis



Damage 10: Front bumper: Spoiler - Scratched - Smart repair



Damage 10: Front bumper: Spoiler - Scratched - Smart repair



Damage 10: Front bumper: Spoiler - Scratched - Smart repair



Damage 10: Front bumper: Spoiler - Scratched - Smart repair



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZCYHZ0N6806060

Hersteller / Modell: OPEL OPEL Grandland 1.5 D Automatik Business Elegance

Datum	KM-Stand	Beschreibung
12.05.2026	140.577	Bremsflüssigkeit; Bremsflüssigkeit ern; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
13.10.2025	121.374	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/Eigendiagnose; Wartung Sonstiges
30.04.2025	104.870	Systemtest/Eigendiagnose
17.02.2025	101.126	Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; HU + AU; Keilrippenriemen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.08.2024	80.290	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.01.2024	61.268	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
25.07.2023	43.439	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
16.12.2022	25.061	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges