



Expertise

Protocol number: 46887168
Order No. / Reference: 26847373
Inspection date: 4 Aug 2026

Manufacturer: Skoda
VIN: TMBJP6NJ2MZ062876

Model: Fabia Combi 1.0 TSI Best of Clever



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Fabia Combi 1.0 TSI Best of Clever	
Vehicle Identification number	TMBJP6NJ2MZ062876
Mileage (Read)	86,466 km
First registration	14 May 2021
Number of holders	1
Next periodical technical inspection	05/2028
(Report not on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	70 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Candy White (F9E)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	3,200 km
Last service on / at	11/2024 at 59,658 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC253482
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / ASS 00347		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,591 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/45 R16 86H	Summer tyres on Light alloy	Nexen	5mm / 5mm
2)	215/45 R16 86H	Summer tyres on Light alloy	Nexen	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R15 85H	Winter tyres on Steel	Hankook	6mm / 6mm
2)	195/55 R15 85H	Winter tyres on Steel	Hankook	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Umbrella storage compartment under the passenger seat
- Storage pockets on the backs of the front seats
- Airbag, driver and switchable passenger airbag
- Airbag, head airbags
- Airbag: Front side airbags
- Allergen filter
- Traction control (ASR)
- Ashtray and lighter at the front
- Exterior mirrors and door handles in body color
- On-board computer with 4.2" screen (black/white) for displaying (time, outside temperature, average and current fuel consumption, distance traveled, driving time, fuel range, average speed and maintenance intervals, speed warning system, door and trunk lid warning)
- Electronic transverse differential lock (XDS+)
- Suspension: Aerodynamic suspension (ground clearance reduced by approximately 15mm)
- Cruise control system (cruise control) including speed limiter
- Tinted windows
- Rear window wiper/washer system with intermittent function
- Air conditioning including odor and allergen filter
- Front and rear headrests are height-adjustable.
- LED license plate lights
- Steering wheel: height and reach adjustable
- Steering wheel: Multifunction leather steering wheel with chrome elements (piano black decor) (as well as gearshift and handbrake levers with leather elements)
- Multi-collision brake assistant (MKB)
- Upholstery: Cloth
- Radio: Skoda Surround Sound System (for digital audio sources)
- Radio preparation for Skoda original music systems
- Radio accessories: 6 speakers
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring
- Wheels: 15" steel rims with Costa wheel covers (6x15 with 185/60 R15 tires)
- Wheels: Tire mobility kit (tire repair spray incl. compressor)
- Gear shift indicator
- Seat belts Fabia (Two height-adjustable three-point seat belts in the front, with belt tensioners - Three three-point seat belts in the rear - Seat belt fastening indicator on the front and rear outer seats)
- SKODA Infotainment Online (Online map updates for navigation (only in conjunction with Amundsen infotainment system), display of weather data, news, headlines, petrol station and parking space search)
- Sun visors on driver and passenger side, with make-up mirrors (and ticket holder on the driver's side)
- Start/stop system including brake energy recuperation
- High-visibility vest compartment in the front doors
- Immobiliser
- Storage compartments (storage compartments in the front door panels with 1.5l bottle holders and storage space for warning vests - Closed storage compartment with lighting in the dashboard - Bottle holder in the center console - Bag hooks and storage compartments in the trunk)
- Anti-lock braking system (ABS)
- Dashboard and center console in black
- Electrically adjustable and heated exterior mirrors
- Outside temperature display in the instrument cluster
- Hydraulic brake assist (HBA)
- Glasses compartment in the headliner
- Tachometer
- Third brake light
- Electromechanical power steering
- Electronic Stability Control (ESC)
- Electric front windows
- Front radar assistant including city emergency braking function
- Transmission: 5-speed transmission
- Heated rear window
- ISOFIX preparation on the outer rear seats, including top tether
- The boot cover can be rolled up and removed.
- Paint finish: Solid
- LED daytime running lights integrated into the main headlights
- Reading lights front and rear
- Engine drag torque control (MSR)
- Multifunction display in the instrument cluster
- Otto particulate filter
- Radio: Swing infotainment system (FM, RDS FM playback function for MP3 or WMA music files, SD memory card slot, USB port, display of vehicle information on the 6.5" touchscreen display (ASR, TPM, parking sensor signal if available))
- Radio accessories: SmartLink+ (Apple CarPlay, Android Auto, MirrorLink & Smartgate UA: Efficiency App (efficiency data), Service App (vehicle status), G-Meter (acceleration values), MFA Pro (extended on-board computer), Performance Pal (performance data), Smartgate pairing via WLAN interface, Smartlink pairing via USB cable)
- Seats: Driver's seat height adjustable
- SKODA Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions relating to vehicle functions), Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Telephone: Bluetooth hands-free system (operation via the radio display possible)
- Central locking



Extra equipment

- Luggage net partition
- LED headlights with integrated cornering lights and LED taillights
- Radio accessories: Voice control for the Amundsen infotainment system
- Lane Change Assist (Blind Spot Detect)
- Paintwork: Special paintwork
- Fatigue detection
- Radio accessory: SKODA Media Command for Amundsen infotainment system
- Seats: Passenger seat height adjustable
- Variable loading floor in the trunk

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
3	Indicator - front	Mirror - left side - Leaking - Replace
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
5	Wheel / tyres	Tyre - front right side - Porous / cracked - Replace
6	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
7	Headlight	Headlight - right side - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 8 Nov 2025	2.942,67 €
2	Side - left, Provided by user / customer, from 12 Sept 2022	2.952,23 €
3	Roof, Front, Side - left, Provided by user / customer, from 19 Oct 2021	3.927,60 €



Repainting

No. Repainting

- 1 Mudguard - left side, Professionally carried out
- 2 Mudguard - right side, Professionally carried out
- 3 Bonnet, Professionally carried out
- 4 Door - rear left side, Professionally carried out
- 5 Door - front left side, Professionally carried out

Paint coat thickness measurement

Mudguard - left side	318 µm	Mudguard - right side	182 µm
Bonnet	254 µm	Door - rear left side	184 µm
Door - front left side	219 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 3: Indicator - front: Mirror - left side - Leaking - Replace



Damage 3: Indicator - front: Mirror - left side - Leaking - Replace



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 7: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 7: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 7: Headlight: Headlight - right side - Scratch(es) - Replace



Repainting 1: Mudguard - left side



Repainting 1: Mudguard - left side



Repainting 2: Mudguard - right side



Repainting 2: Mudguard - right side



Repainting 3: Bonnet



Repainting 3: Bonnet



Repainting 4: Door - rear left side



Repainting 4: Door - rear left side



Repainting 5: Door - front left side



Repainting 5: Door - front left side