



Expertise

Protocol number: 46542409
Order No. / Reference: 26674075
Inspection date: 15 Jul 2026

Manufacturer: Opel	Model: Grandland Plug-in-Hybrid 1.6 DI Automatik Business Edition
VIN: W0VZ4DGZ6N6816793	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Grandland Plug-in-Hybrid 1.6 DI Automatik Business Edition	
Vehicle Identification number	W0VZ4DGZ6N6816793
Mileage (Read)	68,699 km
First registration	28 Jun 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report on hand)	
Power / Engine displacement	133 kw / 1,598 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Rubin Rot Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	-200 km
Last service on / at	06/2025 at 52,764 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ674386
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALW 00027		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,310 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 99V	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/55 R17 99V	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	225/55 R18 102V	Summer tyres on Light alloy	Michelin	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 2 ignition keys, both foldable
- Storage compartments (storage compartment in the instrument panel, driver's side - storage compartment in the center console, front - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 1.0-liter beverage bottles - illuminated glove compartment with cooling and heating function - bag hooks, on the side in the luggage compartment - lashing eyes in the luggage compartment)
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag and seatbelt tensioner)
- On-board computer
- Decorative strips, Erino/Palladium Medium
- Tachometer
- Third brake light
- Electric parking brake
- Electric air conditioning compressor and heater (remote control of the air conditioning, heating or cooling of the interior during the charging process to relieve the battery at the start of the journey)
- Chassis: Driving modes (with 4 adjustable driving modes: Electric mode (standard mode), Sport mode, Hybrid mode and All-wheel drive mode (All-wheel drive mode not with front-wheel drive))
- Luggage compartment cover
- Transmission: 8-speed automatic
- Rear window wiper
- Interior lighting, front and rear (with reading lights front and rear - luggage compartment lighting)
- Interior rearview mirror, automatically dimming
- Child safety lock in the rear doors, manual
- Dual-zone automatic climate control (with separate temperature control for driver and front passenger - recirculation mode, manual - automatic air distribution - sun position sensor - particle and odor filter)
- Charging port (rear left with access to the power charging socket)
- Flat-bottomed leather steering wheel with steering wheel remote control and paddle shifters.
- Illuminated makeup mirror in sun visor, for driver and front passenger
- Mode 2 charging cable (Type 2, up to 1.8 kW), 6 m length, for household sockets)
- Fog light
- Onboard charger (vehicle-integrated charging unit, single-phase (max. 3.7 kW/16 A))
- Otto particulate filter
- Parkpilot, front and rear parking aid (with acoustic warning signal)
- 230V equipment (230V socket on the center console, rear - 12V socket in the luggage compartment)
- Driver and passenger side airbags
- Airbag: Front and side airbags
- Airbag: Head airbags, front and rear outer
- Active pedestrian warning tone (AVAS) (ambient noise up to a driving speed of 50 km/h)
- Ambient lighting, center console and in the front doors
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirrors, electrically adjustable and heated, electrically folding (exterior mirror housing in black)
- Hill Start Assist
- Roof design line in black
- Display: Fully digital 12" color driver information display (specific plug-in hybrid displays - charging time, driving mode information, range and overall charge status - energy consumption display and energy flow diagram - charging area and consumption statistics - battery charge level indicators - charging stations via navigation)
- Electronic brake force distribution (EBD)
- Electronic Stability Program Plus (ESP Plus), Traction Control
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Forward Collision Warning (monitors the distance (close, medium, far) to the vehicle ahead; if the vehicle approaches a vehicle ahead or a pedestrian too quickly, a warning tone sounds and a message appears in the driver information display. - with automatic emergency braking and pedestrian detection - Lane Keeping Assist: warns if the vehicle unintentionally leaves its lane - Traffic Sign Recognition - Driver Drowsiness Detection - Automatic Speed Assist with Stop Function - Automatic Headlights)
- Rear headrests (3), height adjustable
- Front headrests, height adjustable
- Paint finish: Metallic Ruby Red
- LED headlights (LED taillights - LED front turn signals - manual headlight range control - high beam assist)
- Steering wheel, height and reach adjustable
- Steering wheel: Heated, flat-bottomed leather steering wheel
- Center armrest, sliding, front, including storage compartment and cup holder
- My Opel App (with hybrid-specific functions: - Battery charge level indicator, charging time and range monitoring - Remote control of climate control and charging settings - E-Mobility Coaching)
- Park & Go (reversing camera - automatic parking assistant (recognition of parallel and perpendicular parking spaces at speeds below 20 km/h, exiting parallel parking spaces, automatic steering of the vehicle), including parking pilot, front and rear parking aid with audiovisual warning - electrically folding exterior mirrors - blind spot warning in both exterior mirrors (active between 12 km/h and 140 km/h))



- Radio: Multimedia Navi Pro (with 10" color touchscreen display - Navigation: with integrated memory, European road map, 3D map display, dynamic route guidance via map and/or arrow display, display of points of interest, trip planning, GPS module, map display of TMC messages - OpelConnect with telematics services and LIVE navigation service: map updates, emergency call, breakdown call, route and driving information - Voice control for audio, telephone, navigation - Radio, Bluetooth, 2 USB ports, hands-free system - Apple CarPlay, Android Auto)
- Tire pressure warning
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Speed-sensitive power steering
- Seats: FlexFold rear seat backrest split 40:60 and foldable (rear center armrest with pass-through from the luggage compartment)
- Seats: Comfort seats, front (Berson Black fabric - driver's seat manually adjustable in length, height and backrest angle, and passenger seat manually adjustable in length and backrest angle)
- 12-volt power outlet (in the center console, front)
- Pre-wiring for ISOFIX child seat mounting system, including top tether attachment points, rear outer (and for ISOFIX child seat mounting system on the front passenger seat)

- Radio accessories: Digital radio reception DAB+ (Offers a wider selection of radio programs. Digitally broadcast radio stations and traffic information can be received.)
- Regenerative braking system
- Rain sensor
- Wheels: Light alloy 7.5 J x 18 with 5 spokes (with tires 225/55 R18)
- Keyless Start system
- Seat belts (three-point seat belts in all seats - height-adjustable seat belts, front - belt force limiters, front and rear outer seats - double belt tensioners, front - belt tensioners, rear outer seats - warning tone and light for unfastened seat belts, front and rear)
- Specific electric shift lever
- Start/Stop System (Reinforced starter motor - High-performance battery - Switch to deactivate the start/stop function)
- Immobiliser
- Tinted heat-insulating glazing
- Central locking with remote control and interior switches

Extra equipment

- Park & Go Premium (360-degree camera - Automatic parking assistant, including front and rear parking pilot with audiovisual warning - Electrically folding exterior mirrors - Blind spot warning in both exterior mirrors (active between 12 km/h and 140 km/h))
- Winter equipment (heated seats, multi-stage, driver and front passenger - partially heated windshield in the wiper area - FlexFold rear seat backrest split and foldable in a 40:60 ratio and rear center armrest with pass-through from the luggage compartment)
- Detachable trailer hitch (trailer stability program)
- Onboard charger (vehicle-integrated charging unit, single-phase (max. 7.4 kW/32 A))
- Universal charger (1.8-22 kW, 3-phase) with 3 adapters included: - Type EF plug for household socket - Type 2 plug for public charging - CEE-16 plug (3-phase) for industrial socket (three-phase current) - incl. storage bag)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Body	Body (Sämtliche Zierleisten / ausgebleichen) - No deduction
2	Trim / covers	Door trim - rear left side - Scratch(es) - Loss in value
3	Tail light	Tail lamp - left side - Scratch(es) - Loss in value
4	Trim / covers	Boot lid - interior trim - Scratch(es) - Loss in value
5	Instrument panel	Indicator light (Reifendruckkontrollsystem) - on - Perform diagnosis
6	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
7	Front bumper	Front bumper - Scratch(es) - Loss in value
8	Steering system	Steering wheel - Abrasion - Loss in value
9	Door - front right side	Door edge - Scratch(es) - Smart repair
10	Side panel - rear right side	Sill - Scratch(es) - Smart repair
11	Roof	Roof rail - right side - dent(s) - Smart repair
12	Roof	Roof rail - left side - dent(s) - Smart repair
13	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
14	Interior	Rear shelf (Halter gerissen) - Damaged - Replace
15	2nd wheel set	2 tyres - Damaged - Replace
16	Side panel - rear right side	Wheel arch (+ Zierleiste Tür) - Scratched - Replace
17	Misc.	Inspection / maintenance (Kein Nachweis) - Due - Perform
18	2nd wheel set	3 alloy rims - Scratch(es) - Loss in value
19	Roof	Roof (Mit Dellen) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Body	Underbody - Corrosion - No deduction
5	Body	Body - Scratch(es) - No deduction
6	Rear bumper	Rear bumper (Ladekante) - Scratch(es) - No deduction
7	Trim / covers	Floor mats - Holes - Replace

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Das Fahrzeug weist der Laufzeit entsprechende Gebrauchsspuren auf.

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.





Figure 33: Misc.



Damage 2: Trim / covers: Door trim - rear left side - Scratch(es) - Loss in value



Damage 2: Trim / covers: Door trim - rear left side - Scratch(es) - Loss in value



Damage 2: Trim / covers: Door trim - rear left side - Scratch(es) - Loss in value




Damage 3: Tail light: Tail lamp - left side - Scratch(es) - Loss in value



Damage 3: Tail light: Tail lamp - left side - Scratch(es) - Loss in value



Damage 4: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 4: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 4: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 4: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 5: Instrument panel: Indicator light (Reifendruckkontrollsystem) - on - Perform diagnosis



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 7: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper - Scratch(es) - Loss in value




Damage 8: Steering system: Steering wheel - Abrasion - Loss in value



Damage 8: Steering system: Steering wheel - Abrasion - Loss in value



Damage 8: Steering system: Steering wheel - Abrasion - Loss in value




Damage 9: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 9: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 10: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 10: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 10: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 10: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 11: Roof: Roof rail - right side - dent(s) - Smart repair



Damage 11: Roof: Roof rail - right side - dent(s) - Smart repair



Damage 12: Roof: Roof rail - left side - dent(s) - Smart repair



Damage 12: Roof: Roof rail - left side - dent(s) - Smart repair



Damage 13: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 13: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 14: Interior: Rear shelf (Halter gerissen) - Damaged - Replace



Damage 14: Interior: Rear shelf (Halter gerissen) - Damaged - Replace



Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace



Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace



Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace



Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace



Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace




Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace



Damage 15: 2nd wheel set: 2 tyres - Damaged - Replace



Damage 16: Side panel - rear right side: Wheel arch (+ Zierleiste Tür) - Scratched - Replace



Damage 17: Misc.: Inspection / maintenance (Kein Nachweis) - Due - Perform



Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value




Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value



Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value



Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value




Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value




Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value



Damage 18: 2nd wheel set: 3 alloy rims - Scratch(es) - Loss in value




Damage 19: Roof: Roof (Mit Dellen) - Scratch(es) - Paint



Damage 19: Roof: Roof (Mit Dellen) - Scratch(es) - Paint



Damage 19: Roof: Roof (Mit Dellen) - Scratch(es) - Paint



Damage 19: Roof: Roof (Mit Dellen) - Scratch(es) - Paint



Damage 19: Roof: Roof (Mit Dellen) - Scratch(es) - Paint



Wear and tear 7: Trim / covers: Floor mats - Holes - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZ4DGZ6N6816793

Hersteller / Modell: OPEL OPEL Grandland Plug-in-Hybrid 1.6 DI Automatik Business Edition

Datum	KM-Stand	Beschreibung
06.06.2025	52.764	HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges