

Condition Report

DEKRA/ /20260322

Ordered By

Ordered By

Vehicle

License Plate		Contract Number		Bodywork Type	SUV	Transmission	Automatic
Brand	BMW	VIN	WBA35BG050N072649	Drive Wheel	Four-wheel-drive	First Registration	2021.02.10
Model	X3	Year Built	2020	Color	Black	Fuel Type	Hybrid
Label	-	Capacity	1.995 cm3	Power	140 kW	Mileage	139.506 km
MOT	2027.02.05						

Equipment

- Automatic air conditioning / digital
- Electrically adjustable front and rear windows
- Multifunction steering wheel
- ESP / DSC
- ASD / EDS / ASR
- Navigation

Documents

- Original Key
- Registration Book
- Tyre Repair Kit

Wheels

Position	Rim Type	Dimensions	Thread Depth
FL	Könnyűfém	245/50R19	4.00
FR	Könnyűfém	245/50R19	4.00
RL	Könnyűfém	245/50R19	4.00
RR	Könnyűfém	245/50R19	4.00


Paint Thickness [µm]

Part	Left Value	Right Value
Front mudguard	104	112
Engine cover	108	0
Front door	118	116
Rear door	143	115
Roof	128	0
Rear mudguard	119	130
Luggage compartment lid / Rear door	132	0

Last Service

Type	Date	KM
------	------	----

Standard Images





Unacceptable Damage

Jobb első ajtó

Part	Jobb első ajtó	Damage	Scratched	Repair Method	Painting

Jobb hátsó ajtó

Part	Jobb hátsó ajtó	Damage	Scratched	Repair Method	Painting

Utastér

Part	Utastér	Damage	Stained/dirty	Repair Method	Cleaning

Fényezett elemek

No images or videos available.

Part	Fényezett elemek	Damage	Repair Method	Preparation and painting
------	------------------	--------	---------------	--------------------------

Acceptable Damage

Jobb első sárvédő



Part	Jobb első sárvédő	Damage	Stained/dirty	Repair Method	Unnecessary
------	-------------------	--------	---------------	---------------	-------------

Special Notes

A gépjármű a szemle időpontjában szennyezett volt. A hibák ill. az esetleges jégkár csak korlátozottan észlelhetők.

Inspection Details

Inspection Place		Inspection Person	Szloboda István	Inspection Date	2026.03.18
------------------	--	-------------------	-----------------	-----------------	------------

This condition report was prepared by an expert of DEKRA-Expert Kft.
The vehicle inspection was carried out by external visual examination. No test drive was performed and no parts were disassembled during the inspection.
The calculation of unacceptable defects and deficiencies was prepared using data from the Audatex and Eurotax calculation programs.
The expert inspection was carried out in accordance with DEKRA regulations, applying the client's guidelines regarding acceptable and unacceptable defects and deficiencies for returned vehicles.