



BMW 1 Reeks (UKL): 2AKC530

Vinnumber:	WBA7K310005T65139	Versionname:	118i (F40) 1.5i 136pk/cv 5p
First Registrationdate:	22/04/2021	Fiscalpower:	
Expertise Mileage:	146987	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 8000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/40/18/92 V				
Winter tyres:	Fr.L.	Goodyear: 1 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				1.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/40 R 18 92 V
Tyre size FR				225/40 R 18 92 V
Tyre size RL				225/40 R 18 92 V
Tyre size RR				225/40 R 18 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Bumper F, Scratch(es), Repair and paint (complete)





Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Tyre FL, Worn, Check



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Boot carpet, Dirty, Cleaning




Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Mirror side repeater R, Broken, Replace



Bodywork, Paint measurement, Acceptable



Tyres, Out of tolerance, Check



Kenteken	2AKC530
Merk Model	BMW 118i (F40) 1.5i 136pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	4/22/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/23/26	143,757	BMW/MINI service standaard omvang	Uitvoeren
6/23/26	143,757	controle niveaus	Uitvoeren
6/23/26	143,757	remvloeistof	Vervangen
1/9/26	134,235	BMW/MINI service standaard omvang	Uitvoeren
1/9/26	134,235	klein materiaal	N.v.t.
1/9/26	134,235	klein materiaal	
1/9/26	134,235	koelwatervloeistof	Bijvullen/-laden
1/9/26	134,235	remblokken achter	Vervangen
9/5/25	123,628	accu	Bijvullen/-laden
9/5/25	123,628	accu	Vervangen
9/5/25	123,628	klein materiaal	
8/29/25	123,628	batterij	Vervangen
8/29/25	123,628	BMW/MINI service standaard omvang	Uitvoeren
8/29/25	123,628	BMW/MINI service voertuig-check	Uitvoeren
8/29/25	123,628	bougie	Vervangen
8/29/25	123,628	controle niveaus	Uitvoeren
8/29/25	123,628	klein materiaal	
8/29/25	123,628	service luchtfilter	Uitvoeren
8/29/25	123,628	service microfilter	Uitvoeren
8/29/25	123,628	service motorolie	Uitvoeren
10/25/24	93,032	batterij	Vervangen
10/25/24	93,032	BMW/MINI service standaard omvang	Uitvoeren
10/25/24	93,032	BMW/MINI voertuigcontrole	Uitvoeren
10/25/24	93,032	controle niveaus	Uitvoeren
10/25/24	93,032	klein materiaal	Uitvoeren
10/25/24	93,032	ruitenswisserrubber achter	Vervangen
10/25/24	93,032	ruitenswisserrubber vooraan	Vervangen
10/25/24	93,032	service microfilter	Uitvoeren
10/25/24	93,032	service motorolie	Uitvoeren
5/31/24	82,501	BMW/MINI service standaard omvang	Uitvoeren
5/31/24	82,501	controle niveaus	Uitvoeren
5/31/24	82,501	klein materiaal	
5/31/24	82,501	remblokken vooraan	Vervangen
5/31/24	82,501	remvloeistof	Vervangen
8/25/23	64,705	batterij	Vervangen
8/25/23	64,705	BMW/MINI service standaard omvang	Uitvoeren
8/25/23	64,705	BMW/MINI voertuigcontrole	Uitvoeren
8/25/23	64,705	bougie	Vervangen
8/25/23	64,705	klein materiaal	Uitvoeren
8/25/23	64,705	remblokken achter	Vervangen

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/25/23	64,705	ruitwisserrubber achter	Vervangen
8/25/23	64,705	ruitwisserrubber vooraan	Vervangen
8/25/23	64,705	service luchtfilter	Uitvoeren
8/25/23	64,705	service microfilter	Uitvoeren
8/25/23	64,705	service motorolie	Uitvoeren
5/9/22	33,964	batterij	Vervangen
5/9/22	33,964	service microfilter	Uitvoeren
5/9/22	33,964	service motorolie	Uitvoeren