



Expertise

Protocol number: 46839071
Order No. / Reference: 26578038
Inspection date: 31 Jul 2026

Manufacturer: Volkswagen

Model: Touran 2.0 TDI SCR DSG Comfortline

VIN: WVGZZZ1TZNW006277



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Touran 2.0 TDI SCR DSG Comfortline	
Vehicle Identification number	WVGZZZ1TZNW006277
Mileage (Read)	242,930 km
First registration	7 Feb 2022
Number of holders	1
Next periodical technical inspection	02/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Dolphin grey metallic (C7Q)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	26,700 km
Last service on / at	06/2026 at 239,594 km		
Key is / should be	2 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	GF453679
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / BWR 00322		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,230 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	205/60 R16 96V	Summer tyres on Light alloy	Continental	6mm / 6mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Dunlop	3mm / 3mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Dunlop	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • 2 USB-C ports on the front • Storage compartments in the overhead console • Airbag, head airbag system for front and rear passengers • Exterior mirror housings and door handles in body color • Headliner in Storm Grey • Decorative inlays "New Brushed Design" • Diesel particulate filter • Parking assistance • Electronic Stability Program (ESP) with counter-steering support • Luggage compartment cover • Height-adjustable luggage compartment floor • Transmission: 7-speed DSG • Rear window heated • Interior lights with delayed shut-off and dimming function, 2 reading lights front and rear • Headrests (3) in the 2nd row of seats • Black radiator grille with chrome strips on the slats • Steering wheel: Leather • Illuminated makeup mirrors in the sun visors • Multifunction display "Plus" • Non-smoking version • Emergency call service • Proactive occupant protection system in conjunction with "Front Assist" • Tire pressure monitoring system (passive) • Wheels: Tire Mobility Set • Drawers under the front seats • Seat belts: 3 three-point automatic seat belts in the rear • Seats: Front passenger seat backrest folds down completely • Seats: Lumbar support in the front • Start-stop system • Bumpers in body color • Textile floor mats • Prepared for "We Connect" and "We Connect Plus" • Electronic immobilizer • Green thermal insulation glazing • Black trim strips on the side windows | <ul style="list-style-type: none"> • Storage compartment with lid on the instrument panel • Airbag for driver and front passenger • Electrically adjustable and heated exterior mirrors • Third brake light • Black roof rails • Decorative inlays "Piano Black" • Tachometer • Electronic parking brake including auto-hold function • Windscreen in heat-insulating glass • Baggage management package • Additional luggage compartment lighting • Speed limiter • Glove compartment with cooling option • Rear window wiper with intermittent function • ISOFIX mounting points on rear seats • Air conditioning • Front headrests • Paint finish: Solid • Headlight range control • Front center armrest • Fatigue detection • Emergency braking assistant "Front Assist" • Upholstery: Cloth • Radio "Composition" • Radio accessories: 8 speakers • Wheels: Light alloy (4) "Karlstad" 6.5 J x 16 • Gearshift knob in leather • Electromechanical power steering • Seats: 3 individual seats in the 2nd row • Seats: Folding tables on the backs of the front seats • Seats: Comfort seats in the front • Seats: Front seats are height-adjustable • 12V power outlet on the rear of the center console • Daytime running light • First aid kit, warning triangle and high-visibility vest • Warning tone and light for unfastened seat belts front and rear • Central locking without safe locking, with remote control and 2 remote folding keys |
|---|---|



Extra equipment

- Towbar, foldable with electric release
- Heated windshield (laminated safety glass windshield, noise-reducing and heated)
- Paint finish: Metallic
- LED headlights (LED headlights with daytime running lights - dynamic headlight range control)
- Fog lights and cornering lights
- Package: Business (Air Care Climatronic air conditioning with active combination filter, rear controls and 3-zone temperature control - cargo net partition - automatically heated front windshield washer nozzles - headlight cleaning system - heated front seats - washer fluid level warning light)
- High beam control "Light Assist" (automatic headlight control with daytime running lights, "Leaving home" function and manual "Coming home" function - High beam control "Light Assist" - Interior mirror automatically dimming - Multifunction camera - Rain sensor)
- Navigation system "Discover Media" incl. "Streaming & Internet" (screen diagonal 20.3 cm - touchscreen - FM radio reception - dual tuner with phase diversity - MP3 playback - SD card slot - USB-C with Apple compatibility - output power 4x20 watts - map with 2D display - traffic sign display - telephone interface - 3-way sound control - DAB+ digital radio reception)
- "Comfort" telephone interface with inductive charging function

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	2nd wheel set	2 tyres (<4mm, gehören nicht zur Ausstattung) - does not meet manufacturer specifications - No deduction
2	Equipment	Tirefit filler - Expired - Replace
3	Body	Firewall trim (Dämpfung außen) - Damage caused by marten / rodent - Replace
4	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
5	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Door - front left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Interior - Cigarette lighter



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Provided by user / customer, from 3 Dec 2024	4.015,45 €
2	Front, Provided by user / customer, from 2 Feb 2026	5.369,69 €
3	Front, Provided by user / customer, from 9 Jun 2024	10.307,16 €

Repainting

No. Repainting

- 1 Mudguard - left side, Mudguard - right side, Bonnet

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres




Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Damage 1: 2nd wheel set: 2 tyres (<4mm, gehören nicht zur Ausstattung)
- does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres (<4mm, gehören nicht zur Ausstattung)
- does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres (<4mm, gehören nicht zur Ausstattung)
- does not meet manufacturer specifications - No deduction




Damage 1: 2nd wheel set: 2 tyres (<4mm, gehören nicht zur Ausstattung)
- does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres (<4mm, gehören nicht zur Ausstattung)
- does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres (<4mm, gehören nicht zur Ausstattung)
- does not meet manufacturer specifications - No deduction



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Body: Firewall trim (Dämpfung außen) - Damage caused by marten / rodent - Replace



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 5: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Missing part 1: Interior: Cigarette lighter - Missing - Replace



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZ1TZNW006277
Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Touran 2.0 TDI SCR DSG
Comfortline

Datum	KM-Stand	Beschreibung
08.06.2026	239.594	Batterie ern; Bremsflüssigkeit; Bremsflüssigkeit ern; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
28.01.2026	227.195	Systemtest/Eigendiagnose
02.01.2026	224.515	Systemtest/Eigendiagnose
26.11.2025	219.817	Systemtest/Eigendiagnose
11.10.2025	211.845	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Spannrolle ern; Systemtest/Eigendiagnose; Wartung Sonstiges; Zahnriemen/Steuerkett ern
11.07.2025	195.445	Systemtest/Eigendiagnose
11.04.2025	181.213	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
25.02.2025	173.028	AU; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne
29.08.2024	147.130	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.01.2024	115.872	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.08.2023	85.015	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
27.02.2023	55.021	Motoröl b. Wartung; Regelwartungsdienst
29.08.2022	27.294	Motoröl b. Wartung; Regelwartungsdienst