MACADAM








BMW 3 Reeks (KKL): 2CSC015

Vinnumber:	**WBA41FY010FN86966**	Versionname:	**320e Touring (G21) 2.0i 204pk/cv 5p Aut.**
First Registrationdate:	**7/11/2022**	Fiscalpower:	
Expertise Mileage:	**171278**	Power Kw:	**120**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**+ 43000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/50/17/98 Y**			
	Fr.L.	**Firestone: 4 mm**	Fr.R.	**Firestone: 4 mm**
	Re.L.	**Firestone: 6 mm**	Re.R.	**Firestone: 6 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**225/50 R 17 98 Y**
Tyre size FR	**225/50 R 17 98 Y**
Tyre size RL	**225/50 R 17 98 Y**
Tyre size RR	**225/50 R 17 98 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**258**
Tyre make FR	**258**
Tyre make RL	**258**
Tyre make RR	**258**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**

Steering wheel, Worn, Acceptable





Seat cover R, Stain, Cleaning





Backrest cover FR, Scratch(es), Acceptable




Windscreen, Stone chip(s), Windscreen repair




Bumper F, Hole, Replace and paint








Wing RL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable





Alloy rim RL, Scratch(es), Acceptable




Charging cable (normal), Missing, Check



Boot lid covering R, Scratch(es), Acceptable






Tailgate / Boot, Scratch(es), Acceptable




Bumper R, Scratch(es), Repair and paint (complete)








Alloy rim FR, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA41FY010FN86966

ALPHABET

Kenteken	2CSC015
Merk Model	BMW 320e Touring (G21) 2.0i 204pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	11/7/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/27/26	148,209	batterij	Vervangen
3/27/26	148,209	BMW/MINI service standaard omvang	Uitvoeren
3/27/26	148,209	BMW/MINI service voertuig-check	Uitvoeren
3/27/26	148,209	bougie	Vervangen
3/27/26	148,209	klein materiaal	
3/27/26	148,209	koelwatervloeistof	Bijvullen/-laden
3/27/26	148,209	ruitenwisservloeistof	Bijvullen/-laden
3/27/26	148,209	service luchtfilter	Uitvoeren
3/27/26	148,209	service microfilter	Uitvoeren
3/27/26	148,209	service motorolie	Uitvoeren
7/4/25	112,066	BMW/MINI service standaard omvang	Uitvoeren
7/4/25	112,066	klein materiaal	
7/4/25	112,066	remvloeistof	Vervangen
7/4/25	112,066	ruitenwisserrubber achter	Vervangen
7/4/25	112,066	ruitenwisserrubber vooraan	Vervangen
7/4/25	112,066	service microfilter	Uitvoeren
7/4/25	112,066	service motorolie	Uitvoeren
9/2/24	73,272	BMW/MINI service standaard omvang	Uitvoeren
9/2/24	73,272	BMW/MINI service voertuig-check	Uitvoeren
9/2/24	73,272	bougie	Vervangen
9/2/24	73,272	klein materiaal	
9/2/24	73,272	service luchtfilter	Uitvoeren
9/2/24	73,272	service microfilter	Uitvoeren
9/2/24	73,272	service motorolie	Uitvoeren
10/3/23	35,395	batterij	Vervangen
10/3/23	35,395	BMW/MINI service standaard omvang	Uitvoeren
10/3/23	35,395	BMW/MINI voertuigcontrole	Uitvoeren
10/3/23	35,395	klein materiaal	
10/3/23	35,395	ruitenwisservloeistof	Bijvullen/-laden
10/3/23	35,395	service microfilter	Uitvoeren
10/3/23	35,395	service motorolie	Uitvoeren
11/22/22	31	bus olie 1 liter	Uitvoeren