BMW 4 SERIES GRAN COUPÉ

Vehicle information

Make:	**BMW**	License:	**2BGJ758**
Gearbox:		Body color:	
Model:	**4 SERIES GRAN COUPÉ**	VIN:	**WBA21AX090FM10663**
Fuel type:		Power:	**120 kW**
Version:	**MHEV 2.0 420D (120KW) GRAN COUPE AUTO**	First registration	**16/11/2021**
Mileage:	**115229 km**	N° of doors:	

Damage summary

Front	3
Interior	1
Roof & others	1

Commercial pictures


































Options according to the inspector

GPS	**Yes**


Damages

Bodywork
Damaged
Acceptable
Roof & others







Bumper F
Repaired
Acceptable
Front




Bumper F
Bad repair
Paint
Front







Grille
Crack
Replace
Front




Interior
Damaged
Acceptable
Interior



Tyres

Front Left
Summer
Aluminium
225/55/17/101/Y
Michelin
6.0 mm

Front Right
Summer
Aluminium
225/55/17/101/Y
Michelin
6.0 mm

Rear Left
Summer
Aluminium
225/55/17/101/Y
Michelin
6.0 mm

Rear Right
Summer
Aluminium
225/55/17/101/Y
Michelin
6.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**N/A**	Maintenance	**OK**
Maintenance	**17000.0**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**No**
Repair kit	**N/A**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Statutory inspection	**OK**	Statutory inspection	**16/11/2027**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.