DEKRA

DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	VSSZZZKL6 RR097673	Mileage	59 131 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2FKD174	Registration date	29/05/2024	Engine size	1498
Brand	CUPRA	Fuel level	-	Transmission	Automatic
Model	LeonST-2013	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Compliant
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	06/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Emergency compressor kit	✔
Refill emergency kit	✔

Tyres

Michelin 225/40/18 Y Summer 3.0 mm

Bridgestone 225/40/18 Y Summer 3.0 mm






Bridgestone 225/40/18 Y Summer 5.0 mm

Bridgestone 225/40/18 Y Summer 5.0 mm

Damages

1



Part	Special rim 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	225.00€

2



Part	Carpet
Position	Front
Damages	Perforated
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	350.93€

3



Part	Wing
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

4



Part	Special rim 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	225.00€

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	90.00€

6



Part	Special rim 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	225.00€

7



Part	Fabric seat
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	29.62€

8



Part	Special rim 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	225.00€

9



Part	Tyre
Position	Back right
Damages	Cut
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	183.12€

10



Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

11



Part	Bumper
Position	Back
Damages	Dented
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	368.88€

12



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	339.25€

13



Part	Tailgate / Boot door badge
Position	Back
Damages	Not conform
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	34.02€

Summary Inspection

Net Price (Exclusing VAT)	2,344.82€