TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48491867
Order No. / Reference: 27168426
Inspection date: 4 Nov 2026

Manufacturer: Porsche	Model: Panamera 4 E-Hybrid Sport Turismo
VIN: WP0ZZZ97ZML184386	





Vehicle details

Manufacturer / Type / Model / Equipment	
Porsche Panamera 4 E-Hybrid Sport Turismo	
Vehicle Identification number	WP0ZZZ97ZML184386
Mileage (Read)	91,045 km
First registration	23 Sept 2021
Number of holders	1
Next periodical technical inspection (Report on hand)	07/2028
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,894 ccm / 6
Power	243 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Tiefschwarz (C9X)
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	
Last service on / at	07/2026 at 86,604 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GB194028
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0583 / AKG 00026		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,735 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	275/35 R21 103Y	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	315/30 R21 105Y	Summer tyres on Light alloy	Continental	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	275/40 R20 106V	Winter tyres on Light alloy	Michelin	6mm / 6mm
2)	315/35 R20 110V	Winter tyres on Light alloy	Michelin	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Extra equipment

- 21-inch Panamera SportDesign wheels painted in Pla
- Automatically dimming exterior mirrors (in conjunction with
- ISOFIX attachment for child seat on front passenger seat
- Paint finish: deep black metallic
- On-board AC charger with 7.2 kW
- Parking assistant including reversing camera
- Privacy glazing
- USB port on the back
- Ambient lighting
- GT sports steering wheel including steering wheel heating
- Comfort front seats (14-way, electric) with memory function
- LED headlights including Porsche Dynamic Light S
- Panoramic roof system
- Upholstery: Leather interior in black, smooth leather
- Power Steering Plus

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Indicator light (Reifendruck) - on - Perform diagnosis
2	Sill - left side	Sill - dent(s) - Smooth repair work
3	Front bumper	Spoiler - Scratch(es) - Loss in value
4	Trim / covers	Door trim - rear right side (Eingedrückt) - Deformed - Loss in value
5	Trim / covers	Door trim - rear left side (Eingedrückt) - Deformed - Loss in value
6	Seat - rear	Seat upholstery - 2 seater bench - Deformed - Loss in value
7	Bonnet	Bonnet - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Boot lid / rear door, Mudguard - right side, Side panel - rear right side, Professionally carried out

Paint coat thickness measurement

Boot lid / rear door	286 µm	Mudguard - right side	313 µm
Side panel - rear right side	153 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis



Damage 2: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 2: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 2: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 3: Front bumper: Spoiler - Scratch(es) - Loss in value



Damage 3: Front bumper: Spoiler - Scratch(es) - Loss in value



Damage 4: Trim / covers: Door trim - rear right side (Eingedrückt) - Deformed - Loss in value



Damage 4: Trim / covers: Door trim - rear right side (Eingedrückt) - Deformed - Loss in value



Damage 5: Trim / covers: Door trim - rear left side (Eingedrückt) - Deformed - Loss in value



Damage 5: Trim / covers: Door trim - rear left side (Eingedrückt) - Deformed - Loss in value




Damage 5: Trim / covers: Door trim - rear left side (Eingedrückt) - Deformed - Loss in value



Damage 6: Seat - rear: Seat upholstery - 2 seater bench - Deformed - Loss in value



Damage 6: Seat - rear: Seat upholstery - 2 seater bench - Deformed - Loss in value



Damage 6: Seat - rear: Seat upholstery - 2 seater bench - Deformed - Loss in value




Damage 6: Seat - rear: Seat upholstery - 2 seater bench - Deformed - Loss in value



Damage 6: Seat - rear: Seat upholstery - 2 seater bench - Deformed - Loss in value



Damage 6: Seat - rear: Seat upholstery - 2 seater bench - Deformed - Loss in value



Damage 7: Bonnet: Bonnet - Stone chips - Paint



Damage 7: Bonnet: Bonnet - Stone chips - Paint



Damage 7: Bonnet: Bonnet - Stone chips - Paint




Damage 7: Bonnet: Bonnet - Stone chips - Paint



Damage 7: Bonnet: Bonnet - Stone chips - Paint




Damage 7: Bonnet: Bonnet - Stone chips - Paint



Damage 7: Bonnet: Bonnet - Stone chips - Paint




Damage 7: Bonnet: Bonnet - Stone chips - Paint



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear right side




Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear right side