TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48586188
Order No. / Reference: 27211701
Inspection date: 9 Nov 2026

Manufacturer: Ford	Model: Puma 1.0 EcoBoost Hybrid Aut. TITANIUM
VIN: WF02XXERK2PL28631	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Puma 1.0 EcoBoost Hybrid Aut. TITANIUM	
Vehicle Identification number	WF02XXERK2PL28631
Mileage (Read)	86,875 km
First registration	10 Oct 2023
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	999 ccm / 3
Power	92 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	12 %
Last service on / at	03/2026 at 59,984 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT916962
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BSO 00103		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,830 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98W	Summer tyres on Steel rim with wheel cover	Goodyear	4mm / 4mm
2)	215/55 R17 98W	Summer tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98H	Winter tyres on Light alloy	Continental	3mm / 3mm
2)	215/55 R17 98H	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Ambient lighting (front including front door storage, footwell and cup holder lighting with LED technology)
- Electrically adjustable, heated and folding exterior mirrors (painted in body color - with integrated turn signals and ambient lighting)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Brake Assist (EBA)
- Fabric headliner
- Electronic Stability Program (ESP) (with Traction Control System (TCS))
- Wrong-way driver warning function (traffic signs, e.g. no-overtaking zones or speed limits, are detected via the front camera and displayed on the on-board computer.)
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Luggage compartment lighting
- Transmission: 7-speed automatic dual-clutch transmission
- Rear window wiper/washer system
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters for front and outer rear seats - seat belt warning system for front and second-row seats)
- LED fog lights (including static cornering lights)
- Steering column, adjustable in height and reach
- Front center console with integrated armrest (2 cup holders - 12-volt socket)
- Ford navigation system including Ford SYNC 3 with AppLink and 8" touchscreen (Digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - 6 speakers - Android Auto and Apple CarPlay - Bluetooth hands-free system and audio streaming - Steering wheel controls - Radio player - USB port - Voice control for audio and telephone - Road map for Europe - Ford navigation system includes advanced voice control and voice output, detailed visualization (3D display), One Box Search)
- Headlights with LED daytime running lights and LED low beam headlights
- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Driver's seat height adjustable (with lumbar support)
- Seats: Rear seat backrest, foldable, 60:40 split
- Start-stop system
- Variable radiator air intake
- Lashing eyes in the luggage compartment
- Central locking with remote control
- Anti-lock braking system (ABS) (with electronic brake force distribution (EBD))
- Passenger airbag deactivation
- Tires: 7 J x 17 design wheels (4) in 5x2-spoke design, black-silver (with 215/55 R 17 tires)
- Hill start assist
- third brake light
- Tachometer
- Driver information system with on-board computer
- Lane keeping assist including lane keeping assist
- Electric front and rear windows (with quick-down function including all-around closing function)
- High Beam Assist
- Ford EcoCoach (shows the efficiency of current driving behavior)
- Ford MegaBox
- FordPass Connect (including eCall, Live Traffic information)
- Cruise control
- Grab handles for driver and passenger side
- Heated rear window
- Intelligent speed limiter with speed limit display
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- air conditioning, manual
- Rear headrests (3) height adjustable
- Front headrests are height-adjustable
- LED taillights
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system (individually programmable second key)
- Fatigue warning
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Otto particulate filter
- Rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist (including Forward Alert system with pedestrian and bicycle detection)
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Selective driving mode switch (settings "Normal", "Eco", "Sport", "Slippery" and "Unpaved Roads" - Depending on the selected mode, various factors such as the steering, the resistance of the accelerator pedal and the iACC basic settings are affected.)
- Seats: Front sports seats with integrated headrests
- Carpet floor mats, front, velour
- Traffic sign recognition system
- Immobiliser

Extra equipment

- Paint finish: Agate Black Metallic
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Package: Driver Assistance Package II (Automatic) (Active Parking Assist with parallel and perpendicular parking function - Evasive Steering Assist - Distance display and warning - Intelligent adaptive cruise control with traffic sign recognition - Traffic Jam Assist with Stop&Go function - Front parking pilot system - Pre-Collision Assist including collision warning system with pedestrian and cyclist detection - Rear-view camera with "Split View" technology - Blind Spot Assist including Cross Traffic Alert with emergency braking function when reversing out of parking spaces & trailer detection.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Roof	Stub aerial - Damage caused by marten / rodent - Replace
2	Roof	Roof rail - left side - dent(s) - Smooth repair work
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Side panel - rear right side	Sill - Scratch(es) - Smart repair
5	Interior	Interior (Rauch) - Odour - Ozone treatment
6	Door - rear left side	Door - Scratch(es) - Paint
7	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Body	Body - Scratch(es) - No deduction
4	Door - front left side	Door edge - Scratch(es) - No deduction
5	2nd wheel set	2 tyres - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key with remote control

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Das Fahrzeug weist der Laufzeit entsprechende Gebrauchsspuren auf.

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Roof: Stub aerial - Damage caused by marten / rodent - Replace



Damage 1: Roof: Stub aerial - Damage caused by marten / rodent - Replace



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 6: Door - rear left side: Door - Scratch(es) - Paint



Damage 6: Door - rear left side: Door - Scratch(es) - Paint



Damage 7: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 7: Vehicle glazing: Windscreen - Stone chips - Replace