TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48547527
Order No. / Reference: 27175030
Inspection date: 4 Nov 2026

Manufacturer: Mercedes-Benz	Model: Vito 116 CDI Extralang HA BASE
VIN: W1V44760514134612	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 116 CDI Extralang HA BASE	
Vehicle Identification number	W1V44760514134612
Mileage (Read)	132,927 km
First registration	18 Aug 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	120 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Navyblau MB 5610
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	17,200 km
Key is / should be	1 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM189772
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BBJ 05308		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109T	All-season tyres on Steel rim with wheel cover	Semperit	5mm / 5mm
2)	225/55 R17 109T	All-season tyres on Steel rim with wheel cover	Semperit	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109H	Summer tyres on Steel	Dunlop	2mm / 2mm
2)	225/55 R17 109H	Summer tyres on Steel	Dunlop	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/55 R17 109H	Summer tyres on Steel	Dunlop	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Screw-in towing eye front/rear
- Passenger side airbag
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Fixing points in the roof frame
- third brake light
- COC documents
- Diesel particulate filter
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Parking brake
- Generator management (Generator management helps reduce fuel consumption and CO2 emissions. The generator is switched off and the vehicle's electrical system is powered by the battery when it is sufficiently charged. This relieves the engine of the burden of charging the battery, for example, during acceleration. - When braking and during coasting downhill, the generator is switched on and the vehicle's kinetic energy is recuperated to charge the battery.)
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Multifunction steering wheel (with trip computer)
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Tires: Tires without specified make
- Tires: Summer tires
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seats: Adjustable passenger seat
- Start-stop function
- Cruise control
- First aid kit
- Warning triangle
- Immobiliser
- Central locking with radio remote control
- Registration certificate, Part II
- Axle ratio i = 3.267
- Driver's side airbag
- Exterior mirrors, manually adjustable (2)
- Outdoor temperature display
- Battery: Backup battery for starting process
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- Brake lights, adaptive
- Front cupholder
- Electronic tachometer
- Chassis: Standard chassis
- HVO-capable vehicle
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Generator 14 V / 200 A
- Speed limit 210 km/h
- Transmission: 6-speed manual transmission TSG 380
- Weight variant 2,800 kg
- Seatbelt warning device for front passenger seat
- Seatbelt warning device for driver's seat
- Lockable glove box
- Main tank 57 liters
- Boot lid
- Interior trim of cargo area, side
- Communication module (LTE) for digital services
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Headlight range control
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Breakdown management
- Tires: 205/65 R 16
- Tires: Premium protection tires (3 years)
- Headlights: halogen technology
- Key: 3-button remote control
- electromechanical power steering
- Seats: Driver's seat
- 12V socket
- continuous partition wall
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around
- Registration as a truck

Extra equipment

- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Comfort roof control unit in conjunction with rain sensor
- Burglar and theft alarm system (without interior monitoring)
- Fleet Comfort Package
- Generator 14 V / 250 A
- Interior lining of the cargo area up to roof height (wood)
- Large fuel tank, approx. 70 liters
- LED light strip in the cargo area
- Navigation accessories: Live Traffic Information
- Radio: Digital Radio DAB
- Tire pressure monitoring (on front and rear axles (wireless))
- High-resolution reversing camera with guide lines
- Seats: Comfort passenger seat
- Seat heating on passenger side
- Electrically adjustable and heated exterior mirrors, left and right
- Driving light assistant (automatically switching on driving lights)
- Rear camera not foldable
- Tempmatic controlled air conditioning
- Paintwork: Special paintwork (according to sample card)
- Center console with storage compartment
- Halogen fog lights
- Rain sensor
- Spare wheel under the rear of the vehicle with jack
- Wheels: Steel rims 6.5 J x 17
- Keys: 2 additional master keys
- Seats: Comfort driver's seat
- Seat heating on driver's side

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Wheel / tyres	Wheel cover - rear left side - Missing - Replace
4	Door - front left side	Door - Scratch(es) - Smart repair
5	2nd wheel set	2 tyres - Does not meet the leasing specifications - Replace
6	Body	Body - Glued / labelled - De-glue / neutralise
7	Side panel - rear left side	Side panel (unterhalb) - Dent / paintcoat damage - Repair and paint
8	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
9	Boot lid / rear door	Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint
10	Roof	Roof - Deformed - repair according to calculation

Wear and tear

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - Scratch(es) - No deduction
2	Body	A-pillar - left side - Stone chips - No deduction
3	Body	Partition wall - Differs from the original configuration - No deduction
4	Sliding door, right	Sliding door - dent(s) - Smooth repair work
5	Sill - right side	Sill - dent(s) - Smart repair
6	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key (3x)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 10 May 2025	6.539,61 €

Repainting

No.	Repainting
1	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - front left side	171 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 4: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door - Scratch(es) - Smart repair



Damage 5: 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



Damage 6: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Side panel - rear left side: Side panel (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 7: Side panel - rear left side: Side panel (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 7: Side panel - rear left side: Side panel (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 7: Side panel - rear left side: Side panel (unterhalb) - Dent / paintcoat damage - Repair and paint




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid (unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 10: Roof: Roof - Deformed - repair according to calculation



Damage 10: Roof: Roof - Deformed - repair according to calculation



Wear and tear 3: Body: Partition wall - Differs from the original configuration - No deduction



Wear and tear 3: Body: Partition wall - Differs from the original configuration - No deduction



Wear and tear 3: Body: Partition wall - Differs from the original configuration - No deduction



Wear and tear 4: Sliding door, right: Sliding door - dent(s) - Smooth repair work




Wear and tear 4: Sliding door, right: Sliding door - dent(s) - Smooth repair work



Wear and tear 5: Sill - right side: Sill - dent(s) - Smart repair



Wear and tear 5: Sill - right side: Sill - dent(s) - Smart repair



Wear and tear 6: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 6: Vehicle glazing: Windscreen - Stone chips - No deduction



Repainting 1: Door - front left side



Repainting 1: Door - front left side