TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

# Expertise

Protocol number: 48337591
Order No. / Reference: 27019194
Inspection date: 22 Oct 2026

| Manufacturer: Opel | Model: Astra 1.5 D Start/Stop Sports Tourer Edition |
|---|---|
| VIN: W0VBD8EV5M8023626 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Opel Astra 1.5 D Start/Stop Sports Tourer Edition | |
| **Vehicle Identification number** | W0VBD8EV5M8023626 |
| **Mileage** (assumed) | 113,573 km |
| **First registration** | 13 Aug 2021 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,496 ccm / 3 |
| **Power** | 90 kW |
| **Gearbox / Number of gears** | Manual / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Station wagon |
| **Colour / colour code** | Argonsilber Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Grey |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | |
| **Last service on / at** | 11/2025 at 108,411 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GA244575 |
| **Previous damage / Accident** | Detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not possible to drive | **Engine function test** | Not possible |
| **Manufacturer key number/ type code number** | 1844 / ALL 00257 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 1,945 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/55 R16 91H | Winter tyres on Steel | Goodyear | 5mm / 5mm |
| 2) | 205/55 R16 91H | Winter tyres on Steel | Goodyear | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/55 R16 91V | Summer tyres on Steel rim with wheel cover | Continental | 5mm / 5mm |
| 2) | 205/55 R16 91V | Summer tyres on Steel rim with wheel cover | Continental | 5mm / 5mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- 2 ignition keys (one of which is foldable)
- Airbag for driver and front passenger side (passenger airbag can be deactivated)
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable - exterior mirror housing in black)
- third brake light
- black roof rails
- Diesel particulate filter (DPF) (maintenance-free)
- Electronic Stability Program Plus (ESP Plus)
- Speed controller with limiter
- Transmission: 6-speed manual transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3) (height adjustable)
- Cargo area cover
- Steering column, height and reach adjustable
- Lighting equipment (illuminated make-up mirrors in sun visors - reading lights, rear - ambient lighting in the roof console)
- Pedal system: Disengaging safety pedals (PRS (Pedal Release System))
- Quickheat rapid heating system (electric auxiliary heater)
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Wheels: Design wheels, 6.5 J x 16 with tires 205/55 R16
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Start/Stop system (driving assistant - reinforced starter - high-performance battery - eco switch to deactivate the start/stop function - brake energy recuperation)
- Pre-installation for child seat restraint system "ISOFIX" (incl. top tether attachment points, rear outer)
- Heat-insulating glazing, green tinted, and windshield
- Storage compartments (storage compartment in the center console and instrument panel, driver's side - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 0.5-liter beverage bottles - 4 lashing eyes in the luggage compartment)
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag or seatbelt pretensioner)
- Hill Start Assist
- On-board computer (with check control system)
- Roof design line, above in black
- Decorative trim strips Antelao Sand/Polar Silver
- Tachometer
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Back window, heater
- Interior lighting, front and rear
- Air conditioning (with particle and activated carbon filter)
- trunk light
- Front headrests (height adjustable)
- LED daytime running lights (including LED turn signals, front, manual headlight range adjustment)
- Sliding center armrest, front (with storage compartments and cup holders)
- Parkpilot, rear parking aid (with acoustic warning signal when reversing)
- Upholstery: Cloth
- Radio: Digital radio reception DAB/DAB+/DMB-R (Digital Audio Broadcasting)
- Tire pressure monitoring system (tire pressure display for each wheel)
- Power steering (speed-dependent)
- Safety net for luggage compartment (incl. mounting hardware behind 1st or 2nd row of seats)
- Visibility features (rain sensor, front interior rearview mirror automatically dimming, automatic dimming headlights with tunnel detection)
- 12V power outlet in the center console
- Traction Control (TC) Plus (traction control with engine and brake intervention)
- Immobiliser
- Central locking with remote control and interior switches (ignition key matching exterior color)

### Extra equipment

- Detachable trailer hitch (including trailer stability program TSP)
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Seats: Ergonomic active seat (certified by the Campaign for Healthy Backs (AGR) Driver's seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)
- Paint finish: Metallic
- LED headlights
- Radio: Multimedia Navi (Multimedia Radio, 7" touchscreen color display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto - Navigation system with integrated memory - Road map for over 30 European countries - Map display in 2D and 3D - Dynamic route guidance via map and/or arrow display and voice prompts - Dynamic destination guidance via enhanced Traffic Message Channel (TMCpro))

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | It was not possible to drive the vehicle at the time of the inspection. |
| Engine function test | An engine test run could not be performed.<br>This is due to the following reason.:<br>Motor defekt |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Body | Body - Glued / labelled - De-glue / neutralise |
| 2 | Vehicle glazing | Windscreen - Stone chips - Replace |
| 3 | Side panel - rear left side | Side panel - Scratch(es) - Paint |
| 4 | Door - rear left side | Door - Scratch(es) - Paint |
| 5 | Front bumper | Front bumper - Dent / paintcoat damage - Repair and paint |
| 6 | Boot lid / rear door | Boot lid - Scratch(es) - Paint |
| 7 | Engine | Engine - Defective - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Door - rear right side | Door - Scratch(es) - No deduction |
| 2 | Door - front left side | Door edge - Scratch(es) - No deduction |
| 3 | Wheel / tyres | Wheel rim - front right side - Deformed - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

| Description |
|---|
| Documents - Log book |

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Rear, Provided by user / customer, from 18 Nov 2021 | 3.758,98 € |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Strom am Fzg nicht möglich, sobald Booster oder ähnliches angeklemmt wird tritt Kraftstoff aus.
Kilometerstand oder andere elektronische System nicht les- bzw. prüfbar.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)




**Figure 10:** Cargo area




**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents




**Figure 14:** Additional tyres



**Figure 15:** Misc.



**Figure 16:** Misc.



**Figure 17:** Misc.



**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.



**Damage 1:** Body: Body - Glued / labelled - De-glue / neutralise




**Damage 1:** Body: Body - Glued / labelled - De-glue / neutralise




**Damage 2:** Vehicle glazing: Windscreen - Stone chips - Replace



**Damage 2:** Vehicle glazing: Windscreen - Stone chips - Replace




**Damage 3:** Side panel - rear left side: Side panel - Scratch(es) - Paint




**Damage 3:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage 4:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 4:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 4:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



**Damage 5:** Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



**Damage 5:** Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint




**Damage 6:** Boot lid / rear door: Boot lid - Scratch(es) - Paint



**Damage 6:** Boot lid / rear door: Boot lid - Scratch(es) - Paint



**Damage 7:** Engine: Engine - Defective - Replace

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



**Wear and tear 3:** Wheel / tyres: Wheel rim - front right side - Deformed - No deduction



**Wear and tear 3:** Wheel / tyres: Wheel rim - front right side - Deformed - No deduction