PEUGEOT 508 SW

Vehicle information

Make:	**PEUGEOT**	License:	**2CHY066**
Gearbox:		Body color:	
Model:	**508 SW**	VIN:	**VR3FCYHZTNY573715**
Fuel type:		Power:	**96 kW**
Version:	**1.5 BLUEHDI 130 S&S AUTO ALLURE PACK**	First registration	**04/08/2022**
Mileage:	**134110 km**	N° of doors:	


Damage summary

Interior	4
Left	1
Roof & others	2

Commercial pictures



































Options according to the inspector

GPS	**Yes**


Damages

Bodywork
Damaged
Acceptable
Roof & others














Door RL
Dent(s)
Paintless dent repair
Left








Instrument panel, complete
Not functioning (well)
Check
Interior




Interior
Not original part
Check
Interior




Roof
Dent(s)
Paintless dent repair
Roof & others

Seat cover FL
Worn
Check
Interior

Service
Maintenance
Check
Interior



Tyres

Front Left
Winter
Aluminium
215/55/17/98/W
Firestone
5.0 mm
Front Right
Winter
Aluminium
215/55/17/98/W
Firestone
4.0 mm
Rear Left
Winter
Aluminium
215/55/17/98/W
Kleber
5.6 mm
Rear Right
Winter
Aluminium
215/55/17/98/W
Kleber
4.2 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Maintenance	**NOT OK**
Maintenance	**500.0**	Maintenance	**4 maand**
Number of charging cables (normal)	**0**	Number of charging cables (rapid charge)	**0**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**Yes**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Statutory inspection	**OK**
Statutory inspection	**04/08/2028**	Type of Maintenance book	**Digital maintenance**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.