Audi

VIN: WAUZZZGY5MA086853

Estimated repair cost

472.00 EUR
TOTAL



Description

Registration number 2CQD874	**First registration date** -	**Odometer** 79496 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections


#	Element	Defect	Correction	net cost
001	Rim / Front Right Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	
-	-	-	Lumpsum
Bodywork cost	**Paint cost**	**MaterialCost**	**165.00 EUR**
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Rim / Front Left Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Rim / Back Left Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

004	Rim / Back Right Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Acceptable	-




Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

005	Bumper / Front Painted : Yes	Scratched	Painting	269.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
2.80 h	**0.70 h**	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
210.00 EUR	**59.50 EUR**	-	

006	Roof post A/B/C / Back Right	Scratched	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

007	Roof / -	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items


- [x] Tyre repair kit complete
- [x] User manual
- [x] Document holder
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Spare Key

Main set of tyres

Front Left	UNIROYAL	225/45/17 0 V Summer	3 mm
Front Right	UNIROYAL	225/45/17 0 V Summer	5 mm
Back Left	UNIROYAL	225/45/17 0 V Summer	6 mm
Back Right	UNIROYAL	225/45/17 0 V Summer	3 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right



Odometer


Spare Tyre



Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched




Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Roof post A/B/C / Back Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Roof post A/B/C / Back Right / Scratched



Roof post A/B/C / Back Right / Scratched



Roof / - / Scratched



Roof / - / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.