Ford Mustang '19 BEV

Vehicle information

Make:**Ford**
License:**L983FD**
Gearbox:**Automatic**
Body color:
Model:**Mustang '19 BEV**
VIN:**WF0TK1EM6MMA17327**
Fuel type:**Electric**
Power:**198 kW**
Version:**Mustang EV 75kWh RWD**
First registration**30/04/2021**
Mileage:**140898 km**
N° of doors:

Damage summary

Front	1
Interior	3
Left	2
Rear	4
Right	5

Commercial pictures











L-983-FD








L-983-FD


Rijbereik
301 km
85%
Veiligheids-
gordels
OK
km/h
0
GROUND SPEED
P
R
N
D
L
16°
READY
140898 km




WF0TK1EM6MMA17327
1909


BRIDGESTONE



BRIDGESTONE










mach-e




10:38
Kijk voor de veiligheid goed om u heen.
AUTO
A/C


Waarheen?


Batterijcertificaat
Datum van diagnose: 30/10/2026
94,5%
Status van de gezondheid (SOH)*
Ford Mustang MACH e
Standard Range
VIN : WF0TK1EM6MMA17327
Kilometerstand : 140.898 km
* SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA






L-983-FD

Options according to the inspector

Central consol F**Yes**
GPS**Yes**
Headlights Xenon/LED/Laser**Yes**
Hook**Yes**
Panoramic roof**Yes**
Radio multimedia**Yes**
Rear view camera**Yes**
Telephone equipment**Yes**

Damages

Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right





Bumper R
Scratch(es)
Repair and paint (complete)
Rear





Door FL
Bad repair
Repair and paint (complete)
Left







Door FR
Scratch(es)
Repair and paint (partial)
Right







Door RL
Bad repair
Repair and paint (complete)
Left





Door RR
Scratch(es)
Repair and paint (partial)
Right





Ignition key
Missing
Replace
Interior

Rear roof pillar covering L
Scratch(es)
Smart repair
Rear





Rear roof pillar covering R
Scratch(es)
Smart repair
Rear





Seat cover FL
Worn
Replace
Interior





Tailgate / Boot
Scratch(es)
Repair and paint (partial)
Rear





User's manual
Missing
Replace
Interior

Windscreen
Stone chip(s)
Windscreen repair
Front






Wing RR
Scratch(es)
Repair and paint (complete)
Right





Wing trim RR
Scratch(es)
Replace
Right





Tyres

Location	Type	Rim	Measures	Make	Depth
Front Left					
Winter	225/60/18/104/W			Bridgestone	7.0 mm
Front Right					
Winter	225/60/18/104/W			Bridgestone	6.8 mm
Rear Left					
Winter	225/60/18/104/W			Vredestein	4.2 mm
Rear Right					
Winter	225/60/18/104/W			Vredestein	3.8 mm

Checks

CO2 Emission	**0**
Digital maintenance	**Yes**
Luggage cover	**Yes**
Number head rests	**5**
Number of charging cables (rapid charge)	**1**
Number of keys total	**1**
Service book	**N/A**
User's manual	**No**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.