TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48588554
Order No. / Reference: 27279732
Inspection date: 9 Nov 2026

Manufacturer: Mercedes-Benz	Model: 311 CDI Sprinter Kompakt VA
VIN: W1V9076311P215102	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz 311 CDI Sprinter Kompakt VA	
Vehicle Identification number	W1V9076311P215102
Mileage (Read)	81,809 km
First registration	3 Feb 2020
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	2,143 ccm / 4
Power	84 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Iridiumsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	509 Tag(e)
Key is / should be	3 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FS118327
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ARJ 02665		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	3mm / 3mm
2)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel	Continental	6mm / 6mm
2)	235/65 R16 115R	Winter tyres on Steel	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R	Summer tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control
- Outdoor temperature display
- third brake light
- Diesel particulate filter and SCR
- Driving light assistant
- Transmission: 6-speed manual
- Instrument panel and combination instrument with various storage options
- Communication module (LTE) for digital services
- Headlight range control
- Center section with 2-DIN storage compartments and air vents
- Sliding door on the right side
- Power steering
- Seats: Driver's seat adjustable
- continuous partition wall
- Lashing eyes
- ASSYST maintenance interval indicator
- Central locking with radio remote control
- Driver's side airbag
- Exterior mirrors, manually adjustable (2)
- Battery: fleece battery 1x 12 V / 70 Ah
- Brake lights, adaptive
- Tachometer
- Electric window regulator for driver and passenger door
- Seatbelt warning device for driver's seat
- KEYLESS start
- Child safety locks on doors in the passenger compartment
- Headrests (2), front
- Mercedes-Benz emergency call system
- Upholstery: Cloth
- Wheels: Steel rims 6.5 J x 16
- Crosswind Assist
- Seats: Passenger seat
- Daytime running light
- Doors: Rear doors, double-wing doors opening 180 degrees, available in two height versions
- Immobiliser

Extra equipment

- Acoustic package XM4
- BOTT
- Paint finish: Metallic
- Navigation (linguatronic voice control, Wi-Fi hotspot, multimedia connection unit for connecting portable devices via an additional USB-C interface, center fill speaker for improved sound and voice output, improved hands-free function, dual-phone operation, digital operating instructions)
- Package: Parking package with reversing camera
- Package: SMOKER
- Spare wheel
- Key: Multi-button radio remote control
- Seats: Comfort driver's seat
- Seat heating on driver's side
- Entrance rear door
- Tempmatic controlled air conditioning
- MBUX multimedia system with 7-inch touchscreen (High-resolution 7-inch touchscreen (960 x 540 pixels), AM/FM radio with dual tuner, Bluetooth connectivity with audio streaming and hands-free function, smartphone integration via Android Auto or Apple CarPlay, multimedia connection unit for connecting portable devices via a USB-C interface, 4 x 25 W output power, sound adjustment, separate volume control for audio and telephone, 2-way front speakers)
- Spare wheel carrier with jack (under frame end)
- Keys: 2 additional master keys
- Seats: Lumbar support for driver's seat
- Hot water auxiliary heater (5 kW)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Braking system	Brake fluid - No evidence - No deduction
3	Misc.	Main inspection - No evidence - No deduction
4	Trim / covers	Floor mats (VL) - Holes - Replace
5	Door - front left side	Door edge - Scratch(es) - Smart repair
6	Boot lid / rear door	Rear door - right side (Farbton) - Unprofessionally repaired - Loss in value
7	Sliding door, right	Sliding door (Farbabweichung) - Unprofessionally repaired - Loss in value
8	Body	Body (Flugrost-Mehrkosten möglich) - Soiled - Conditioning

Missing parts

Description
Documents - Service book (Digitale Nachweise)
Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, not professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Boot lid / rear door, Unprofessionally carried out, Invoice of repair done Non-existent
2	Door - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent
3	Boot lid / rear door, Unprofessionally carried out

Paint coat thickness measurement

Boot lid / rear door	217 µm	Door - rear right side	247 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Damage 4: Trim / covers: Floor mats (VL) - Holes - Replace




Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Boot lid / rear door: Rear door - right side (Farbton) - Unprofessionally repaired - Loss in value



Damage 6: Boot lid / rear door: Rear door - right side (Farbton) - Unprofessionally repaired - Loss in value



Damage 7: Sliding door, right: Sliding door (Farbabweichung) - Unprofessionally repaired - Loss in value



Damage 7: Sliding door, right: Sliding door (Farbabweichung) - Unprofessionally repaired - Loss in value



Damage 8: Body: Body (Flugrost-Mehrkosten möglich) - Soiled - Conditioning




Damage 8: Body: Body (Flugrost-Mehrkosten möglich) - Soiled - Conditioning




Damage 8: Body: Body (Flugrost-Mehrkosten möglich) - Soiled - Conditioning



Damage 8: Body: Body (Flugrost-Mehrkosten möglich) - Soiled - Conditioning



Damage 8: Body: Body (Flugrost-Mehrkosten möglich) - Soiled - Conditioning



Missing part 2: Equipment: Vehicle key - Missing - Replace



Repainting 1: Boot lid / rear door



Repainting 2: Door - rear right side



Repainting 2: Door - rear right side