TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48463740
Order No. / Reference: 27186680
Inspection date: 26 Oct 2026

Manufacturer: Ford	Model: Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. TITANIUM
VIN: WF0PXXGCHPPL02820	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. TITANIUM	
Vehicle Identification number	WF0PXXGCHPPL02820
Mileage (Read)	71,009 km
First registration	22 Sept 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	10/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	97 %
Last service on / at	10/2026 at 70,708 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT924132
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BYE 00002		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,035 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92V	Summer tyres on Steel rim with wheel cover	Goodyear	3mm / 3mm
2)	205/60 R16 92V	Summer tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel	Pirelli	6mm / 6mm
2)	205/60 R16 96H	Winter tyres on Steel	Cooper	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable
- Fabric headliner
- Roof spoiler painted in car color
- Tachometer
- Electronic Shifter
- Driver information system with on-board computer, color (10.7 cm screen diagonal)
- Electric parking brake with auto-hold function
- FordPass Connect including live traffic information
- Speed limiter
- Transmission: 8-speed automatic transmission
- Illuminated glove compartment
- rear window wiper
- Interior mirror, automatically dimming
- Isofix mount
- Headrests: 2 front and 3 rear, height adjustable
- LED taillights
- Steering wheel: 3-spoke design
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Emergency call assistant
- Front and rear parking pilot system
- Post-Collision Assist
- Tire repair kit
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Selective driving mode switch
- Seats: Passenger seat height-adjustable, manually
- Seats: Rear seat backrest
- Start-stop system
- Black trim above the side window
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Tires: 6.5 J x 16 design wheels (4) with 205/60 R16 tires
- Roof rails, aluminum
- Diesel particulate filter (DPF)
- Third brake light
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric windows front and rear
- Ford Power Start function
- luggage compartment cover
- Cruise control
- Rubber mats
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Air conditioning with automatic temperature control
- Paint finish: Solid
- LED headlights
- Adjustable steering column
- Center console "Premium" front
- Navigation: Ford SYNC 4 including Ford navigation system with AppLink, 13.2" touchscreen and DAB/DAB+
- Upholstery: Cloth
- Pre-Collision Assist
- Tire Pressure Monitoring System (TMPS)
- Headlight assistant with day/night sensor
- Electromechanical speed-dependent power steering
- Seats: Driver's seat height adjustable
- Seats: Front sports seats with enhanced lateral support
- Carpet floor mats in the front
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats

Extra equipment

- Package: Easy Parking (Active Parking Assist with parking and exiting function (in conjunction with 8-speed automatic transmission including semi-automated vehicle guidance) - Door edge protection - Rearview camera with "Split View" technology)
- Detachable towbar (including ESP trailer stabilization)
- Paint finish: Metallic
- Safety partition net for luggage compartment
- Seats: Front seats can be heated individually and variably.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Front bumper	Spoiler (Links) - Malposition - Un- / install
2	Door - front left side	Door edge - Scratch(es) - Smart repair
3	Instrument panel	Indicator light (Reifendruckkontrolle) - on - Perform diagnosis
4	Front bumper	Spoiler (Rechts) - Scratched - Replace
5	Door - rear left side	Door seal (Kleberablösung) - Damaged - Replace
6	Roof	Roof rail - right side - dent(s) - Smooth repair work
7	Rear bumper	Rear bumper - Scratched - Smart repair
8	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
9	Front bumper	Front bumper - Scratched - Repair and paint
10	Side panel - rear right side	Side panel - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - rear right side	Door handle - outside - Scratch(es) - No deduction
2	Bonnet	Bonnet - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Door - rear right side	Door - Scratch(es) - No deduction
5	Door - front right side	Door - Scratch(es) - No deduction
6	Mudguard - right side	Mudguard - right side - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Engine - Engine cover

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN




Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.





Figure 36: Misc.



Damage 1: Front bumper: Spoiler (Links) - Malposition - Un- / install




Damage 1: Front bumper: Spoiler (Links) - Malposition - Un- / install



Damage 1: Front bumper: Spoiler (Links) - Malposition - Un- / install



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Instrument panel: Indicator light (Reifendruckkontrolle) - on - Perform diagnosis



Damage 4: Front bumper: Spoiler (Rechts) - Scratched - Replace



Damage 4: Front bumper: Spoiler (Rechts) - Scratched - Replace



Damage 4: Front bumper: Spoiler (Rechts) - Scratched - Replace



Damage 4: Front bumper: Spoiler (Rechts) - Scratched - Replace




Damage 5: Door - rear left side: Door seal (Kleberablösung) - Damaged - Replace




Damage 5: Door - rear left side: Door seal (Kleberablösung) - Damaged - Replace




Damage 5: Door - rear left side: Door seal (Kleberablösung) - Damaged - Replace




Damage 5: Door - rear left side: Door seal (Kleberablösung) - Damaged - Replace



Damage 6: Roof: Roof rail - right side - dent(s) - Smooth repair work




Damage 6: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 6: Roof: Roof rail - right side - dent(s) - Smooth repair work




Damage 7: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 8: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 8: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 9: Front bumper: Front bumper - Scratched - Repair and paint




Damage 9: Front bumper: Front bumper - Scratched - Repair and paint



Damage 9: Front bumper: Front bumper - Scratched - Repair and paint




Damage 9: Front bumper: Front bumper - Scratched - Repair and paint



Damage 9: Front bumper: Front bumper - Scratched - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Scratched - Repair and paint




Damage 10: Side panel - rear right side: Side panel - Scratched - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Scratched - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Scratched - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Scratched - Repair and paint



Wear and tear 1: Door - rear right side: Door handle - outside - Scratch(es) - No deduction




Wear and tear 2: Bonnet: Bonnet - Scratch(es) - No deduction




Wear and tear 3: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 3: Vehicle glazing: Windscreen - Stone chips - No deduction




Wear and tear 4: Door - rear right side: Door - Scratch(es) - No deduction



Wear and tear 4: Door - rear right side: Door - Scratch(es) - No deduction



Wear and tear 5: Door - front right side: Door - Scratch(es) - No deduction




Wear and tear 5: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 6: Mudguard - right side: Mudguard - right side - dent(s) - No deduction



Wear and tear 6: Mudguard - right side: Mudguard - right side - dent(s) - No deduction



Missing part 1: Engine: Engine cover - Missing - Replace