DEKRA

DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	JMZKBAC34 0A361494	Mileage	69 004 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2HVV691	Registration date	02/09/2024	Engine size	1490
Brand	MAZDA	Fuel level	-	Transmission	Automatic
Model	2-Hybrid-Berlina-KBAC3-2021	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	12/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique















Other technical information

Adapter USB	✔
Service manual holder	✖
User manual	✖
Warranty booklet	✖

Tyres

Bridgestone 195/55/16 V Summer 5.0 mm

Bridgestone 195/55/16 V Summer 5.0 mm




Bridgestone 195/55/16 V Summer 5.0 mm

Bridgestone 195/55/16 V Summer 5.0 mm




Damages

1



Part	Service manual holder
Position	-
Damages	Missing
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

2



Part	User manual
Position	-
Damages	Missing
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

3



Part	Warranty booklet
Position	-
Damages	Missing
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

4



Part	Bonnet
Position	-
Damages	Scratched
Severity	-
Repair mode	Polishing
Net cost (Excluding VAT)	29.62€

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	60.00€

6



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	350.00€

prise de photo difficile dans cette endroit.couleur craqueler

7



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Polishing
Net cost (Excluding VAT)	29.62€

sous reserve peinture

8



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	29.62€

9



Part	Door sill
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

10



Part	Sill
Position	Right
Damages	Dented
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	377.75€

11



Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	289.25€

12



Part	Door
Position	Front right
Damages	Dented
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	348.50€

13



Part	Alloy wheel 16"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	123.00€

Summary Inspection

Net Price (Exclusing VAT)	1,637.36€