# MERCEDES-BENZ A-CLASS

## Vehicle information


| | | | |
|---|---|---|---|
| Brand: | **MERCEDES-BENZ** | License plate: | **2CGM526** |
| Gearbox: | | Body color: | |
| Model: | **A-CLASS** | LEVEL: | **W1K1770841V147386** |
| Fuel type: | | Power: | **100 kW** |
| Version: | **1.3 A 180 BUSINESS SOLUTION ESSENTIAL** | First registration | **15/07/2022** |
| Mileage: | **82298 km** | Number of doors: | |

## Summary of damages


| | |
|---|---|
| **Before** | 1 |
| **Interior** | 2 |
| **Roof & other** | 1 |

## Commercial photos





















## Equipment corresponding to the VIN according to the manufacturer's information

| | | | |
|---|---|---|---|
| Airbag | Rain sensor | Distance control | Power steering |
| Electrical operation of windows | GPS | Alloy wheels | Phone |
| Multifunction steering wheel | | | |

## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |

## Damages



**Bodywork**


Damaged -

Acceptable.


Roof & other

























Damaged **Interior**
- Acceptable
Interior









**Front bumper,**
scratch(es),
paint
front






**AVD Seat Upholstery**
Stain
Clean
Interior



## Tires

**Front Left**
Summer
Aluminum
205/60/16/96/H
Michelin
6.0 mm

**Front Right**
Summer
Aluminum
205/60/16/96/H
Michelin
6.0 mm

**Left Back**
Summer
Aluminum
205/60/16/96/V
Continental
8.0 mm

**Rear Right**
Summer
Aluminum
205/60/16/96/V
Continental
8.0 mm

## Controls

| | | | |
|---|---|---|---|
| Category | **Private vehicle** | Registration certificate - home address section | **No** |
| Vehicle registration certificate | **Yes** | Certificate of Conformity | **Yes** |
| Compressor | **Yes** | Vehicle inspection | **15/07/2028** |
| Vehicle inspection | **OK** | Interview | **OK** |
| Interview | **over 304 days** | Repair kit | **Yes** |
| Number of charging cables (220V) | **0** | Number of charging cables (fast charging) | **0** |
| Total number of keys | **2** | Factory reset | **Yes, the vehicle has been reset to factory settings.** |
| Type of maintenance log | **Digital interview** | | |

## NIV Details

| | | |
|---|---|---|
| ABS (anti-lock braking system) | Active Brake Assist | Driver's airbag |
| Driver's knee airbag | Passenger airbag | Head airbags |
| Side airbags | Automatic headlight activation | Speed Limit Assist |
| Attention Assist (fatigue sensor) | Active lane departure warning system | Black side protection strips |
| 1/3 - 2/3 split folding rear bench seat | Bluetooth | ESSENTIAL+ Business Solution |
| Rearview camera | Grey fabric headliner | THERMATIC automatic air conditioning |
| USB-C connection in the rear center console | USB-C connection in the storage compartment | Window frames in black |
| DAB - Digital Radio Tuner | Automatic deactivation of the passenger airbag | Rain sensor |
| Power steering | Double cup holders at the front | DYNAMIC SELECT |
| ESP (Electronic Stability Program) | Petrol particulate filter | Keyless Go Start Function |
| ECO Start/Stop function | Black Tandel fabric cover | Multi-branch JAV 6.5Jx16'' ET 44+ 205/60 |
| Keyless Start | Parking kit | Lighting and visibility kit |
| Live Traffic Information | Mercedes-Benz navigation | Metallic paint |
| Halogen headlights | Remote Services | Black air vents |
| Comfort suspension + lowered chassis | Tire pressure monitoring system | MBUX multimedia system |
| Floor mat (velvet) | Tempomat & Speedtronic | Touchpad |
| Rear electric windows | Front electric windows | Leather multifunction steering wheel |

## Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.