TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48116332
Order No. / Reference: 27041248
Inspection date: 14 Oct 2026

Manufacturer: Volkswagen	Model: ID.5 Pro Performance Upgrade Pro
VIN: WVGZZZE2ZPP520505	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen ID.5 Pro Performance Upgrade Pro	
Vehicle Identification number	WVGZZZE2ZPP520505
Mileage (Read)	132,594 km
First registration	19 Jun 2023
Number of holders	2
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	SUV
Colour / colour code	Mythosschwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	256 Tag(e)
Last service on / at	06/2025 at 80,652 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS481997
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CQL 00058		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,640 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	255/50 R19 103T	Winter tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	255/50 R19 103T	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit			

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports on the front
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Ambient lighting, 10 colors
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- On-board tools and tire mobility set (12-volt compressor and tire sealant)
- e-Sound
- Parking assistance
- ESP Electronic Stability Program
- Transmission: 1-speed automatic
- Infotainment accessories: Online update capability from ID.Software 2.1
- Rear headrests (3)
- Mode 3 Type 2 charging cable, 16 A
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency call service
- Stainless steel pedals in a "Play/Pause" design
- Tire pressure monitoring system
- Wheel accessories: Covers for alloy wheels
- Wheel accessories: Wheel locks with enhanced theft protection
- Keyless Start system
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Armrest for front seats
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Bumpers in body color
- Ambient lighting with logo projection
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- Car2X
- Black surround for the infotainment display and central controls
- Driving profile selection
- Back window, heater
- Interior mirror automatically dimming
- ISOFIX mounting points for child car seats
- Front headrests
- LED taillights
- Centre console
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Radio accessories: Digital radio reception DAB+
- Wheels: Alloy wheels (4) "Hamar" 8 J x 19 in black gloss-turned finish (wheels in black, surface gloss-turned - tires 235/55 R 19 front, tires 255/50 R 19 rear)
- Windscreen wiper intermittent control
- electromechanical power steering
- Seat belts: Warning tone and light for unfastened seat belts in the front and rear.
- Seats: Driver's seat height adjustable
- Voice control
- Lane keeping assistant “Lane Assist”
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: "Discover Pro" navigation function
- Central locking including remote control

Extra equipment

- Foldable towbar (electric release)
- Paint finish: Metallic
- Package: Assistance package "Plus" incl. "IQ.DRIVE" with "Travel Assist" (Easy Open & Close - tailgate with sensor-controlled opening and closing, with remote control, Adaptive Cruise Control (ACC) stop&go, speed limiter, anti-theft alarm with interior monitoring and towing, Travel Assist, Lane Assist and Emergency Assist, illuminated strip between headlights and door handle recesses, memory radio for Park Assist, multifunction steering wheel with LED lighting, Park Assist, Active Parking Assist, occupant protection, keyless entry and start system, Keyless Access with Safe-Side, Lane Change Assist, Side Assist, Area View including Rear View camera)
- Package: Infotainment Package "Plus" (Augmented Reality Head-up Display - Navigation System "Discover Pro": 23.4 cm touchscreen, map with 2D display, traffic sign recognition, points of interest, App-Connect Wireless, voice control - Sound system, 6 speakers, digital 12-channel amplifier, subwoofer, 450 watts total output - Telephone interface "Comfort" with inductive charging function including hands-free system, Bluetooth audio, external antenna connection with LTE support)
- Package: Sport package (progressive steering - sport suspension)
- Wheels: Winter wheels (4) "Hamar" 8 J x 19 (total) in Dark Graphite/ gloss-turned (winter tires 235/55 R 19 T / 255/50 R 19 T)
- Heat pump for range optimization
- Interior Style "Plus" Platinum Grey with black steering wheel (30-color ambient lighting, electrically adjustable, folding, and heated exterior mirrors, passenger-side mirror dipping function, pneumatically adjustable lumbar support in the front, massage function, heated leather multifunction steering wheel with touch controls, asymmetrically split-folding rear seat backrest with pass-through and center armrest, 2 cup holders, front seat center panels and outer rear seat panels in ArtVelours microfleece, heated front seats, ergoActive front seats with electrical adjustment, memory function, and sliding thigh support)
- Package: Design package (3D LED taillights with dynamic turn signals - Dynamic Light Assist high beam control for LED matrix headlights - IQ.LIGHT - LED matrix headlights with automatic headlight control, bad weather light, welcome function - illuminated strip between the headlights - tinted rear side windows and rear window)
- Package: Comfort Package "Plus" incl. telematics box (2 USB-C ports front, 2 USB-C charging sockets rear center console - laminated safety glass windshield, wirelessly heated and infrared-reflecting, noise-insulating - luggage net - luggage compartment floor - Climatronic with active combination filter and 3-zone temperature control - variable center console - leather multifunction steering wheel, heated, with touch controls - cargo net partition - rain sensor - automatically heated windshield washer nozzles - heated front seats - telematics box for the recording and analysis of vehicle data)
- Textile floor mats front and rear

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Interior	Cargo area floor - Soiled - Clean
2	Door - front left side	Brightware - lower - Scratched - Smart repair
3	Door - front left side	Door - Scratched - Smart repair
4	Front bumper	Front bumper (+ Luftgitter+Spoiler erneuern) - Damaged - repair according to calculation

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Door - front right side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit filler

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Fahrzeugmodellbezeichnung laut Rechnung: "Volkswagen ID.5 Pro Performance".

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung, Mehrkosten und somit Abweichung der für die Stoßstange ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Damage 1: Interior: Cargo area floor - Soiled - Clean



Damage 2: Door - front left side: Brightware - lower - Scratched - Smart repair



Damage 2: Door - front left side: Brightware - lower - Scratched - Smart repair



Damage 3: Door - front left side: Door - Scratched - Smart repair



Damage 3: Door - front left side: Door - Scratched - Smart repair



Damage 3: Door - front left side: Door - Scratched - Smart repair



Damage 4: Front bumper: Front bumper (+ Luftgitter+Spoiler erneuern) - Damaged - repair according to calculation



Damage 4: Front bumper: Front bumper (+ Luftgitter+Spoiler erneuern) - Damaged - repair according to calculation



Damage 4: Front bumper: Front bumper (+ Luftgitter+Spoiler erneuern) - Damaged - repair according to calculation



Damage 4: Front bumper: Front bumper (+ Luftgitter+Spoiler erneuern) - Damaged - repair according to calculation

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Damage 4: Front bumper: Front bumper (+ Luftgitter+Spoiler erneuern) - Damaged - repair according to calculation



Missing part 1: Equipment: Tirefit filler - Missing - Replace