TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48576850
Order No. / Reference: 27107032
Inspection date: 28 Oct 2026

Manufacturer: Volkswagen	Model: ID.3 Pro
VIN: WVWZZZE1ZPP000642	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen ID.3 Pro	
Vehicle Identification number	WVWZZZE1ZPP000642
Mileage (Read)	29,154 km
First registration	27 Oct 2022
Number of holders	1
Next periodical technical inspection	10/2027
(Report on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Car hatchback
Colour / colour code	Mondsteingrau / Dach Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Dark grey-Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13 Tag(e)
Last service on / at	11/2024 at 15,771 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM738032
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CKU 00057		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,270 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 95T	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/55 R18 95T	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 95T	Summer tyres on Steel	Bridgestone	5mm / 5mm
2)	215/55 R18 95T	Summer tyres on Steel	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- third brake light
- CCS charging socket
- Black surround for the infotainment display and central controls
- Driving profile selection
- Transmission: Direct drive, 1-speed
- rear window wiper
- "Climatronic" air conditioning system (active combination filter - stationary air conditioning)
- Charging: 11 kW AC charging capacity
- LED taillights
- LED headlights with automatic headlight control
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency call service
- Online update capability from ID.Software 2.1 onwards.
- Radio: "Ready 2 Discover"
- Radio accessories: 4 + 1 speakers
- Wheels: 4 steel wheels 7.5 J x 18 (wheel covers - tires 215/55 R 18)
- Keyless start system without safe locking
- Seat belts: Three-point automatic seat belts at the front with belt tensioners
- Seats: Armrests, front seats
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened seat belts front and rear
- Airbag for driver and front passenger
- Ambient lighting, 10 colors
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Vehicle tool kit
- Car2X
- e-Sound
- Parking assistance
- Electronic Stability Program (ESP)
- Speed limiter
- Rear window heated
- ISOFIX mounting points
- Headrests (5) front and rear
- Mode 3 Type 2 charging cable, 16 A
- Charging: Maximum DC charging power depends on the traction battery.
- Steering wheel: Multifunction steering wheel
- Front center console with 2 cup holders
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery in "Fragment" fabric
- Radio accessories: 2 USB-C ports at the front
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set with 12-volt compressor and tire sealant
- electromechanical power steering
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Lane keeping assistant “Lane Assist”
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear

Extra equipment

- Charging cable: Mains charging cable for household socket
- Package: Infotainment package (Navigation system "Discover Pro" (Touchscreen 25.4cm, FM radio, dual tuner with phase diversity, RDS, radio station logos, MP3, USB-C interface, Apple compatibility, map with 2D display, traffic sign display, points of interest, voice control, DAB+) - Telephone interface "Comfort" with inductive charging function (hands-free system, Bluetooth audio))
- Paintwork: two-tone with black roof, solid color
- Package: Interior Style "Plus" with black steering wheel (3 rear seats, electrically adjustable, asymmetrically split and folding, center armrest, pass-through, 2 cup holders - 30-color ambient lighting - electrically folding, adjustable and heated exterior mirrors - ErgoActive front seats, electrically adjustable, memory and sliding thigh support - pneumatically adjustable lumbar support for front seats with massage function - multifunction leather steering wheel, heated, with touch controls - stainless steel pedals in "Play/Pause" design - "ArtVelours" microfleece seat centers - ambient lighting with logo projection - heated front seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Front bumper	Spoiler - Scratched - Loss in value
3	Equipment	Vehicle key - Damaged - Replace
4	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
5	Side panel - rear right side	Side panel - Scratch(es) - Paint
6	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Interior	Interior - Soiled - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.






Figure 28: Misc.



Figure 29: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Front bumper: Spoiler - Scratched - Loss in value



Damage 2: Front bumper: Spoiler - Scratched - Loss in value




Damage 2: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Equipment: Vehicle key - Damaged - Replace



Damage 4: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 4: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 4: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 6: Front bumper: Front bumper - Scratched - Paint



Damage 6: Front bumper: Front bumper - Scratched - Paint