MG

VIN: LSJWS4395SZ110934

Estimated repair cost

75.00 EUR
TOTAL



Description

Registration number 2HVX471	**First registration date** -	**Odometer** 16325 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Front Left Rim/Tyre diameter : 18 " / Surface : Diamond cut	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Rim / Back Left Rim/Tyre diameter : 18 " / Surface : Diamond cut	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Wing / Front Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

004	Door sill / Front Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

005	Door / Back Left	Scratched	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

006	Bumper / Back Painted : No	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

007	Door / Front Right	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

008	Roof / - [1]	Paint etching	Polishing	37.50 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

[1] Ovb

Loose Items

- [x] Tyre repair kit complete
- [x] User manual
- [x] Rear parcel shelf
- [x] Spare Key

Main set of tyres

Front Left	GITI	215/50/18 0 V Summer	5 mm
Front Right	GITI	215/50/18 0 V Summer	5 mm
Back Left	GITI	215/50/18 0 V Summer	6 mm
Back Right	GITI	215/50/18 0 V Summer	6 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment




Front right



Odometer



Spare Tyre



Vin



Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Wing / Front Left / Scratched



Wing / Front Left / Scratched



Door sill / Front Left / Scratched



Door sill / Front Left / Scratched



Door / Back Left / Scratched



Door / Back Left / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Door / Front Right / Dent



Door / Front Right / Dent



Roof / - / Paint etching

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Roof / - / Paint etching

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.