TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48508022
Order No. / Reference: 27211739
Inspection date: 3 Nov 2026

Manufacturer: Peugeot	Model: 508 SW Plug-In Hybrid 225 e-EAT8 GT
VIN: VR3F4DGZTNY654906	





Vehicle details

Manufacturer / Type / Model / Equipment	
Peugeot 508 SW Plug-In Hybrid 225 e-EAT8 GT	
Vehicle Identification number	VR3F4DGZTNY654906
Mileage (Read)	182,188 km
First registration	30 Mar 2023
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,598 ccm / 4
Power	133 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	TYPE HABILLAGE EXTERIEUR METALLISEE VERNIS
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	27,000 km
Last service on / at	09/2026 at 179,279 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG055479
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADY 00024		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,290 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R18 98Y	Summer tyres on Light alloy	Continental	6mm / 0mm
2)	235/45 R18 98Y	Summer tyres on Light alloy	Continental	5mm / 0mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	3mm / 3mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	1mm / 2mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Active Blind Spot Assist
- Electrically adjustable, heated and folding exterior mirrors (with LED approach lighting - integrated LED turn signals)
- Illuminated glove compartment
- Turn signals with lane change indicator function
- third brake light
- Roof rails in high-gloss black
- Digital instrument cluster with high-resolution 12.3" screen, adjustable and customizable
- EBV (Electronic Brakeforce Distribution)
- Front parking aid, acoustic and visual
- Electric front and rear windows (with comfort operation and anti-pinch protection)
- electric parking brake
- Front collision warning
- front and rear floor mats
- luggage compartment roller blind
- Cup holder in the center console
- Heated rear window
- Rear window and side windows in the second row are more heavily tinted.
- rear window wiper
- Rear apron with diffuser look in black
- Interior mirror automatically dimming
- Frameless interior mirror
- Map pockets on the front seatbacks
- Manual child lock
- Height-adjustable headrests
- Radiator grille in racing flag pattern in "Dark Chrome" (with high-gloss black surround)
- Blue LED ambient lighting on the front door panels
- LED ceiling lighting at the front (2 reading lights at the front and rear)
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- Makeup mirror (illuminated for driver and front passenger)
- Front center armrests with illuminated storage compartment
- Multimedia: Mirror Screen (Transfer of multimedia content and apps from a compatible smartphone to the vehicle's touchscreen, allowing direct control of compatible functions and apps - CarPlay (for compatible Apple iPhone models) - Android Auto (for compatible smartphone models with Android operating system))
- Emergency brake assist (with automatic activation of the hazard warning lights)
- On-board charger 3.7 kW, 1-phase
- Particle filter: OPF (Otto particulate filter)
- Break warning
- Upholstery: Fabric/faux leather
- Active Safety Brake Plus
- Airbag: Side airbag (for driver and front passenger)
- Airbag: Curtain airbags front and rear
- Adaptive Cruise Control (ACC) with Stop & Go function (including lane positioning assistant)
- Exterior mirrors in Perla Nera Black
- Hill start assist
- On-board computer
- Black headliner
- Decorative inserts in carbon look (for door panels and dashboard)
- Dual exhaust with chrome-plated tailpipes
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP) (with ASR (traction control))
- High beam assist
- Follow-me-home function (automatic)
- Full LED headlights with headlight range control (LED taillights - LED turn signals with static cornering lights)
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point seat belts in all seats (height-adjustable three-point seat belts with belt locks - pyrotechnic belt tensioners and electrically controlled belt force limiters - safety-optimized front headrests - warning light and warning signal for unfastened or unfastened seat belts for driver, front passenger and rear passengers - rear seats: 3 three-point seat belts - belt force limiters on the side seats - Isofix child seat anchors on the outer seats)
- Keyless system (keyless access and start system)
- Automatic climate control (2 zones) (separately adjustable for driver and front passenger)
- LED ambient lighting in the front footwell
- Blue LED ambient lighting on the dashboard (under the center console and the cup holder)
- LED daytime running lights
- "Sperone" 18" alloy wheels, two-tone (with 235/45 R 18 98Y tires)
- light sensor
- Rear center armrest with pass-through flap
- Multifunctional touchscreen (capacitive screen, 7 toggle switches, access to key functions such as radio, air conditioning, navigation system, vehicle settings, telephone and connectivity)
- Fatigue warning
- Navigation system: 3D navigation system NAC (Real-time navigation by TomTom Services - 3D navigation including 3D display of buildings and monuments - Voice recognition for navigation, telephone and media - Touchscreen operation - PEUGEOT Connect Box - Map transfer to the digital instrument cluster - 2 USB ports (Type A))
- Aluminum pedals and stainless steel door sills
- Upholstery: Decorative copper stitching on the dashboard
- Radio accessories: 2 USB ports (Type A) in row 2
- Radio accessories: Digital radio reception DAB+
- Rain sensor

- Radio: Audio (Bi-tuner - 8 speakers (midrange and tweeters) - MP3-compatible - Bluetooth hands-free system with audio streaming via Bluetooth - USB port (Type A) - AUX input - operation via steering wheel and touchscreen)
- Wheels: Anti-theft wheel bolts
- Reversing camera with 180° surround view
- Electric power steering
- Seats: Driver's seat height adjustable
- Sport mode (to activate the following functions: - Display of driving dynamics parameters on the instrument cluster - More responsive accelerator pedal response - More responsive power steering - Increased engine noise)
- Glazing: Laminated glass windshield, noise-reducing
- Traffic sign recognition (with display of the speed recommendation in the instrument cluster (additional recognition of stop signs, one-way street signs and the beginning and end of no-overtaking zones))
- Immobiliser
- Central locking activated from inside with remote control (doors lock automatically when driving off)
- Tire pressure monitoring system
- Wheels: Tire repair kit (compressor + tire sealant spray)
- paddle shifters on the steering wheel
- Seats: Passenger seat height adjustable
- Seats: Rear bench seat and backrest 40/60 split folding (Magic Flat System with control element in the boot)
- Lane keeping assist with steering intervention
- Technical features: Plug-in hybrid version (Acoustic pedestrian warning system (AVAS), pressure tank system including switch for opening the fuel filler flap, selectable driving modes: Electric/Hybrid/Sport, preconditioning function, HYBRID logo on the fenders and tailgate, functions (Brake) and (e-Save) for energy recovery when releasing the accelerator pedal and for preserving purely electric range (10 km, 20 km or the full charging capacity))
- Decorative trim in high-gloss black on the side windows

Extra equipment

- Mechanically swiveling towbar with ball head
- tailgate sensor-controlled
- Paint finish: Special metallic paint
- On-board charger 7.4 kW, 1-phase
- Radio accessories: FOCAL sound system (total output 515 watts - 10 speakers including center speaker and subwoofer - HiFi woofer and midrange speaker as well as TNF tweeter - 12-channel amplifier)
- Pre-installation for luggage compartment partition net
- Fire extinguisher
- Inductive charging station
- charging cable
- Panoramic tilt/slide sunroof with manual blind
- Seats: Ergonomic Comfort Seats Plus with AGR seal of approval (GT) (Ergonomic comfort seats in front, electrically adjustable, driver's seat with memory function - massage function for driver and front passenger seat - front seat heating)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Roof	Roof rail - left side - dent(s) - Smooth repair work
3	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
4	Vehicle glazing	Door glass - rear left side - Scratch(es) - Loss in value
5	Side panel - rear left side	Side panel - dent(s) - Smart repair
6	Door - front right side	Door (Lackkante) - Paint defect - Conditioning
7	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
8	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
9	Wheel / tyres	Tyre - front right side (+ gerissen, nicht fahrbereit) - Worn - Replace
10	Side panel - rear right side	Elbow (Und einschlüsse) - dent(s) - Smart repair
11	Mudguard - right side	Mudguard - right side (Wellig und einschlüsse) - Unprofessionally repaired - Lacquer
12	Roof	Roof (Anätzung) - Paint defect - Lacquer
13	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
14	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	2nd wheel set	Tyres - complete set - Worn - No deduction
2	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
3	Instrument panel	Centre console - front - Scratch(es) - No deduction
4	Seat - front	Seat cover - left side - Scratch(es) - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Door - rear right side	Door - dent(s) - Smart repair

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Provided by user / customer, from 21 Sept 2026	4.820,52 €
2	Front, Rear, Side right, Provided by user / customer, from 5 Jan 2024	9.235,11 €

Repainting

No.	Repainting
1	Roof rail - right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
4	Mudguard - right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - right side	171 µm	Mudguard - right side	206 µm
Side panel - rear right side	202 µm	Door - front left side	165 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres




Figure 18: Navigation




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Vehicle glazing: Door glass - rear left side - Scratch(es) - Loss in value




Damage 4: Vehicle glazing: Door glass - rear left side - Scratch(es) - Loss in value



Damage 5: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 5: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 5: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 6: Door - front right side: Door (Lackkante) - Paint defect - Conditioning



Damage 6: Door - front right side: Door (Lackkante) - Paint defect - Conditioning



Damage 7: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 9: Wheel / tyres: Tyre - front right side (+ gerissen, nicht fahrbereit) - Worn - Replace



Damage 9: Wheel / tyres: Tyre - front right side (+ gerissen, nicht fahrbereit) - Worn - Replace



Damage 9: Wheel / tyres: Tyre - front right side (+ gerissen, nicht fahrbereit) - Worn - Replace



Damage 10: Side panel - rear right side: Elbow (Und einschlüsse) - dent(s) - Smart repair



Damage 10: Side panel - rear right side: Elbow (Und einschlüsse) - dent(s) - Smart repair



Damage 10: Side panel - rear right side: Elbow (Und einschlüsse) - dent(s) - Smart repair



Damage 11: Mudguard - right side: Mudguard - right side (Wellig und einschlüsse) - Unprofessionally repaired - Lacquer



Damage 11: Mudguard - right side: Mudguard - right side (Wellig und einschlüsse) - Unprofessionally repaired - Lacquer




Damage 11: Mudguard - right side: Mudguard - right side (Wellig und einschlüsse) - Unprofessionally repaired - Lacquer




Damage 12: Roof: Roof (Anätzung) - Paint defect - Lacquer




Damage 12: Roof: Roof (Anätzung) - Paint defect - Lacquer




Damage 12: Roof: Roof (Anätzung) - Paint defect - Lacquer



Damage 12: Roof: Roof (Anätzung) - Paint defect - Lacquer



Damage 12: Roof: Roof (Anätzung) - Paint defect - Lacquer



Damage 13: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 13: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 13: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 13: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 13: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Wear and tear 6: Door - rear right side: Door - dent(s) - Smart repair



Wear and tear 6: Door - rear right side: Door - dent(s) - Smart repair



Repainting 1: Roof rail - right side



Repainting 1: Roof rail - right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side



Repainting 3: Door - front left side



Repainting 3: Door - front left side



Repainting 4: Mudguard - right side



Repainting 4: Mudguard - right side