Skoda

VIN: TMBJW8NX5PY009571

Estimated repair cost

1,163.49 EUR
TOTAL



Description

Registration number
2JBP786

First registration date
-

Odometer
70245 km

Color
-

Model year
-

Upholstery
-

Number of doors
-

Number of seats
-

Generation
-

Body Type
Coupe

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Compressor tyre repair kit / -	Missing	Replace	74.58 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	74.58 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

002	Registration certficate2 / -	Missing	Replace	250.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

		Bodywork time -	Paint time -	Part Price -	Lumpsum **250.00 EUR**
		Bodywork cost -	Paint cost -	MaterialCost -	
003	Registration certficate / -		Missing	Replace	0.00 EUR
		Bodywork time -	Paint time -	Part Price -	Lumpsum -
		Bodywork cost -	Paint cost -	MaterialCost -	
004	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17 "		Scratched	Acceptable	-
		Bodywork time -	Paint time -	Part Price -	Lumpsum -
		Bodywork cost -	Paint cost -	MaterialCost -	
005	Wing / Front Right		Scratched	Acceptable	-
		Bodywork time -	Paint time -	Part Price -	Lumpsum -
		Bodywork cost -	Paint cost -	MaterialCost -	
006	Door / Front Right		Scratched	Acceptable	-
		Bodywork time -	Paint time -	Part Price -	Lumpsum -
		Bodywork cost -	Paint cost -	MaterialCost -	
007	Door / Back Right		Scratched	Polishing	37.50 EUR
		Bodywork time **0.50 h**	Paint time -	Part Price -	Lumpsum -
		Bodywork cost **37.50 EUR**	Paint cost -	MaterialCost -	
008	Wing / Back Right		Scratched	Painting	279.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	2.40 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	204.00 EUR	-	

009	Bonnet / -	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

010	Bumper / Front [1]	Improper Repair	Repair	202.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	1.50 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	127.50 EUR	-	

011	Door / Front Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

012	Rear-view mirror / Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

013	Interior complete / -	Dirty	Cleaning	75.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	-	-	

014	Fabric door lining / Back Left [2]	Tear	Smart repair	68.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	68.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

015	Tailgate / Boot door / -	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

016	Bumper / Back	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

017	Interior tailgate lining / Back	Scratched	Replace	108.91 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	**71.41 EUR**	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

018	Fabric door lining / Back Right	Scratched	Smart repair	68.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	68.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

019	Roof / -	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

[1] Lak laat los

[2] X3

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Quick charging cable (Type 2, Mode 3)
- [x] Document holder
- [ ] Registration certificate owner
- [x] Spare Key
- [x] Tyre repair kit complete
- [x] Triangle
- [x] Rear parcel shelf
- [ ] Compressor tyre repair kit
- [x] First aid kit
- [ ] Registration certificate

Main set of tyres

Front Left	CONTINENTAL	205/55/17 95 V All-season	5 mm
Front Right	CONTINENTAL	205/55/17 95 V All-season	5 mm
Back Left	CONTINENTAL	205/55/17 95 V All-season	5 mm
Back Right	CONTINENTAL	205/55/17 95 V All-season	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left


Rear left


Boot opened



Rear right


Rear passenger compartment



Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation




Spare Tyre


Cable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Vin



Other



Compressor tyre repair kit / - / Missing



Rim / Front Right / Scratched



Wing / Front Right / Scratched



Door / Front Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Bonnet / - / Scratched



Bumper / Front / Improper Repair


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Front / Improper Repair



Bumper / Front / Improper Repair



Bumper / Front / Improper Repair



Door / Front Left / Scratched



Rear-view mirror / Left / Scratched



Interior complete / - / Dirty



Interior complete / - / Dirty




Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Fabric door lining / Back Left / Tear



Fabric door lining / Back Left / Tear

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Fabric door lining / Back Left / Tear



Fabric door lining / Back Left / Tear



Tailgate / Boot door / - / Scratched



Bumper / Back / Scratched



Interior tailgate lining / Back / Scratched



Interior tailgate lining / Back / Scratched



Interior tailgate lining / Back / Scratched



Interior tailgate lining / Back / Scratched



Interior tailgate lining / Back / Scratched



Fabric door lining / Back Right / Scratched



Fabric door lining / Back Right / Scratched



Roof / - / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.