MACADAM

BMW I4

Vehicle information


Brand:	**BMW**	License plate:	**2BVW891**
Gearbox:		Body color:	
Model:	**I4**	LEVEL:	**WBY71AW040FM72805**
Fuel type:		Power:	**250 kW**
Version:	**BEV EDRIVE40 GRAN COUPE**	First registration	**12/04/2022**
Mileage:	**182080 km**	Number of doors:	


Summary of damages

Back	1
Before	1
RIGHT	1
LEFT	1
Interior	1
Roof & other	1

Commercial photos






























Options according to the inspector

GPS	**Yes**

Damages

Left Wing
Claw(s)
Paint
Left





Bodywork

Damaged -

Acceptable.


Roof & other

















Trunk/Hatchback
Scratch(es)
Paint
Rear




Damaged **Interior**
- Acceptable
Interior


Alloy wheel AVD
Scratch(es)
LI - Repair and paint (complete)
Right





Front bumper dent

(s) and scratch(es)

LI - Repair and paint (complete)

Front






Tires

Front Left

Summer

Aluminum

225/55/17/101/W

Hankook

3.0 mm

Front Right

Summer

Aluminum

225/55/17/101/W

Hankook

4.0 mm

Left Back

Summer

Aluminum

225/55/17/97/W

Goodyear

4.0 mm

Rear Right

Summer

Aluminum

225/55/17/97/W

Goodyear

2.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**OK**
Vehicle inspection	**09/02/2028**	Interview	**OK**
Interview	**23/04/2028**	Repair kit	**P/A**
Number of charging cables (220V)	**1**	Number of charging cables (fast charging)	**1**
Total number of keys	**2**	Charge level	**30**
Factory reset	**Yes, the vehicle has been reset to factory settings.**	Runflat	**P/A**
SOH	**93.0**	Type of maintenance log	**Digital interview**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.